

EXHIBIT: PacifiCorp PAC_124
CPUC PROCEEDING: H.25-07-005
SPONSOR/WITNESS: PacifiCorp/Carrie Laird
DESCRIPTION: 5G149_FireIncident_072721-
Yreka.xlsx
DATE IDENT. 6/9/2026 RECD. _____
ALJ: GERALD F. KELLY

PAC_124

Fire Incident

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W
	Fire Incident ID	Circuit ID	Incident Timestamp	Outage Timestamp	Outage ID(s)	Greater Outage ID	Fire Incident Class	County	District Name	Facility Points	Reportable Incident	Created By	Has Outage	Substation Name	Is FHCA?	Is ESS?	Nearest Upstream ESS Device	Exclude From ESS Effectiveness?	Loss of Transmission?	Latitude	Longitude	Voltage	Outage Direct Cause
1																							
2	06272021-Yreka	5G149	2021-06-27 07:58:00 PM	2021-06-27 07:44:00 PM	[CPCC1464663]	2195722		Siskiyou	YREKA	[06245007.0235361]			TRUE	Yreka	FALSE	FALSE		FALSE	FALSE	41.73	-122.62	12,470	B/O EQUIPMENT

Fire Incident

	A	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AL	AM	AN	AO	AP	AQ	AR
1	Fire Incident ID	Outage Component	Address	State	City	Contact From Object	Contact From Object Comment	Determination	Determination Comment	Outage Class	Outage Comments	Device ID(s)	Device Type Title(s)	Equipment Failure	Equipment Involved with Fire Incident	Land Use at Origin Comment	Notes	Suspected Initiating Cause	Fire Size in Acres	Material At Origin	Rural Or Urban	Contributing Factor
2	06272021-Yreka	FUSE (NO CAUSE FOUND) OH	801 Sierra Vista Way	CA	Yreka	N/A		Utility personnel		DISTRIBUTION	SOURCE: Failed b phase potehead at fp 235361.	[OH_235361_1910141786]	[Fuse]	Fuse	FUSE			Equipment failure	0.00	Vegetation	Rural	Unknown

Fire Incident

	A	AS	AT	AU	AV	AW	AX	AY	AZ	BA	BB	BC	BD	BE	BF	BG	BH	BI	BJ	BK	BL
	Fire Incident ID	Facility Contacted	Facility Contacted Comment	Other Companies Attached to the Pole	Material At Origin Comment	Within City Limit	Is 3rd Party Caused Fire	Suspected Initiating Cause Comment	Control Center	Fire Detection Method	Fire Detection Method Comment	Prevailing Weather at Time of Fire	Fuel Bed Description Comment	Contributing Factor Comment	Fire Size	Land Use at Origin	Fuel Bed Description	Line Class	Fire Name	Fire Incident Notes Or Comments	Fire Size Details
1																					
2	06272021-Yreka	N/A		none			No			Public					<0.25	Rural	Brush fuel model - Fuel bed comprised of mainly brush or shrubs where damage occurred (e.g. chamise, manzanita, chaparral, scotch broom, etc.).	[Distribution]		There was a 10 by 10 foot area fire near fp 235361 that was extinguished. No report of damage to any property at this time. The burned area was below 2 blown fuses that resulted in an outage.	10'x10' 0.002 Acres

Fire Incident

	A	BM	BN	BO	BP	BQ	BR	BS	BT	BU	BV	BW	BX	BY	BZ	CA
1	Fire Incident ID	Suppressing Agency	Internal Cause Determination	HFTD Class	Suppressed By	Equipment Failure Comment	Corrective Action Needed	Facility Identification	Investigation Notes	Investigation Priority	Investigation Status	Investigation User	Pre-Investigation Notes	Priority Number	Source	Attachments
2	06272021-Yreka	Yreka Fire Department	Attributed	Tier 2	Fire agency		FALSE									