EXHIBIT: PacifiCorp PAC_218
CPUC PROCEEDING: H.25-07-005
SPONSOR/WITNESS: PacifiCorp/Carrie Laird
DESCRIPTION: Public - Response to CPUC SED Data Request 2.13 (SED-02-PacifiCorp 2020 WMP)
DATE IDENT. 6/9/2026 RECD. _____
ALJ: GERALD F. KELLY

PAC_218
(Public)

CPUC SED Data Request 2.13

PacifiCorp stated in response to SED-01 Q8(a) that, "The following table identifies fire ignitions that occurred on circuits where routine cycle maintenance was not recorded as complete within calendar year 2020... The general vicinity of the location where vegetation contact occurred on circuit 5G41, was inspected and worked by vegetation management prior to the November 2020 ignition date."

Date	Time	Lat	Long	City	HFTD	Suspected Cause	Facility ID	Circuit
4/24/2020	19:11	[redacted]		Weed	Tier 2	Contamination	06241005.0110000	5G83
9/18/2020	12:21			Fort Jones	Tier 2	Object contact – Vegetation	06243009.0192400	5G41
11/1/2020	13:33			Weed	Tier 2	Equipment failure – Insulator and Bushing	06241005.0013641	5G83

Figure 1: PacifiCorp Table 8(a) ignitions (excluding row 4, vehicle contact)

(a) Update Figure 1 by adding the size of the area burned; the fire suppression costs (PacifiCorp and fire authority); the number of structures damaged or destroyed; and any injuries and/or loss of life from such fire.

(b) Provide the fire authority report for each fire shown in Figure 1.

(c) Provide all notifications to the Commission (including the date) and all fire authority reports regarding the ignitions in Figure 1. If PacifiCorp did not report such fire to the Commission, explain why.

(d) For each ignition location shown in Figure 1, state whether PacifiCorp conducted vegetation inspection(s) at such location prior to the ignition. If so, explain the inspection cycle and program. Provide all Documents Related to Your answer and state the page number(s) of the relevant section(s) of such Documents.

(e) For each ignition location shown in Figure 1, state whether PacifiCorp conducted vegetation remediation work at such location prior to the ignition. If so, explain the inspection cycle and program and describe the type of work completed. Provide all Documents Related to Your answer and state the page number(s) of the relevant section(s) of such Documents.

Despite PacifiCorp's diligent efforts, certain information protected from disclosure by the attorney-client privilege or other applicable privileges or law may have been included in its responses to these data requests. PacifiCorp did not intend to waive any applicable privileges or rights by the inadvertent disclosure of protected information, and PacifiCorp reserves its right to request the return or destruction of any privileged or protected materials that may have been inadvertently disclosed. Please inform PacifiCorp immediately if you become aware of any inadvertently disclosed information.

Response to CPUC SED Data Request 2.13

(a) Please refer to the table provided below:

Date	Time	Lat	Long	City	HFTD	Suspected Cause	Facility ID	Circuit	Area Burned	Suppression Costs	Structures Damaged or Destroyed	Injuries or Loss of Life
4/24/2020	19:11	[redacted]		Weed	Tier 2	Contamination	06241005.0110000	5G83	.11 acres	No record	No record	No record
9/18/2020	12:21			Fort Jones	Tier 2	Object contact – Vegetation	06243009.0192400	5G41	.43 acres	No record	No record	No record
11/1/2020	13:33			Weed	Tier 2	Equipment failure – Insulator and Bushing	06241005.0013641	5G83	< 3 square meters	No record	No record	No record

(b) PacifiCorp has no record of any fire authority report regarding these fire incidents.

(c) Please refer to the Company's response to CPUC SED Data Request 1.2, specifically Attachment CPUC SED 1.2, which provides a copy of PacifiCorp's 2020 Fire Incident Data Collection Annual Report submitted around March 31, 2021.

(d) The following provides information regarding PacifiCorp's vegetation management inspections conducted of the circuits in question and information regarding vegetation management work identified at locations nearest to the ignition location.

- 06241005.0013641 - 5G83 - Nearest work location to the identified facility ID was inspected on May 14, 2020.
  i. Please refer to Attachment CPUC SED 2.13, specifically file "SED_13_5G83_Inventory" which provides the inspection report of circuit 5G83 and identification of locations requiring work. The inspection date of the closest location where work was identified to the subject pole is May 14, 2020 and is highlighted yellow in the attachment. No work at the subject pole location was identified during inspection. During an inspection, work locations are recorded in the inventory report. Inspection of portions of the circuit where no work is identified are not recorded in the inventory report. Therefore, the inspection date of vegetation in the vicinity of the subject pole can reasonably be inferred to be on or about May 14, 2020, based on the inspection date of the nearest location where work was identified and took place prior to the fire ignition.

Despite PacifiCorp's diligent efforts, certain information protected from disclosure by the attorney-client privilege or other applicable privileges or law may have been included in its responses to these data requests. PacifiCorp did not intend to waive any applicable privileges or rights by the inadvertent disclosure of protected information, and PacifiCorp reserves its right to request the return or destruction of any privileged or protected materials that may have been inadvertently disclosed. Please inform PacifiCorp immediately if you become aware of any inadvertently disclosed information.

- 06243009.0192400 - 5G41 - Nearest work location to the identified facility ID was inspected July 2, 2020.
  i. Please refer to Attachment CPUC SED 2.13, specifically file "SED_13_5G41_Inventory" which provides inspection report of circuit 5G41 and identification of locations requiring work. The inspection date of the closest location where work was identified to the subject pole is July 20, 2020 and is highlighted yellow in the attachment. No work at the subject pole location was identified during inspection. During an inspection, work locations are recorded in the inventory report. Inspection of portions of the circuit where no work is identified are not recorded in the inventory report. Therefore, the inspection date of vegetation in the vicinity of the subject pole can reasonably be inferred to be on or about July 2, 2020, based on the inspection date of the nearest location where work was identified and took place prior to the fire ignition.

- 06241005.0110000 - 5G83 - Nearest work location to the identified to the latitude and longitude identified in the Figure 1 was inspected May 6, 2020.
  i. Please refer to Attachment CPUC SED 2.13, specifically file "SED_13_5G83_Inventory" which provides inspection report of circuit 5G83 and identification of locations requiring work. The inspection date of the closest location where work was identified to the subject pole is May 6, 2020 and is highlighted blue in the attachment. No work at the subject pole location was identified during inspection. During an inspection, work locations are recorded in the inventory report. Inspection of portions of the circuit where no work is identified are not recorded in the inventory report. Therefore, the inspection date of vegetation in the vicinity of the subject pole can reasonably be inferred to be on or about May 6, 2020, based on the inspection date of the nearest location where work was identified and took place prior to the fire ignition.

(e) PacifiCorp vegetation management inspection and correction times at locations nearest to the ignition location are as follows:

- 06241005.0013641 - 5G83 - Nearest work location corrected on 1/8/2021
  i. Please refer to Attachment CPUC SED 2.13, specifically file "SED_13_5G83_Work_Complete" which documents the work at the nearest work location was completed (highlighted blue).

- 06243009.0192400 - 5G41 - Nearest work location corrected on 8/11/2020.
  i. Please refer to Attachment CPUC SED 2.13, specifically file "SED_13_5G41_Work_Complete" which documents the work at the nearest work location was completed.

Despite PacifiCorp's diligent efforts, certain information protected from disclosure by the attorney-client privilege or other applicable privileges or law may have been included in its responses to these data requests. PacifiCorp did not intend to waive any applicable privileges or rights by the inadvertent disclosure of protected information, and PacifiCorp reserves its right to request the return or destruction of any privileged or protected materials that may have been inadvertently disclosed. Please inform PacifiCorp immediately if you become aware of any inadvertently disclosed information.

- 06241005.0110000 - 5G83 - Nearest work location corrected on 1/11/2021
    i. Please refer to Attachment CPUC SED 2.13, specifically file "SED_13_5G83_Work_Complete" which documents the work at the nearest work location was completed (highlighted blue).

Despite PacifiCorp's diligent efforts, certain information protected from disclosure by the attorney-client privilege or other applicable privileges or law may have been included in its responses to these data requests. PacifiCorp did not intend to waive any applicable privileges or rights by the inadvertent disclosure of protected information, and PacifiCorp reserves its right to request the return or destruction of any privileged or protected materials that may have been inadvertently disclosed. Please inform PacifiCorp immediately if you become aware of any inadvertently disclosed information.

PAC_218.02
(Public)

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P
1	**Pacific Power - Distribution Work Complete Report - All Work Codes**															
2	For 1/1/2020 to 12/31/2021; Transmission Or Distribution: Distribution; All; All States; All Companies; All Crew Foremen; All Districts; Feeder or Line: 5G83; All Work Codes; All Reliability Concerns; All Exceptions															
3	**R#**	**Date Work Completed**	**Crew Foreman**	**Company**	**District**	**Feeder**	**Work Code**	**Exception**	**Personal Contact Made?**	**Landowner Name**	**Address**	**City**	**State**	**Landowner Phone**	**Notes**	**Work Summary**
4		1/8/2021	Randy Briggs	Trees LLC - TX	MT SHASTA	5G83		No	No			Weed	CA			
5		1/11/2021	Randy Briggs	Trees LLC - TX	MT SHASTA	5G83		No	No			Weed	CA			

	A	B	C	D	E	F	R	S	T	U	V	W	X	Y	Z	AA	AB	AC	AD	AE	AF
1	**Pacific Power - Distribution Work Complete Report - All Work Codes**						**Total Work Completed Units by Mitigation Effort**														
2	For 1/1/2020 to 12/31/2021; Transmission Or Distribution: Distribution; All; All States; All Companies; All Crew Foremen; All Districts; Feeder or Line:						**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**
3	**R#**	**Date Work Completed**	**Crew Foreman**	**Company**	**District**	**Feeder**	**Prune**	**Secondary Prunes**	**Brush Prune Sq Ft**	**Removals Brush Sq Ft**	**Removals 6-11"**	**Removals 12-23"**	**Removals 24" +**	**Reliability Prunes Brush Sq Ft**	**Reliability Prunes 6-11"**	**Reliability Prunes 12-23"**	**Reliability Prunes 24" +**	**Reliability Removals Brush Sq Ft**	**Reliability Removals 6-11"**	**Reliability Removals 12-23"**	**Reliability Removals 24" +**
4		1/8/2021	Randy Briggs	Trees LLC - TX	MT SHASTA	5G83	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**
5		1/11/2021	Randy Briggs	Trees LLC - TX	MT SHASTA	5G83	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**

	A	B	C	D	E	F	AH	AI	AJ	AK
1	**Pacific Power - Distribution Work Complete Report - All Work Codes**									
2	For 1/1/2020 to 12/31/2021; Transmission Or Distribution: Distribution; All; All States; All Companies; All Crew Foremen; All Districts; Feeder or Line: 5G83;						**GIS References**			
3	**R#**	**Date Work Completed**	**Crew Foreman**	**Company**	**District**	**Feeder**	**LAT**	**LONG**	**Form ID**	**Map Object ID**
4		1/8/2021	Randy Briggs	Trees LLC - TX	MT SHASTA	5G83	[redacted]		38628	239141
5		1/11/2021	Randy Briggs	Trees LLC - TX	MT SHASTA	5G83			39360	237980

PAC_218.03
(Public)

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
1	**Pacific Power - Distribution Inventory Report - All Work Codes**																				
2	For 5/14/2020 to 5/14/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Inspectors; All Districts; All; All Work Codes; All Ownership; All Contact Types; All Crew Types; All Cycle Busters; All TGR; All Reliability Concerns																			**35**	**28**
3	**R#**	**Date Inspected**	**Time Inspected**	**Inspector**	**Company**	**District**	**Feeder**	**Work Code**	**Contact Type**	**Ownership**	**Landowner Name**	**Address**	**City**	**State**	**Landowner Phone**	**Landowner Email**	**Crew Type**	**Work Description**	**Work Summary**	**Cycle Busters**	**TGR?**
80	5.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			lift_climb	PTS 1 MAPLE POLE #E10899		0	No

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
1	**Pacific Power - Distribution Inventory Report - All Work Codes**							**Total Inventoried Units by Mitigation Effort**																		
2	For 5/14/2020 to 5/14/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Inspectors; All Districts; All; All Work Codes; All Ownership; All Contact Types; All Crew Types; All Cycle Busters; All TGR; All Reliability Concerns							**186**	**16**	**450**	**1445**	**1**	**4**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**GIS References**			
3	**R#**	**Date Inspected**	**Time Inspected**	**Inspector**	**Company**	**District**	**Feeder**	**Prune**	**Secondary Prunes**	**Brush Prune Sq Ft**	**Removals Brush Sq Ft**	**Removals 6-11"**	**Removals 12-23"**	**Removals 24" +**	**Reliability Prunes Brush Sq Ft**	**Reliability Prunes 6-11"**	**Reliability Prunes 12-23"**	**Reliability Prunes 24" +**	**Reliability Removals Brush Sq Ft**	**Reliability Removals 6-11"**	**Reliability Removals 12-23"**	**Reliability Removals 24" +**	**LAT**	**LONG**	**Form ID**	**Map Object ID**
80	5.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]	[redacted]	2227	239141

Pacific Power - Distribution Inventory Report - All Work Codes

For 5/14/2020 to 5/14/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Inspectors; All Districts; All; All Work Codes; All Ownership; All Contact Types; All Crew Types; All Cycle Busters; All TGR; All Reliability Concerns — 35 — 28

R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
3.8	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Personal				Albany	OR			Flagging	2 maples PTS		0	No
3.9	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	4 maples PTS		1	No
	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36		Personal				Chiloquin	OR	[redacted]		Lift	Pts 1 small leafed lime and 1 fruitless cherry UL P#065402		0	No
7.7	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36		Door_Card				Chiloquin	OR			Lift	Pts 2 spruce UL P#188305		0	No
8	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36		Personal				Chiloquin	OR			Lift	Pts 1 willow & 2 aspen UL p#174800		1	Yes
4	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	2 maples PTS		1	No
4.1	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Telephone				Albany	OR	[redacted]		Flagging	6 sweet gums PTS		0	No
4.2	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Climb	1 cedar PTS service		0	No
4.3	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Climb	1 maple 1 oak PTS		0	No
2.95	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	1 ash PTS front yard, 1 ash PTS service backyard climb		0	No
9.4	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Personal				Crooked river	OR			Lift	Pts 5 juniper front field along rd. Pts 4 juniper west of pl235400 along fence. Possible removals waiting on go ahead. Customer wants CHIPS. Please call ahead for dump location. Dianna[redacted]			
9.1	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Telephone				Crooked river	OR			Lift	Pts 2 juniper front yard pl234503. Clear service			
9.6	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 7 juniper front field along rd. Pts 3 juniper west of pl235300 to end pole at house. Pts 1 juniper to clear service			
9.7	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 3 juniper front field along rd			
9	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 1 juniper at pl233640			
10.1	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			lift_climb	Pts 1 juniper at driveway entrance. For gate access if needed call. [redacted]			
8.8	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Personal				Crooked river	OR			Lift	Remove 350' juniper brush at driveway entrance pl233701			
8.6	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Personal				Crooked	OR			Lift	Clear end pl233705. Call ahead to secure dogs. Joseph[redacted]			
10	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Personal				Crooked river	OR			Lift	Pts 1 juniper front field along rd. Pts 4 juniper west of pl234100 to end pl233100			
9.5	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 3 juniper front field along rd			

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
24	9.9	5/14/2020	12:00 AM	N/A		CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 9 juniper in front field along rd and along short tap across corner of field to Pony Tr. Remove 225' juniper near driveway entrance and pole. Pts 1 juniper to clear service. Call Brad for access through gate if needed. [redacted] talked to			
25	9.8	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 6 juniper in front field along rd . Removal 200' juniper brush under wire sw of pl235202			
26	8.6	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Remove 250' juniper brush at pl233700			
27	9.3	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 5 juniper front field along rd. Remove 100' juniper brush at pl234502, Remove 20' of juniper brush at pl235500			
28	10.2	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 3 juniper along stallion rd ending at mustang rd. Pts 1 juniper to clear service line to house.			
29	9.2	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 2 juniper front yard. Remove 100' juniper brush at pl234500			
30	8.9	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 1 juniper front yard			
31	8.6	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36		Door_Card				Chiloquin	OR			Lift	Pts 1 ponderosa ROL P#204800		0	No
32	10.3	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 2 juniper along fence to end pole. Remove 75' of juniper brush under wire. Pts 1 juniper to clear service			
33	10.4	5/14/2020	12:00 AM	Michael Tegano	Wright Tree Service	CENT OREGON	4D131		Door_Card				Crooked river	OR			Climb	*** don't drive in field *** Pts 5 juniper across field to end pole at house. Call ahead [redacted]			
34	10.5	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Remove 125' of juniper at pl and guide wire			
35	10.6	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Personal				Crooked river	OR			Lift	Pts 3 juniper west of pl233400 to end pl. Pts 2 juniper to clear service			
36	10.7	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Letter				Crooked river	OR			Lift	Pts 2 juniper at driveway entrance. Concerned customer. Call ahead [redacted]			
37	10.8	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Climb	Pts 1 juniper at driveway entrance. Pts 3 juniper along neighbouring fence line. West of pl233300. Neighbour's have been notified			
38	21.4	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70		Door_Card				Gates	OR			Flagging	Tap heading south. Pole 255103. Dead Alder, cedar and firs. ABSOLUTELY NO TRUCK DOWN DRIVEWAY TO 33502. No SPRAY.			

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
39	10.9	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked	OR			Climb	Pts 3 juniper along pony tr. Pts 1 juniper behind house to clear service			
40	11	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Personal				Crooked river	OR			Lift	Pts 2 juniper west of pl233201 to end pl232200. Pts 3 juniper in front field along filly pl			
41	11.1	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 1 juniper at driveway entrance. Pts 4 juniper at pl233202. Clear service			
42	11.2	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Personal				Crooked river	OR			Lift	Pts 1 juniper to clear service			
43	4.7	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	1 spruce PTS for service		0	No
44	11.6	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36		Personal				Chiloquin	OR	[redacted]		Lift	Make safe 2 black locust. Top below line height p#093703		0	No
45	4.4	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	Spruce PTS		0	No
46	21.6	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70		Door_Card				Gates	OR			Flagging	span east of previous. Maple at Pole# 255105.			
47	21.5	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70		Door_Card				Gates	OR			Flagging	First span east of tap heading south. Maple and fir.			
48	4.5	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	Maple PTS p-p sec		0	No
49	4.6	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	1 conifer PTS p-p sec		0	No
50	4.8	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	1 Pine PTS sec		0	No
51	21.7	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70		Door_Card				Gates	OR			Lift	Dry work . Tap heading south. Pole# 256101			
52	4.9	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261		Door_Card				Albany	OR			Flagging	2 sycamores in median PTS		0	No
53	21.8	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70		Door_Card				Gates	OR			Flagging	Next span. Pole 256101. Maple brush and maple to prune.			
54	11.5	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36		Door_Card				Chiloquin	OR			Lift	Pts 1 black poplar & 1 common pear p#047002		0	No
55		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Personal				Roseburg	OR	[redacted]		Lift	PTS 5 Douglas fir, 1 sweetgum east of P276501. Call owner before working on property.		0	No
56		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Climb	PTS 1 doug fir N of P277301.		0	No
57		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Personal				Roseburg	OR	[redacted]		lift_climb	Remove two large hazard trees east of P277404, at end of property. PTS 1 cedar, 1 doug fir east of P277404. PTS 1 doug fir west, 1 madrone under lines east of P276500 in backyard. Call owner before working on property.		0	No
58		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Lift	1 douglas fir NE of P277405.		0	No
59		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Lift	PTS 1 maple in driveway south of P277502.		0	No
60		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Lift	PTS 3 oak south, 3 oak north of P277503.		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
61		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Personal				Roseburg	OR			Lift	Remove large stem placing significant strain on svc/pole near driveway southeast of P277602		0	No
62		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Climb	PTS 1 douglass fir south of P277401.		0	No
63		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Climb	PTS 2 doug fir, 250sqft doug fir brush north of P277301 on hill. Poison oak in area. Left dh seeking removal of these trees.		0	No
64		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Lift	PTS 1 ash west of P277602, clear w/s off overhead guy wire.		0	No
65	11.3	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Door_Card				Crooked river	OR			Lift	Pts 1 juniper at end pl233202			
66		5/14/2020	12:00 AM	Gavin Cockrell	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Climb	PTS 1 sweetgum away from lines.			
67		5/14/2020	12:00 AM	Gavin Cockrell	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Lift	PTS cypress to the south east of line. Remove proposed pine snag to the south of line mid span.			
68		5/14/2020	12:00 AM	Gavin Cockrell	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Lift	Prune purple plum shrub below lines on northeast corner of property.		0	Yes
69		5/14/2020	12:00 AM	Gavin Cockrell	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Climb	Prune brush below utility lines in backyard. Could not access property due to gate. Inspected outside perimeter. Could not contact via phone.			
70	11.3	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131		Telephone				Crooked river	OR			Lift	Pts 2 juniper east of driveway entrance.			
71		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Lift	PTS 1 doug fir, 1 pine south of P276300. PTS 1 maple east of P276404.		0	No
72		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			lift_climb	PTS 1 grand fir, 1 oak, 1 plum, 1 sweetgum, west of P276300.		0	No
73		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			Lift	PTS 1 aspen southwest of P276402.			
74		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17		Door_Card				Roseburg	OR			lift_climb	PTS 1 cedar, 1 doug fir immediately north of P276402. 1 doug fir, 1 pagoda dogwood north of P276401.		0	No
75		5/14/2020	12:00 AM	Emily Dickson	ACRT	ROSEBURG	5U17		Personal				Roseburg	OR	[redacted]		Climb	1 Dougfir & 1 ponderosa PTS & take dead top from Doug-fir.1 oak remove front leg east P272000. 2 cottonwood PTS. Birds nest.1 oak PTS west P272000. 1 Doug-fir east P271001.1 oak PTS adjacent P271001 btwn fences. Leave message. Key to access easement. Cli		0	No
76		5/14/2020	12:00 AM	Emily Dickson	ACRT	ROSEBURG	5U17		Personal				Roseburg	OR			Lift	Access property from driveway to [redacted]. 2 Doug-fir PTS north of P271101. 2 oak PTS north and 2 oak south from P271101. Spoke to renter.		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
77	11.1	5/14/2020	12:00 AM	Jordan McMillan	ACRT	MEDFORD	5R227		Personal				MEDFORD	OR			Climb	PTS 1 oak by pole		0	No
78		5/14/2020	12:00 AM	Jordan McMillan	ACRT	MEDFORD	5R55B		Door_Card				ASHLAND	OR			Backyard_Lift	PTS 1pondo pine in backyard		0	No
79	10.9	5/14/2020	12:00 AM	Jordan McMillan	ACRT	MEDFORD	5R227		Personal				MEDFORD	OR			Backyard_Lift	PTS 1 oak under line		0	No
80	5.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			lift_climb	PTS 1 MAPLE POLE #E10899		0	No
81	10.6	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 MAPLE POLE #118402		1	Yes
82	10.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 3 GREY BIRCH 1 HAWTHORNE POLE #118404		0	No
83	10.8	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	REMOVE 3 LOCUST TREES POLE #118406		1	Yes

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
1	**Pacific Power - Distribution Inventory Report - All Work Codes**													**Total Inventoried Units by Mitigation Effort**												
2	For 5/4/2020 to 5/14/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Inspectors; All Districts; All; All Work Codes; All Ownership; All Contact Types; All Crew Types; All Cycle Busters; All TGR; All Reliability Concerns							**186**	**16**	**450**	**1445**	**1**	**4**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**GIS References**			
3	**R#**	**Date Inspected**	**Time Inspected**	**Inspector**	**Company**	**District**	**Feeder**	**Prune**	**Secondary Prunes**	**Brush Prune Sq Ft**	**Removals Brush Sq Ft**	**Removals 6-11"**	**Removals 12-23"**	**Removals 24" +**	**Reliability Prunes Brush Sq Ft**	**Reliability Prunes 6-11"**	**Reliability Prunes 12-23"**	**Reliability Prunes 24" +**	**Reliability Removals Brush Sq Ft**	**Reliability Removals 6-11"**	**Reliability Removals 12-23"**	**Reliability Removals 24" +**	**LAT**	**LONG**	**Form ID**	**Map Object ID**
4	3.8	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**		[redacted]		1876	242074
5	3.9	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**4**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1877	242075
6		5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1879	242159
7	7.7	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1880	235385
8	8	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36	**3**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1881	242229
9	4	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1882	242230
10	4.1	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**6**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1883	242231
11	4.2	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**0**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1884	242235
12	4.3	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1885	242242
13	2.95	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**1**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1886	242244
14	9.4	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**9**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1887	242249
15	9.1	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1888	242250
16	9.6	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**10**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1889	242251
17	9.7	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**3**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1890	242252
18	9	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1891	242253
19	10.1	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1892	242254
20	8.8	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**0**	**0**	**0**	**350**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1893	242255
21	8.6	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1894	242256
22	10	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**5**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1895	242257
23	9.5	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**3**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1896	242258
24	9.9	5/14/2020	12:00 AM	N/A		CENT OREGON	4D131	**10**	**1**	**0**	**225**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1897	242259
25	9.8	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**6**	**0**	**0**	**200**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1898	242260
26	8.6	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**0**	**0**	**0**	**250**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1899	242261
27	9.3	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**5**	**0**	**0**	**120**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1900	242262
28	10.2	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**3**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1901	242263
29	9.2	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**2**	**0**	**0**	**100**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1902	242264
30	8.9	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1903	242265
31	8.6	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1904	242274
32	10.3	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**2**	**1**	**0**	**75**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1905	242304
33	10.4	5/14/2020	12:00 AM	Michael Tegano	Wright Tree Service	CENT OREGON	4D131	**5**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1906	242315
34	10.5	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**0**	**0**	**0**	**125**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1907	242325
35	10.6	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**3**	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1908	242332
36	10.7	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1909	242340
37	10.8	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**4**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1910	242355
38	21.4	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1911	242375
39	10.9	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**3**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1912	242376
40	11	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**5**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1913	242383
41	11.1	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**5**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1914	242397
42	11.2	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	**0**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1915	242403
43	4.7	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**0**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1916	242404
44	11.6	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36	**2**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1917	241762
45	4.4	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**0**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1918	242406
46	21.6	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1919	242411
47	21.5	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1920	242412
48	4.5	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**0**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1921	242409
49	4.6	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**0**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1922	242410
50	4.8	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	**0**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1923	242420
51	21.7	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				1924	242415

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24" +	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24" +	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24" +	LAT	LONG	Form ID	Map Object ID
52	4.9	5/14/2020	12:00 AM	Azaria Bower	ACRT	ALBANY	4M261	2	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		1925	242423
53	21.8	5/14/2020	12:00 AM	Gary Tryon	Asplundh Tree Experts	STAYTON	4M70	0	0	0	0	0	0	0	0	0	0	0	0	0	0				1926	242425
54	11.5	5/14/2020	12:00 AM	Jarrod Lial	ACRT	KLAMATH FALLS	5L36	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1927	242421
55		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	6	0	0	0	0	0	0	0	0	0	0	0	0	0				1928	242434
56		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1929	242435
57		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	4	0	0	0	0	1	1	0	0	0	0	0	0	0				1930	242436
58		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1931	242437
59		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1932	242438
60		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	6	0	0	0	0	0	0	0	0	0	0	0	0	0				1933	242439
61		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	0	1	0	0	0	0	0	0	0	0	0	0	0	0				1934	242439
62		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1935	242440
63		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	2	0	250	0	0	0	0	0	0	0	0	0	0	0				1936	242440
64		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1937	242441
65	11.3	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1938	242443
66		5/14/2020	12:00 AM	Gavin Cockrell	ACRT	ROSEBURG	5U17	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1939	242455
67		5/14/2020	12:00 AM	Gavin Cockrell	ACRT	ROSEBURG	5U17	1	0	0	0	1	0	0	0	0	0	0	0	0	0				1940	242456
68		5/14/2020	12:00 AM	Gavin Cockrell	ACRT	ROSEBURG	5U17	0	0	100	0	0	0	0	0	0	0	0	0	0	0				1941	242459
69		5/14/2020	12:00 AM	Gavin Cockrell	ACRT	ROSEBURG	5U17	0	0	100	0	0	0	0	0	0	0	0	0	0	0				1942	242460
70	11.3	5/14/2020	12:00 AM	Robert Canaday	ACRT	CENT OREGON	4D131	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1943	242464
71		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	3	0	0	0	0	0	0	0	0	0	0	0	0	0				1944	242517
72		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	4	0	0	0	0	0	0	0	0	0	0	0	0	0				1945	242517
73		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1946	242518
74		5/14/2020	12:00 AM	Zach Wilder	ACRT	ROSEBURG	5U17	4	0	0	0	0	0	0	0	0	0	0	0	0	0				1947	242518
75		5/14/2020	12:00 AM	Emily Dickson	ACRT	ROSEBURG	5U17	9	0	0	0	0	0	0	0	0	0	0	0	0	0				1948	242581
76		5/14/2020	12:00 AM	Emily Dickson	ACRT	ROSEBURG	5U17	6	0	0	0	0	0	0	0	0	0	0	0	0	0				1949	242582
77	11.1	5/14/2020	12:00 AM	Jordan McMillan	ACRT	MEDFORD	5R227	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1950	242448
78		5/14/2020	12:00 AM	Jordan McMillan	ACRT	MEDFORD	5R55B	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1951	242449
79	10.9	5/14/2020	12:00 AM	Jordan McMillan	ACRT	MEDFORD	5R227	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1952	242461
80	5.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2227	239141
81	10.6	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2236	245497
82	10.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				2248	245510
83	10.8	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	0	0	0	0	3	0	0	0	0	0	0	0	0				2251	245514

PAC_218.04
(Public)

Pacific Power - Distribution Inventory Report - All Work Codes

For 1/1/2020 to 12/31/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Inspectors; All Districts; Feeder or Line: 5G83; All Work Codes; All Ownership; All Contact Types; All Crew Types; All Cycle Busters; All TGR; All Reliability Concerns

322 | 147

R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
8.5	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS 1 DOUG FIR OVERHANG NORTH OF POLE #224902		0	No
8.7	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	PTS 2 PINE OVERGANG 1/4 SPAN SOUTH OF POLE #154002		0	No
8.6	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			lift_climb	PTS 1 PINE overhang South of driveway		0	No
8.2	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	PTS 1 PINE OVERHANG southeast of driveway		0	No
1.1	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Flagging	PTS 1 SYCAMORE POLE #193640		0	No
4.4	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 100 FT.OF BRUSH EAST 3/4 WAY DOWN SPAN FROM POLE #264900		1	No
4.2	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA	[redacted]		Lift	Remove 1 Box Elder chip live branches and pile dead ones. Leave larger logs in manageable lengths.		0	No
4.3	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA	[redacted]		Lift	REMOVE 1 BLACK LOCUST TREE *STACK WOOD IN MANAGEABLE LENGTHS AND STACK ANY BRANCHES UNABLE TO CHIP*		0	No
4.6	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 2 LOCUST WEST OF POLE #E4137		1	No
4.5	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA	[redacted]		Lift	PTS 3 POPLAR WEST OF POLE E4135		1	No
3.8	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS 1 CEDAR 1/2 SPAN SOUTH OF POLE #		0	No
3.7	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	PTS 1 PINE 1/4 SPAN NORTH OF POLE #361501		0	No
3.9	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	PTS 1 PINE 1/2 SPAN SOUTH OF POLE #E13215		0	No
5.1	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	REMOVE 2 LOCUST TREES POLE #010900		1	No
3.2	5/1/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	REMOVE 2 BOX ELDER PTS 1 BOX ELDER POLE #E9972		1	Yes
3.1	5/1/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 4 BOX ELDER B/N POLE #E58 & #361144		1	Yes
3.3	5/1/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 COTTONWOOD BEHIND POLE #E9977		0	No
1.3	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA	[redacted]		lift_climb	PTS 3 OAK 1 PINE B/N POLE # E22351 & E22352		0	No
5.8	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA	[redacted]		Lift	PTS 1 BOX ELDER POLE # 012400 CALL AHEAD BEFORE WORK 5309384393 * requested I be on site during trimming*		0	No
2.9	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS 1 WILLOW WEST OF POLE #E4558 ACCESS FROM UNION ST.		1	No
2.7	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS 8 WILLOWS B/N POLE #365200 & #E18947		1	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
25	4.7	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA	[redacted]		lift_climb	PTS BLACK OAK POLE #E13216 *PRUNE HEAVY ON LINE SIDE TO REMOVE WEIGHT AND LESSEN CHANCE OF FALL INTO LINES*		0	No
26	5.9	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 2 ASH, 1 MAPLE & 1 ASPEN		1	No
27	6.1	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Lift	PTS 1 BOX ELDER POLE#011404		1	Yes
28	3.6	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Lift	PTS 2 BLACK OAKS NORTH OF POLE #13/45		0	No
29	3.5	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			lift_climb	PTS 1 BLACK OAK SOUTH OF POLE # 13/45		0	No
30	2.6	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA	[redacted]		Lift	PTS 1 CRAB APPLE * CALL NUMBER ABOVE BEFORE WORK TREE LOCATED IN DONKEY ENCLOSURE*		1	No
31	4.9	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 1 CEDAR IN REAR OF STRUCTURE BEST ACESS FROM ROAD BEHIND		0	No
32	4.8	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 CHERRY IN REAR OF STRUCTURE BEST ACCESS FROM KENNEDY AVE BEHIND STRUCTURE		1	No
33	5.5	5/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 LOCUST B/N POLE #011703 & #011707		1	No
34	5.2	5/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 BOX ELDER POLE #011706		1	No
35	5.3	5/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 2 LOCUST POLE #011801		1	Yes
36	5.4	5/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 RED MAPLE		0	No
37	9.3	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 white birch 2 ponderosa directly under line		0	No
38	9.4	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Lift	PTS 1 locust 1 white birch		0	No
39	9.2	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 maple on 449 1 maple at 443		0	No
40	9.1	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Lift	PTS 1 spruce		0	No
41	8.9	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			lift_climb	PTS 1 box leaf elder		0	No
42	9.6	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 ash		0	No
43	9.8	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 spruce 1 box edler		0	No
44	6.5	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Lift	PTS 6 oak on left side of rd. Directly under wire		0	No
45	6.4	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	Hazard tree underline 1 oak		1	No
46	6.3	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	PTS 1 oak 1 pondo pine		0	No
47	1.2	5/7/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Climb	PTS 7 POPLAR & 1 LOCUST POLE #194303		1	No
48	5.6	5/7/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Lift	PTS 2 WALNUT POLE # 012644		1	Yes
49	1.4	5/7/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Lift	PTS 3 CHERRY & 1 CEDAR POLE #7/037 BEST ACCESS FROM BEHIND SUBSTATION		1	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
50	2.5	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 2 CEDAR 1 PINE B/N POLE #1192 & #1171		0	No
51	1.9	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 ELM POLE #E7720		0	No
52	2.2	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 PINE NORTH OF POLE #E9275		0	No
53	2.3	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 PONDEROSA PINE NEAREST SOUTHERN MOST DRIVEWAY ENTRANCE POLE # E9275		0	No
54	1.8	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	Pts 1 black locust pole #311804		0	No
55	2.4	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 CEDAR & 1 PINE POLE #637		0	No
56	6.6	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA	[redacted]		Flagging	PTS 5 COTTONWOOD 1 OAK & 1 APPLE POLE #334700		1	No
57	6.2	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA	[redacted]		Climb	PTS 1 PONDEROSA PINE NO POLE NUMBERS ON BOTH POLES AROUND TREE *STOP BY OFFICE OF BLACK BUTTE TOWING BEFORE PROCEEDING WITH WORK*		0	No
58	1.5	5/12/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 1 CEDAR POLE #25800/E1221		0	No
59	6.9	5/13/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Flagging	PTS 1 PONDEROSA PINE POLE #040401		0	No
60	6.8	5/13/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 COTTONWOOD CORNER OF OLD HWY 99 AND N OLD STAGE RD		0	No
61	5.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			lift_climb	PTS 1 MAPLE POLE #E10899		0	No
62	10.6	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 MAPLE POLE #118402		1	Yes
63	10.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 3 GREY BIRCH 1 HAWTHORNE POLE #118404		0	No
64	10.8	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	REMOVE 3 LOCUST TREES POLE #118406		1	Yes
65	10.4	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 MAPLE POLE #117402		1	No
66	10.9	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 3 WALNUT POLE B/N POLE #118604 &#118509		1	Yes
67	10.2	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 BOX ELDER 2 WHITE BIRCH 1 RED MAPLE		1	Yes
68	10.5	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 2 COTTONWOOD POLE #118510		1	Yes
69	10.3	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 1 ELM B/N POLE #117502 & #117501		0	No
70	11.1	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 MAPLE POLE #117602		1	No
71	10.1	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 2 COTTONWOOD B/N POLE #117609 & #117506		1	Yes
72	11.2	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 BOX ELDER POLE #119405		1	Yes
73	11.3	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 COTTONWOOD B/ N POLE #119401 & #119309		1	Yes

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
74	9.5	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 ATLAS CEDAR NORTH OF POLE #116741		0	No
75	9.9	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS 2 LOCUST TREES POLE #117609		1	No
76	2.8	5/19/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS 1 MAPLE POLE #E17059		1	Yes
77	7.4	5/19/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA	[redacted]		Climb	CALL OWNER AHEAD OF WORK REMOVE DEAD PINE UPHILL OF LINES POLE #174600 *TREE IS FLAGGED* LOP AND SCATTER LIMBS AND STACK WOOD IN MANAGEBALE LENGHTS IN DITCH NEXT TO ROAD		0	No
78	11.4	5/19/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 2 LOCUST TREES WEST OF POLE #119307 BEHIND UNIT #12		1	Yes
79	8.4	5/20/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	REMOVE 1 DEAD WHITE FIR WEST OF LINES POLE #224900		0	No
80	8.3	5/20/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			lift_climb	PTS 1 CEDAR POLE #225802		0	No
81	7.5	5/21/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Climb	PTS 3 CEDARS POLE #162901		0	No
82	8.1	5/21/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS PINES & CEDARS POLE #229300		1	No
83	7.9	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS 1 ELM POLE NUMBER #169602		0	No
84	7.6	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			lift_climb	PTS 1 CEDAR POLE #163902		0	No
85	7.8	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Climb	PTS 1 ALDER POLE # 165801		1	No
86	7.7	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	REMOVE LOCUST POLE #E5439		1	No
87	7.2	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			lift_climb	PTS 2 CEDAR B/N POLE #092103 & #092201		0	No
88	7.3	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 1 APPLE TREE POLE #092201		1	No
89	8.8	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PRUNE 1 BLACK OAK TO RELIEVE WEIGHT ON LINE SIDE AND REDUCE STRIKE POTENTIAL ACROSS DRIVEWAY. PTS 7 BLACK OAK 1 CHERRY PLUM BUSH POLE B/N POLE #154500 & #153503		0	No
90	7.1	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 2 LOCUST POLE #092202		1	Yes
91	2.1	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 2 WALNUT POLE #E6877		1	No
92	3.4	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			lift_climb	PTS 1 BOX ELDER ACCESS THROUGH [redacted] DRIVEWAY		1	Yes
93	6.7	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA	[redacted]		Lift	PTS 6 WATER BIRCH, 1 WILLOW, & 1 GALLBERRY POLE #E17392 * Contact owner for access through locked gate off of Edgewood rd.*		1	No
94	1.7	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 POPLAR POLE #311802		1	Yes
95	1.6	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 2 BOX ELDERS POLE #311802		1	Yes

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
96	11.5	5/27/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Flagging	PTS HAZARD TREE DEAD CEDAR ON NORTH BOUND SIDE OF ROAD PRUNE TO REDUCE STRIKE POTENTIAL ACROSS FROM POLE #118501		0	No
97	1.5	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				McCloud	CA			Lift	PTS 1 CHERRY POLE #366000		1	No
98	99.2	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83		Personal				Weed	CA			lift_climb	Pole 030701 to 030601. Side/OV Pine, Remove three 12-23 Pine under lines and one 12-23 on side of lines. Remove two 12-23 Cedar under lines.		0	No
99	99.4	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83		Personal				Weed	CA			Climb	Pol 031704. Prune OV and under limbs on Pine by bench.		0	No
100	99.5	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83		Personal				Weed	CA			Climb	Pole 031704 to 031702. Side prune Cedar midspan. Prune Oak at end of span.		0	No
101	91.6	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	Pole 031701 to 031702. Short span behind main home. Prune oak.		0	No
102	99.9	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83		Personal				Weed	OR			Climb	Pole 030800. Remove 2 pine trees within 2 feet of lines. In field.		0	No
103	91.8	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			lift_climb	Remove three 6" Cedars and 2 Cedar saplings. Prune 4 trees for service drop.		0	No
104	99.1	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83		Personal				Weed	CA			lift_climb	Pole 030702 to 030701. Remove 2 6-12" and 1 12-23 Pine under lines. Side and Ov 2 Pine. Remove dead 12-23 Pine.		0	No
105	91.7	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			Climb	Pole 031701. Prune Oak, Cedar and 2 Fir.		0	No
106	91.3	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				Weed	CA			lift_climb	Pole 030600 to 030700. Remove 12-23 Pine under line at pole 030600, Pine side 1/4 span, Pine side 3/4 span.		0	No
107	92.4	5/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 2 PINE & REMOVE 2 LOCUST POLE #030902		0	No
108	92.5	5/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 2 CEDAR & 2 PINE B/N POLE #030__1 & #		0	No
109	92.3	5/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 1 WALNUT POLE #030904		0	No
110	92.6	5/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	PTS 3 PINE & 2 CEDAR 1/3 SPAN B/N POLE #030801 & #		0	No
111		6/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 1 CEDAR REMOVE 3 CEDARS POLE #031901		0	No
112		6/16/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 MAPLE POLE #115646		1	Yes
113		7/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				Weed	CA			Lift	PTS 1 FIR POLE #E10762		0	No
114	11.7	7/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 OAK MIDSPAN EAST OF LINE B/N POLE #3/47 & #2/47		0	No
115	11.8	7/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Climb	PTS 1 OAK MIDSPAN B/N POLE #3/47 & #4/47		0	No
116	12.1	7/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 PINE WITHIN 4' OF LINE SOUTH OF POLE #6/47		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
117		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	HAZARD TREE MAKE SAFE 2 DEAD PINE BOTH SIDES OF ROAD 1 NORTH AND 1 SOUTH OF LINE POLE #177801		0	No
118		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	HAZARD TREE MAKE SAFE 1 CEDAR SNAG UPHILL OF POLE #176700		0	No
119		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	HAZARD TREE MAKE SAFE 1 RECENTLY DECLINED PINE EAST OF POLE #176600		0	No
120		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Climb	HAZARD TREE MAKE SAFE 1 PINE & 1 DEAD PINE LIMB NORTH OF LINE POLE #177800		0	No
121		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			lift_climb	MAKE SAFE DEAD TOP PINE POLE #179900		0	No
122		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 1 PINE POLE #119403		0	No
123		9/12/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Personal				WEED	CA			Lift	PTS 1 LOCUST POLE #E15380		1	Yes
124		9/13/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Personal				Weed	CA			lift_climb	PTS 1 dead top out of cedar mid span make safe 1 small dead cedar same spot		0	No
125		9/13/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Personal				Weed	CA			lift_climb	PTS 1 oak mid span touching wire access through off rd or behind Houston meadows wood		0	No
126		9/13/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83		Telephone				Weed	CA	[redacted]		lift_climb	Make safe 1 huge dead top Doug fir right hand side of line and end pole if standing in drive by gate		0	No
127	11.6	9/24/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 3 PINE, 2 FIR & 2 CEDARS B/N POLE#E16330 & #		0	No
128	11.7	9/24/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 PINE POLE #E16317 "ACCESSED OFF WILLOW AVE"		0	No
129		9/24/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83		Door_Card				WEED	CA			Lift	PTS 1 PINE SOUTH OF POLE #E12318		0	No

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
1	**Pacific Power - Distribution Inventory Report - All Work Codes**							**Total Inventoried Units by Mitigation Effort**																		
2	For 1/1/2020 to 12/31/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Inspectors; All Districts; Feeder or							**227**	**4**	**300**	**300**	**13**	**20**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**GIS References**			
3	**R#**	**Date Inspected**	**Time Inspected**	**Inspector**	**Company**	**District**	**Feeder**	**Prune**	**Secondary Prunes**	**Brush Prune Sq Ft**	**Removals Brush Sq Ft**	**Removals 6-11"**	**Removals 12-23"**	**Removals 24"+**	**Reliability Prunes Brush Sq Ft**	**Reliability Prunes 6-11"**	**Reliability Prunes 12-23"**	**Reliability Prunes 24"+**	**Reliability Removals Brush Sq Ft**	**Reliability Removals 6-11"**	**Reliability Removals 12-23"**	**Reliability Removals 24"+**	**LAT**	**LONG**	**Form ID**	**Map Object ID**
4	8.5	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]	[redacted]	1123	230192
5	8.7	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1124	230193
6	8.6	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1125	230194
7	8.2	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1126	230195
8	1.1	4/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1144	230343
9	4.4	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	0	100	0	0	0	0	0	0	0	0	0	0	0				1196	230716
10	4.2	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	0	0	0	0	0	1	0	0	0	0	0	0	0				1198	230748
11	4.3	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	0	0	0	0	1	0	0	0	0	0	0	0	0				1201	230758
12	4.6	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1214	230900
13	4.5	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1219	230934
14	3.8	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1228	230996
15	3.7	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1229	230998
16	3.9	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1230	230997
17	5.1	4/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	2	0	0	0	0	0	0	0	0	0				1237	231059
18	3.2	5/1/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	2	0	0	0	0	0	0	0	0	0				1425	236022
19	3.1	5/1/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				1429	236026
20	3.3	5/1/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1432	236030
21	1.3	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				1422	230691
22	5.8	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1423	236020
23	2.9	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1424	236021
24	2.7	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	8	0	0	0	0	0	0	0	0	0	0	0	0	0				1426	236023
25	4.7	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1428	236025
26	5.9	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				1430	236027
27	6.1	5/4/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1431	236029
28	3.6	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1455	236233

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
29	3.5	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		1458	236235
30	2.6	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1459	236256
31	4.9	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1472	237755
32	4.8	5/5/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1473	237756
33	5.5	5/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1484	237922
34	5.2	5/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1486	237964
35	5.3	5/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1487	237963
36	5.4	5/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1488	237967
37	9.3	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	3	0	0	0	0	0	0	0	0	0	0	0	0	0				1490	237935
38	9.4	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1491	237973
39	9.2	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1492	237976
40	9.1	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1493	237980
41	8.9	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1494	237983
42	9.6	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1495	237988
43	9.8	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1500	238020
44	6.5	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	6	0	0	0	0	0	0	0	0	0	0	0	0	0				1503	238047
45	6.4	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1504	238064
46	6.3	5/6/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1505	238069
47	1.2	5/7/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	8	0	0	0	0	0	0	0	0	0	0	0	0	0				1596	230381
48	5.6	5/7/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1598	239139
49	1.4	5/7/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				1601	239143
50	2.5	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				1599	239140
51	1.9	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1605	239184
52	2.2	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				1608	239214
53	2.3	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2224	239471
54	1.8	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2225	239472
55	2.4	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2226	239473
56	6.6	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	7	0	0	0	0	0	0	0	0	0	0	0	0	0				2232	245490
57	6.2	5/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2234	245494

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
58	1.5	5/12/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		2243	245504
59	6.9	5/13/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2244	245505
60	6.8	5/13/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2250	245513
61	5.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2227	239141
62	10.6	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2236	245497
63	10.7	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				2248	245510
64	10.8	5/14/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	0	0	0	0	3	0	0	0	0	0	0	0	0				2251	245514
65	10.4	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2228	245486
66	10.9	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	3	0	0	0	0	0	0	0	0	0	0	0	0	0				2229	245487
67	10.2	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				2230	245488
68	10.5	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2237	245498
69	10.3	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2238	245499
70	11.1	5/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2245	245506
71	10.1	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2233	245493
72	11.2	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2235	245495
73	11.3	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2240	245501
74	9.5	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2246	245508
75	9.9	5/18/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2249	245511
76	2.8	5/19/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2239	245500
77	7.4	5/19/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	0	0	0	0	1	0	0	0	0	0	0	0	0				2241	245502
78	11.4	5/19/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2247	245509
79	8.4	5/20/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	0	0	0	0	1	0	0	0	0	0	0	0	0				2231	245489
80	8.3	5/20/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2242	245503
81	7.5	5/21/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	3	0	0	0	0	0	0	0	0	0	0	0	0	0				2667	249869
82	8.1	5/21/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	5	0	0	0	0	0	0	0	0	0	0	0	0	0				2680	249890
83	7.9	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2668	249873
84	7.6	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2669	249875
85	7.8	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2671	249878
86	7.7	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	0	0	100	0	0	0	0	0	0	0	0	0	0				2673	249880
87	7.2	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2675	249882

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
88	7.3	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		2676	249884
89	8.8	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	8	0	100	0	0	0	0	0	0	0	0	0	0	0				2677	249885
90	7.1	5/22/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2679	249887
91	2.1	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2670	249877
92	3.4	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2672	249879
93	6.7	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	100	0	0	0	0	0	0	0	0	0	0	0				2674	249881
94	1.7	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	5	0	0	0	0	0	0	0	0	0	0	0	0	0				2678	249886
95	1.6	5/26/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2681	249891
96	11.5	5/27/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2682	249888
97	1.5	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2769	250206
98	99.2	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83	1	0	0	0	0	6	0	0	0	0	0	0	0	0				2849	46744
99	99.4	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2850	46744
100	99.5	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				2851	46744
101	91.6	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2852	250666
102	99.9	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83	0	0	0	0	0	2	0	0	0	0	0	0	0	0				2853	250667
103	91.8	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	0	4	0	200	3	0	0	0	0	0	0	0	0	0				2854	250668
104	99.1	5/28/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	MT SHASTA	5G83	2	0	0	0	1	3	0	0	0	0	0	0	0	0				2855	250669
105	91.7	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				2856	250672
106	91.3	5/28/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	1	0	0	0	0	0	0	0	0				2857	250675
107	92.4	5/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	2	0	0	0	0	0	0	0	0	0				2942	251196
108	92.5	5/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	4	0	0	0	0	0	0	0	0	0	0	0	0	0				2943	251198
109	92.3	5/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				2944	251199
110	92.6	5/29/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	5	0	0	0	0	0	0	0	0	0	0	0	0	0				2974	251202

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
111		6/11/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	2	1	0	0	0	0	0	0	0	0		[redacted]		7429	251190
112		6/16/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				7711	237976
113		7/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9554	268843
114	11.7	7/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9682	268154
115	11.8	7/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9683	268161
116	12.1	7/6/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9684	268165
117		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13592	290548
118		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	1	0	0	0	0	0	0	0	0	0				13593	290549
119		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	1	0	0	0	0	0	0	0	0				13594	290550
120		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13595	290551
121		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13596	290552
122		8/15/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13597	274229
123		9/12/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				15858	302361
124		9/13/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	2	0	0	0	0	0	0	0	0	0	0	0	0	0				15860	302562
125		9/13/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				15861	302564
126		9/13/2020	12:00 AM	Jordan McMillan	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				15862	302565
127	11.6	9/24/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	7	0	0	0	0	0	0	0	0	0	0	0	0	0				17840	307571
128	11.7	9/24/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17841	307572
129		9/24/2020	12:00 AM	Megan Trujillo	ACRT	MT SHASTA	5G83	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17842	239214

PAC_218.05
(Public)

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P
1	**Pacific Power - Distribution Work Complete Report - All Work Codes**															
2	For 8/11/2020 to 8/11/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Crew Foremen; All Districts; Feeder or Line: 5G41; All Work Codes; All Reliability Concerns; All Exceptions															
3	**R#**	**Date Work Completed**	**Crew Foreman**	**Company**	**District**	**Feeder**	**Work Code**	**Exception**	**Personal Contact Made?**	**Landowner Name**	**Address**	**City**	**State**	**Landowner Phone**	**Notes**	**Work Summary**
4	5.2000	8/11/2020	Dustin Geffe	Trees LLC - TX	YREKA	5G41		No	No		[redacted]	Etna	CA			

	A	B	C	D	E	F	R	S	T	U	V	W	X	Y	Z	AA	AB	AC	AD	AE	AF
1	**Pacific Power - Distribution Work Complete Report - All**													**Total Work Completed Units by Mitigation Effort**							
2	For 8/11/2020 to 8/11/2020; Transmission Or Distribution: Distribution; All; All States; All						**0**	**0**	**0**	**0**	**6**	**6**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**
3	**R#**	**Date Work Completed**	**Crew Foreman**	**Company**	**District**	**Feeder**	**Prune**	**Secondary Prunes**	**Brush Prune Sq Ft**	**Removals Brush Sq Ft**	**Removals 6-11"**	**Removals 12-23"**	**Removals 24" +**	**Reliability Prunes Brush Sq Ft**	**Reliability Prunes 6-11"**	**Reliability Prunes 12-23"**	**Reliability Prunes 24" +**	**Reliability Removals Brush Sq Ft**	**Reliability Removals 6-11"**	**Reliability Removals 12-23"**	**Reliability Removals 24" +**
4	5.2000	8/11/2020	Dustin Geffe	Trees LLC - TX	YREKA	5G41	**0**	**0**	**0**	**0**	**6**	**6**	**1**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**

	A	B	C	D	E	F	AH	AI	AJ	AK
1	**Pacific Power - Distribution Work Complete Report - All**									
2	For 8/11/2020 to 8/11/2020; Transmission Or Distribution: Distribution; All; All States; All						**GIS References**			
3	**R#**	**Date Work Completed**	**Crew Foreman**	**Company**	**District**	**Feeder**	**LAT**	**LONG**	**Form ID**	**Map Object ID**
4	5.2000	8/11/2020	Dustin Geffe	Trees LLC - TX	YREKA	5G41	[redacted]		14617	268326

PAC_218.06
(Public)

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
1	**Pacific Power - Distribution_Inventory Report -All Work Codes**																				
2	For 1/1/2020 to 12/31/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Inspectors; All Districts; Feeder or Line: 5G41; All Work Codes; All Ownership; All Contact Types; All Crew Types; All Cycle Busters; All TGR; All Reliability Concerns																			**427**	**364**
3	**R#**	**Date Inspected**	**Time Inspected**	**Inspector**	**Company**	**District**	**Feeder**	**Work Code**	**Contact Type**	**Ownership**	**Landowner Name**	**Address**	**City**	**State**	**Landowner Phone**	**Landowner Email**	**Crew Type**	**Work Description**	**Work Summary**	**Cycle Busters**	**TGR?**
4	2.9	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Fort Jones	CA			Backyard_Lift	PTS 1 plum hawthorn under wire by wooden fence		0	No
5	1.2	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pondo pine mid span on corner		0	No
6	1.3	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS pondo pine 1 by pole 1 mid span heading up mustang ln		0	No
7	1.5	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 4 pone pine 2 next to pole 2 heading west down highway towards substation		0	No
8	1.6	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 50sq ft pondo pine by pole heading S toward next pole		0	No
9	1.7	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 2 pondo pines at driveway entrance		0	No
10	1.8	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 pondo by pole 1 pondo mid span West of pole 1 oak 1 pondo pine mid span E of pole towards substation		0	No
11	1.9	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 2 pondo pines by pole		0	No
12	2.1	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 2 pondo pines under line by pole across highway		0	No
13	2.2	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 Pondo under line at address [redacted]		0	No
14	15.9	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	PTS 40 Pondo pines from pole 05402 to pole 050501 9 spans of line. Entire section down the rd.		0	No
15	2.6	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 pondo by pole 1 oak heading N on highway 1 pondo across highway at pole 054903		0	No
16	2.8	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 plum hawthorn in irrigation ditch		1	No
17	3.1	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Fort Jones	CA			Backyard_Lift	2 European bird cherry N of pole 2 European bird cherry E of pole towards old barn, 1 poplar mid span heading towards old barn		0	No
18	1.1	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 4 pondo pine heading towards houses mid span		0	No
19	2.7	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 Locust by pole 1 locust W of pole mid span by pole 1132		0	No
20	72.9	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 dying apple tree		0	No
21	73.2	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 juniper split at the top dead in middle of span		0	No
22	73.1	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 oak by barn in creek		0	No
23	73.3	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 oak 1 pondo pine under line in alfalfa field		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
24	72.6	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 3 juniper under wire		0	No
25	72.4	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 juniper by pole		0	No
26	72.3	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 6 plums under wire 4 cedar hedge 2 apple at pole 1 locust 1 maple out front on Eastside by pole 120502		0	No
27	72.5	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 split juniper under line mid span		0	No
28	71.7	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA	93253306308		Flagging	PTS 1 locust by house slot of dead matter in canopy 1 box elder with dead further downw line by pole 0223300		0	No
29	70.9	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 poplar 2 black Hawthorne		0	No
30	6.6	6/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Phoenix	OR			Lift	PTS 1 FIR 2 williow		0	No
31	4.7	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Letter				Etna	CA			lift_climb	PTS 1 pondo pine on downhill side heading south 1 oak 1 pondo pine next to pole 1 oak mid span heading North		0	No
32	4.5	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 3 Pondo pine by barn mid span heading north		0	No
33	4.6	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 2 dead snags along road behind barn heading north		0	No
34	4.9	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 2 oak mid span heading East		0	No
35	5.1	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 apple mid span in yard 2 willow in yard		0	No
36	4.8	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove 2 dead pondo pine mid span		0	No
37	6.9	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Scott valley etna	CA			lift_climb	Remove 1 dead pondo pine in crux of line at pole B6551		0	No
38	7.1	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 pondo pine by pole it's the one starting to die		0	No
39	4.4	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 DOUG FIR BY pole 1 Arborvitae by pole		0	No
40	4.1	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 locust by pole		0	No
41	3.9	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 locust by pole		0	No
42	4.2	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA	5305985564		Lift	PTS 1 oak mid span uphillside on other side of chain fence. 1 locust mid span on down hill side by other house a d white fence. Call ahead		0	No
43	4.3	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 locust 1 poplar 1 spruce 1 fruiting tree along side of house		0	No
44		6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 Top of big poplar dead 1 small poplar under line 1 pine 1 fruiting tree by pole B6589 work your way north		0	No
45		6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak heading north mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
46		6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 oak on south side next to pole		0	No
47	6.4	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 small pondo pine mid span heading north away from house		0	No
48	6.5	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 oak behind royal coachman trailer a d camper on downhill side		0	No
49	6.8	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 DEAD pondo pine mid span heading up the hill you will see it from rd.		0	No
50	6.4	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 small pondo pine mid span heading north away from house		0	No
51	6.5	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 oak behind royal coachman trailer a d camper on downhill side		0	No
52	6.8	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 DEAD pondo pine mid span heading up the hill you will see it from rd.		0	No
53	17.3	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak mid span on dirt road off highway 436 underwire left side of rd		0	No
54	17.5	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 alder in canal		1	No
55	17.6	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo pine along roadside by pole work west down highway		0	No
56	17.7	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 pondo pine 1 mid span one close to pole		0	No
57	17.8	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo pine along driveway under line mid span		0	No
58	18.1	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 hig leaf maple behind house near end pole in ditch		0	No
59	18.3	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 elderberry by pole 1 oak reaching toward wire on uphill side keep walking uphill to mid span where you will find 1 Doug fir and 1 cedar under wire		0	No
60	18.2	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS Start at pole 296601 work north down line 1 pondo pine 1 fruiting tree 1oak at pole 296704 all under wire along fence located on back of property line		0	No
61	17.9	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 cedar mid span front of house under wire		0	No
62	19.2	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 dying Juniper hazard tree		0	No
63	30.5	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak 1 walnut/ash in front of house		0	No
64	30.3	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cedar outside house mid span uphill side		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
65	30.1	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 large oak in yard of 839 close to the end pole		0	No
66	30.2	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak 1 cedar by pole on front fence 1 cedar at end of fence close to pole 296105		0	No
67	20.9	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 elm up along drive		0	No
68	20.8	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 oak by pole		0	No
69	20.7	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo pine on corner of church and Cleveland		0	No
70	20.6	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak by pole back of house		0	No
71	17.1	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak next to substation		0	No
72	73.6	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 locust in front of house by fence		0	No
73	74.1	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak left side of house under wire reaching toward top wire		0	No
74	73.8	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 oak by pole 4 oak moving down toward pole 057401 at pole remove 2 pondo pine brush		0	No
75	73.9	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				E	CA			Backyard_Lift	PTS 1 oak 1 pondo pine in backyard area behind house		0	No
76	73.4	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 dying silver maple		0	No
77	73.5	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 hawthorne		0	No
78	73.7	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove 1 dead tree by end pole and trough		0	No
79	16.1	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 lodgepole Remove 1 dead lodge pole mid span to corner pole		0	No
80	15.5	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo pine mid span on irrigation canal		0	No
81	15.4	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo pine mid span		0	No
82	15.3	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 pondo pine next to pole 1 oak mid span		0	No
83	15.2	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak in front yard directly under line		0	No
84	15.1	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Poplar 1 fir mid span heading toward highway		0	No
85	14.9	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 oaks in front yard		0	No
86		7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 overhanging oak off right off dirt rd on line heading up the hill		0	No
87	3.3	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust next to pole 1 maple 1 cedar next to pole 294604 2 spans		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
88	5.2	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 cedar close to pole B280 remove 2 cedar mid span PTS 2 cedar by pole unmarked		0	No
89	5.3	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	Remove 4 dead pondo pine by pole		0	No
90	5.8	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 oak on downhill side mid span 1 by pole		0	No
91	6.1	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak by pole corner fence of front yard		0	No
92	6.2	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 black Hawthorne heading down dirt rd away from town		0	No
93	6.3	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 black Hawthorne in marsh area mid span		0	No
94	5.9	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 2 DYING LOCUST next to pole one off service drop		0	No
95	6.6	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak by pole under wire		0	No
96	6.7	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1oak by pole front of house		0	No
97	3.2	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 Box elder on side of road by pole			
98	7.2	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 large locust on side of house reaching toward wire		0	No
99	8.8	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 2 oak close to pole 312901 by pool 2 oak mid span towards pole 312900		0	No
100	8.9	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 Oak by pole 1 dead tree by abandoned white house		0	No
101	9.4	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 PONDO pine next to pole		0	No
102	11.7	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 dead Jeffery pine mid span between pole 357400 and pole 357401		0	No
103	11.2	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS The top of dying Jeffery pine with addresses tagged on it.		0	No
104	11.1	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 oak heading East about 30 ft from pole on roadside		0	No
105	10.8	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 dead Jeffery pine mid span heading NW down line off road toward house		0	No
106	10.6	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 Jeffery pine mid span heading south down rd.		0	No
107	9.8	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 oak under wire right as your approaching the house		0	No
108	10.4	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 dead Jeffery pine tree on right side of whispering pines dirt rd		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
109	10.3	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 dead Jeffery pine out away from line needs to be topped NE of pole		0	No
110	10.1	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 dead Jeffery pine on right side mid span heading East of pole		0	No
111	9.7	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak under wire by pole off N kidder creek heading east		0	No
112	9.5	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	Make safe 1 dead tree in crux of pole 367903 and 367902		0	No
113	9.5	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak mid span heading NE from pole 368900		0	No
114	9.3	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 oak mid an heading South from pole		0	No
115	9.2	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak mid span heading east down dirt road driveway		0	No
116	9.1	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 oak mid span south of pole back behind purple house along fence line		0	No
117		7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak by pole 6 oaks heading towards house left hand side		0	No
118	11.8	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 dead pondo pine mid span at the "slow please" sign		0	No
119	11.4	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Jeffery pine next to pole under wire		0	No
120	11.3	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 OAK mid span		0	No
121	11.5	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 Jeffery pine mid span heading south		0	No
122	11.6	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Jeffery pine mid span heading east, right off road under wire		0	No
123	10.9	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak by pole 1 Jeffery pine mid span on right side of drive way		0	No
124	10.7	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak by pole 1 Jeffery pine mud span heading toward main road		0	No
125	10.5	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 pondo pine on right side of driveway 30 ft from pole heading North		0	No
126	10.2	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak directly under wire mid span heading south of pole		0	No
127	9.9	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 pondo pine reaching out towards line mid span		0	No
128	8.7	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak mid span west of pole		0	No
129	12.1	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 dead fir tree HAZARD NW of pole about 50 ft. 1 oak mid span under wire		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
130	12.2	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 dead Jeffery pine Remove right next to wire access off of S kidder creek right after 1600 address sign down rd heading West PTS 1 poplar next to pole 368542		0	No
131	12.4	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 poplar 1 pondo pine next to pole along S kidder creek rd 1 pondo pine under wire next to pole 366400		0	No
132	12.5	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 dead top poplars next to pole. Turn off S kidder take a left and ita right by mailbox		0	No
133	12.6	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cedar surrounding pole		0	No
134	12.7	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 cedar by pole down driveway 1 on driveway 1 further down by creek		0	No
135	12.8	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 cedars by pole 1 alder 1 poplar mid span 1 oak by pole 363200		0	No
136	12.9	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 big ash mid span beside red barn behind restroom shed		0	No
137	12.3	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 Pondo pine mid span by fence heading away from S kidder creek		0	No
138	11.9	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 cedar under wire mid span heading west down S kidder		0	No
139	70.4	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 2 oak mid span by Main st sign with person reading a book		0	No
140	70.2	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 cedar under wire by pole at Etna city limit sign		0	No
141	70.1	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 dead poplar in old creek at bridge 1 maple under line at bridge		0	No
142	61.9	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 pondo pine by pole along highway at T of highway and Starr access rd		0	No
143	61.8	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 pondo pine mid span of pole 7 38 and 8 38 along S state highway 3 already touching wires.		0	No
144	8.4	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak by pole 1 cottonwood wood/ alder at corner of property underwire		0	No
145	8.6	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 pondo pine by pole		0	No
146	8.3	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 pondo pine 1 elm 1 oak in yard of 600 house		0	No
147	16.2	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 oak on back of property behind horses		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
148	16.3	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 oak directly under wire next to pole 050104 1 oak mid span 1 pondo mid span heading towards [redacted]		0	No
149	16.4	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1pondo pine 1 oak on back of property next to pole 050103		0	No
150	16.5	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 pondo pine by pole on back corner of property		0	No
151	16.6	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 dead pine next to line 50 ft from pole Make safe		0	No
152	16.9	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 large dead tree close to pole off of valley pines rd		0	No
153	16.7	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 dead pine 60 ft NW of pole 066000 make safe		0	No
154	7.5	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 elm tree off main south of pole 1 deadora cedar North of pole		0	No
155	7.7	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 Poplar under line behind white fence off main street.		0	No
156	7.6	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 3 oak along white fence line in front of house 1 elm 1 pondo across the street. From pole 295401		0	No
157	7.4	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 locust by pole in front yard		0	No
158	7.9	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 cedar next to pole 1 oak end of span next to pole 293303		0	No
159	8.1	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 juniper/cedar next to pole 2 cedar 1 pondo pine south of pole heading down mountain view a blue spruce end of span next to pole 292302		0	No
160	8.2	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 apple in front of house 1 locust on corner of property		0	No
161	8.5	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 6 poplars in front of house under line		0	No
162	14.7	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 2 locust in front yard off off pinecone drive		0	No
163	14.6	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 Pondo pine 20 ft south of pole 1 pondo pine 1 oak mid span heading south from marked pole toward end of rd.		0	No
164	14.2	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1pondo corner of property on red fir and pine cone heading SW of pole 1 pondo pine mid span 1 oak 2 pondos at end of span at next pole 067705		0	No
165	14.1	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 pondo 1 oak mid span in front of house SW of pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
166	13.8	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak on corner of property right by pole heading down white fir ln		0	No
167	13.7	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 pondo pine corner of property by green mailbox 1 oak at end of span by pole 065600		0	No
168	13.4	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 4 oak along span 1 oak by end of span pole 065603		0	No
169	13.3	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 oak mid span heading NW down line 1 oak at end of span and next pole		0	No
170	13.6	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 pondo pine at pole		0	No
171	13.5	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 noble for tree dead top		0	No
172	13.9	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak in front of yard		0	No
173	14.5	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak by rock wall 2 Doug fir1 oak around pole		0	No
174	14.4	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 oak and 1 pondo pine at 555 address sign		0	No
175	17.2	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 3 locust in front yard 1 oak in front yard 1 cedar in front yard all along the highway		0	No
176	40.1	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 2 maple 2 oak in pond by house work down the line to next trees 1 pondo pine out reaching toward line at next pole		0	No
177	40.2	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 3 pondo pine 1 oak mid span heading downhill		0	No
178	40.3	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 Pondo pone mid span up hill side 2 pondo near pole 2 pondo mid span 4 oak mid span heading downhill		0	No
179	60.1	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 2 oak by end pole work back towards Main rd 1 choke cherry mid span		0	No
180	60.2	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 2 OAK in irrigation flow		0	No
181	60.3	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 cedar at end pole with transformer in thicket of trees go past horse trailer and tractor cross two fences		0	No
182	50.9	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pondo mid span directly underline work towards end pole		0	No
183	18.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust trees at pole at start of alley in front of barn garage		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
184	18.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 box elder in back left corner of house backyard. Along brown wooden fence on Charles street		0	No
185	18.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 poplar by pole in front right hand corner of yard		0	No
186	18.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Poplar in front of house mid span of pole heading west 1 dead poplar on side of house.		0	No
187	18.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cedarcin front yard 1 elm tree on border of fence to next house by chickens		0	No
188	19.1	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 cherry trees in front yard 1 pondo pine 1 ash/walnut by pole		0	No
189	5.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Seiad	CA	5304963462		lift_climb	PTS 1 Cedar between house and trailer by pole 2 dead pines beside wire.		0	No
190	19.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 catalpa in front of abandoned house		0	No
191	19.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 elm tree in front of house under wire south of pole		0	No
192	19.3	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 poplar in corner of yard brown chain link fence		0	No
193	19.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Box Edler in front yard		0	No
194	19.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak side of house by driveway		0	No
195	19.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 locust 1 mulberry in front of yard 1 horse chestnut next house		0	No
196	50.2	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 Silver maple in front of abandoned house 1 black Hawthorne 1 pondo pine by pole		0	No
197	50.3	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 cedarvin front of house by pole under wire		0	No
198	50.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 OAK under wire in front of house		0	No
199	50.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 dead poplar at 2034 1 black Hawthorne at next pole along sawyers bar 324002		0	No
200	50.1	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 1 oak 1 walnut in front of house at end of rock wall 3 locust mid span under wire		0	No
201	40.9	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 Locust by pole 1 locust mid span by cedar		0	No
202	40.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak mid span heading NE towards town by dumpster		0	No
203	40.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1locust front if house by pole 1 oak mid span under wire heading v into town		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
204	50.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 3 oak in span to the end pole PTS 2 oak in span heading toward rd pole 325102 all under wire 2 spans		0	No
205	40.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 3 oak at pole in front of house right hand side of drive 2 OAK at second to last pole before end pole unmarked back behind house on fence line 325203		0	No
206	50.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pine 1 cedar at Y for driveway marked you are entering private property on circle saw		0	No
207	50.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS from pole 328100 towards end pole 1 cedar 1 alder/willow next to cedar directly under wire close to pole mid span 2 alder in creek to get there take first off shoot immideate right after gate with circle saw		0	No
208	40.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 2 oak 1 pondo mid span of pole heading out of town		0	No
209	40.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS from pole 326401 to end pole I span starting with 1 pondo pine 1 oak mid span work up drive to 1 pine 1 oak at end pole		0	No
210	30.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 OAK dead branches on downhill wire mid span from 1127 driveway 1 pondo line directly under wire 1 branch dead in oak by communications line these trees are in back yard of [redacted] 1 oak by end pole		0	No
211	30.9	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 2 pondo pines 1 pine in front of house along roadway under wire		0	No
212	30.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 6 oaks 1 by pole by 4 mailboxes		0	No
213	19.9	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 DEAD poplar on opposite side of rd by pond		0	No
214	20.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak 1 catalpa in front yard 1 oak 1 cedar 2 poplar along side of house on college street.		0	No
215	20.1	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 oak by pole heading downhill along college		0	No
216	20.3	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cedar in side yard by pole, work NW down street toward end pole 1 fir tree by pole 1 oak mid spa in Y of driveway 1 pondo pine 1oak by end pole 296301		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
217	20.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak in Front of yard 1 juniper 1 box elder 1 maple at next pole 297201 heading towards college street		0	No
218	20.2	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 dead pondo pine 1 pondo pine directly under wire 1 oak mid span on downhill side in front yard along driveway		0	No
219	30.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1crab apple side yard 1 locust front yard		0	No
220	60.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cherry tree front corner of yard 1 silver maple in next yard same span		0	No
221	60.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 2 oaks front yard 1 chestnut		0	No
222	60.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Letter				Etna	CA			Lift	PTS 1 elm tree reaching toward wire in front of church		0	No
223	60.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak by pole front yard		0	No
224	30.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 overhanging pondo pine mid span with slow children sign on it		0	No
225	60.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 white birch in front of yard dead crown		0	No
226	70.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak 2 spruce 2 cedar on rodeo rd in backyard		0	No
227	70.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust on corner of where Holzhauser lane and Island rd T Bone together		0	No
228	1.1	7/13/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	YREKA	5G41		Door_Card				Etna	CA			Lift	2 Oaks, 1 Chestnut PTS		1	Yes
229	1.2	7/13/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	YREKA	5G41		Door_Card				Etna	CA			Lift	7 Oaks PTS, 1 within 4'. Pole 328705		0	No
230	1.3	7/13/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	YREKA	5G41		Door_Card				Etna	CA			Lift	Oak, Walnut, Locust PTS, Pole 324005		1	Yes
231	71.8	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 willow mid span in creek 1 tree at end pole under line 1 tree at next pole SE of willow		0	No
232	72.7	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 box elder by pole across from white house		0	No
233	71.9	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 black Hawthorne mid span 3 willows heading west of pole 2 poplar by pole do entire span reaching up toward wire access these point through brown gate in right hand side if rd before getting to the house which if off to the right at Y down dirt rd. D		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
234	72.2	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 6 willow in creek under line in entire span 700 sq ft 3 black Hawthorne 2 choke cherry all the way out along river until you reach the clearing		1	No
235	72.1	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 5 willows in entire span 1 by pole main truck shooting up away from creek toward fence, small shoots off back go toward line rest under line 1 pondo pine		1	No
236	70.6	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 2 locust in front yard 1 lilac 1 apple mid span of pole heading west out towards field		0	No
237	70.7	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 2 oak going up hill reaching for line 1 at next pole		0	No
238	70.3	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 2 black Hawthorne by pole landmark speed sign coming into and leaving town		0	No
239	61.7	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo pine by pole 1 locust mid span 1 pondo mid span		0	No
240	61.6	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust by pole in front yard		0	No
241	61.5	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 catlpa at pole 1 cedar mid span heading west down to pole 284104		0	No
242	61.2	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 Choke cherry around pole.		0	No
243	61.3	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				E	CA			Lift	PTS 1 BOX elder in front of blue house 1 catapla in front of yellow house with cedar		0	No
244	61.4	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS top of dead cedar by pole 1 locust in front yard all in white fence		0	No
245	61.1	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Maple front yard 1 poplar next pole 283103 1 cedar on thatbpo.e as well		0	No
246	60.9	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cedar mid span heading towards the town Etna 1 apple down at pole surrounded in blackberries		0	No
247	18.9	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Dead locust in corner if yard by communication pole/wire make safe		0	No
248	17.4	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 oak under wire close to pole		0	No
249	5.4	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	Remove tree		0	No
250	5.5	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	Tree removal		0	No
251	5.6	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	1 dead tree mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
252	1.3	7/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Ashland	OR			Flagging	PTS 2 oaks mid span heading NW back towards town		0	No
253	5.5	7/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	Remove 2 small juniper underline mid span of pole 027400 and 026400 off Eller lane rd		0	No
254	71.6	7/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 apple tree at pole in backyard by the old barn		0	No
255	14.8	7/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo around corner pole with transformer at the end of the street		0	No
256	16.8	7/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove 3 dead pondos		0	No
257	1.1	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS entire span pole 1 35 to pole 175701 includes 13 black Hawthorne 7 choke cherry 1 oak Remove 1 small black Hawthorne mid span remove 1 choke cherry at pole 175701		0	No
258	1.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span pole 175701 to pole 176701 7 choke cherry remove 3 small choke cherry mid span in blackberries 2 black Hawthorne 1 oak at remove I small black Hawthorne end of span.		1	No
259	1.3	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 20 sq ft brush of black Hawthorne starting at pole moving down until mid span		0	No
260	1.4	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 8 square feet of choke cherry brush at pole		0	No
261	1.5	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 black Hawthorne in yard of white manufactured house off Holzhauser to pole 178702		1	No
262	1.6	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span pole 178702 to pole 1 black Hawthorne 4 willow 1 weeping willow remove 20 square feet choke cherry mid span 10 sq feet choke cherry brush and 1 black Hawthorne at next pole 178700		1	No
263	1.7	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 9 Black Hawthorne 30 ft black Hawthorne brush of entire span from pole 178700 to pole 179701 2 willow 1 black Hawthorne at pole 179701 30 ft willow brush 10ft black Hawthorne brush at that pole		1	No
264	1.8	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span from pole 179701 to unmarked corner pole by pink door barn with transformer PTS 5 willow 5 black Hawthorne		1	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
265	1.9	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS Entire span from unmarked pole to pole 160702 3 black Hawthorne 3 choke cherry top dead out of 1 willow mid span 1 willow		1	No
266	2.1	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span pole 160701 t0 160700 2 apple 3 willow remove 30 ft willow brush 30 ft Cherry brush 2 apple 2 willow 1 black Hawthorne towards end of span		1	No
267	2.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span pole 160700 to pole 161701 5 willow 5 black Hawthorne 1 choke cherry 3 apple 10 ft willow brush 10ft black Hawthorne brush		1	No
268	2.3	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span pole 161701 to pole 161700 10 black Hawthorne 1 willow		1	No
269	2.4	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	Remove 5 ft black Hawthorne brush west of pole close to pole in grass			
270	2.5	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 4 Black Hawthorne 1 apple at pole		0	No
271	2.7	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 4 black Hawthorne pole remove 10ft of black Hawthorne brush		0	No
272	2.6	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS dead out of 1 poplar at driveway 1 black Hawthorne mid span other side of driveway		0	No
273	2.8	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 5 black Hawthorne make safe 2 dead top cedars across rd by hay barn		0	No
274	2.9	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span pole 098000 to pole 099001 8 black Hawthorne 40ft black Hawthorne brush		0	No
275	3.1	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 6 black Hawthorne 50ft of black Hawthorne brush in spanof poles		0	No
276	3.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 black mid span		0	No
277	3.3	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 locust along Holzhauser lane		0	No
278	3.4	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 Locust by front drive 1 lilac 1 box elder by house off service drop		0	No
279	3.5	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust 4 elm 2 silver maple 1 is overhang rd		0	No
280	3.6	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 black Hawthorne 15ft black Hawthorne brush		0	No
281	3.7	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust at pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
282	3.8	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 2ft of oak brush by pole 1 big oak mid span heading towards houses		0	No
283	3.9	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 Aspen 2 black walnut 1 silver maple off service drop remove 5ft Aspen brush off service drop 1 black walnut mid span by entrance of driveway white gate		0	No
284	4.1	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 2 apple 1 black Hawthorne 1 cedar mid span by house 3 apple's aft et that towards end pole		0	No
285	4.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 maple off service drop PTS 1 silver maple behind house by barn, lots of dead branches		0	No
286	4.3	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 fruiting tree down field rd off to the right you'll see 1 tree on the entire line thats it.		0	No
287	4.4	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 6 locust in front of house		0	No
288	4.5	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 black Hawthorne 10ft of black brush		0	No
289	4.6	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 black Hawthorne mid span		0	No
290	4.7	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 juniper mid span		0	No
291	4.8	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 4 locust in front yard 1 locust 1 plum cherry 3 aspen 1 box elder/ash 1 lilac off service drop		0	No
292	74.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 6 willows in Scott river on back of property by wooden bridge		1	Yes
293	8.6	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 juniper mid span		0	No
294	8.7	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak opposite side of rd from pole 2 juniper mid span 3 juniper at next pole 302301		0	No
295	8.8	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 juniper		0	No
296	8.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 maple 1 juniper in front yard off service drop by wood shed 1 oak mid span 1 maple/ oak at end pole		0	No
297	8.5	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS from pole 257300 to pole 4 pondo pines 3 oak 1 juniper		0	No
298	8.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 2 juniper 1 pondo pine mid span heading North		0	No
299	8.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 2 pondo pines 4 oaks by pole 4 oaks mid span heading toward house 2 pondo pine at end pole in backyard of house		0	No
300	8.4	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 2 pondo by pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
301	8.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust by pole heading NE		0	No
302	7.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak on Eastside 2 oak on service drop		0	No
303	7.8	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	1 smaller locust along highway mid span 2 locust off service drop of house		0	No
304	7.7	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 Juniper mid span heading NE of pole 1 dying juniper SW of pole 10 ft of rose brush 1 black Hawthorne		0	No
305	7.6	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 10 sq ft black Hawthorne brush		0	No
306	7.5	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 juniper 1 poplar by pole		0	No
307	7.4	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 locust off service line by front of house off Eastside rd 1 maple on side of house in the back off service drop		0	No
308	7.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 4 box elder 1 black elderberry mid span		0	No
309	5.6	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 box edler 2 locust at pole side of house 2 locust 1 box elder by red barn off service drop from pole		0	No
310	5.7	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 juniper mid span heading west of pole remove 2small juniper by pole 029100		0	No
311	5.8	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 1 small pondo pine mid span of pole heading west		0	No
312	5.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 Juniper east of pole 1 juniper west of pole at pole 118803		0	No
313	6.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	1 locust 3 juniper mid span at culvert east from pole		1	No
314	6.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 juniper at pole 019701 behind barn with metal slant roof		0	No
315	6.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 3 juniper by pole heading East 3 juniper heading west		0	No
316	6.4	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 locust off drop 1 apple off drop 1 Aspen off drop 1 fir off drop by pole 120500		0	No
317	6.5	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 3 juniper to pole 121400 remove 1 small juniper next to pole		0	No
318	6.6	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 juniper East of pole 4 juniper west of pole 4 small juniper removals		0	No
319	6.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 juniper mid span heading south remove 3 small juniper heading north mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
320	7.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 Juniper at pole remove 2 small juniper brush south of pole PTS 1 pondo pine 1 juniper across rd		0	No
321	7.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 juniper mid span 2 pondo south of pole 1 juniper NE of pole mid span towards end pole 1 juniper at end pole		0	No
322	6.7	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 3 locust by pole along driveway		0	No
323	6.8	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 6 locust 1 maple 1 oak 2 locust boyband pole 1 apple off service drop 1 dead limb in locust off service line		0	No
324	5.4	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 3 locust in span heading south down rd.		0	No
325	5.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 locust off service drop 2 black Hawthorne 5 willow heading west over Scott river		1	No
326	5.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 3 locust in front yard 1 box alder heading SW down line		0	No
327	5.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 dead top shrub looking black walnut		0	No
328	4.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 30ft black brush		0	No
329	9.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 black Hawthorne at pole		0	No
330	9.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 willow mid span		0	No
331	9.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 willow mid span heading SE 9 black Hawthorne entire span to pole 106102		0	No
332	80.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 2 dying pondo pines make safe at pole		0	No
333	80.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	Make safe 2 dying pondo pines mid span		0	No
334		7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	Remove 4 small black Hawthorne brush 15sq ft at base of pole 5sq ft if choke cherry brush 8sq ft black Hawthorne brush mid span heading SW down Eller towards pole 044103		0	No
335		7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 black Hawthorne at pole 1black Hawthorne 30 ft to the left of pole		0	No
336		7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 silver maple at pole off service drop dead branches. 1 silver maple at next pole heading back out towards Eller lane 046101		0	No
337		7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 3 Black Hawthorne 2 choke cherry 1 oak 50ft brush		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
338	26.1	7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 5 oak mid span heading south down highway away from etna 1 oak 1 pine off service drop		0	No
339	26.2	7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 3 sq ft black Hawthorne brush by pole standing about 6ft tall		0	No
340	31.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo pine mid span 1 sage brush at next pole 322800		0	No
341	31.7	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 bitter brush next to pole		0	No
342	31.8	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo mid span remove two 5ft pondo pine brush mid span. One 5ft pondo pine brush towards next pole 320800 remove 100ft pine brush at pole 320800 work your way South down the PTS 1 pondo mid span		0	No
343		7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA				PTS 4 pondo pine mid span downhill side of pole. PTS Uphill side to next pole 1 pondo pine 1 box edler near pole 2 oak 3 pondo pine mid span 30 ft cherry brush remove 20 ft black walnut brush remove 10 ft oak brush remove mid span PTS 2 black Hawthorne 1		1	No
344	10.1	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 OAK 1 juniper by pole 1 juniper 1 pondo close to pole uphill side remove 30ft pondo pine brush under wire 5ft cedar brush PTS 1 pondo pine 10 ft pondo pine brush mid span 3 oak 10 ft pondo pine brush at next pole 220700		0	No
345		7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 3 locust 1 oak closs ro pole 7 locust mid span 1 oak 1 alder mid span 4 locust 1 pondo at next pole 220600		1	No
346	10.2	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 oak 1 pine 3 locust off service drop from transformer 3 pine close to pole heading downhill side towards house 1 apple 2 oak 1 locust mid span		1	No
347	10.3	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 oak 4 pine heading uphill		0	No
348	10.4	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 oak south of pole 6 oak north of pole Trees located off island rd		0	No
349	10.5	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 choke cherry north of pole		0	No
350	10.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 10 Oaks on island rd		0	No
351	10.7	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 3 oak 6 elm on island rd		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
352	10.8	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 oak at pole 1 oak 1 pine off service drop		0	No
353	10.9	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 OAK 1 has dead branches in front yard off service drop 4 pines SW of pole toward pole 286700		0	No
354	11.1	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	PTS 1 fruiting tree mid span of to the right.		0	No
355	11.2	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Climb	PTS 2 cedar 1 Willow 1 elderberry 1 cherry 1 spruce at end pole			
356	11.3	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 pine down hillside 1 cedar off service drop		0	No
357	11.4	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Turn down driveway, cross cattle guard, take rd off to the left at Y go up hill take next right wind down to old shed. PTS 2 pones by pole 1 pine off service drop		0	No
358	11.5	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 willow 1 black Hawthorne 1 choke cherry		0	No
359	11.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 willow at corner pole		1	No
360	11.7	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 cherry N of pole 1 catalpa 1 European white birch SW of pole		0	No
361	11.8	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 Aspen off service drop		0	No
362	11.9	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 lilac off service drop 1 fruiting tree 1 oak at end of span SW of pole heading towards next pole		0	No
363	12.1	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 Oak off service drop		0	No
364	12.2	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 6 cotton wood along drive 1 silver maple mid span heading toward house		0	No
365	12.3	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 silver maple mid span 1 small silver maple by white fence and RV		0	No
366	12.4	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 willow by pole 1 liquid amber off service drop heading west down the line toward the end pole 2 maple at end pole 284700 1 maple off service drop		0	No
367	12.5	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 locust 1 silver maple 1 oak off service drop to house [redacted] 1 European white birch off pole 284501 service drop		0	No
368	25.9	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 3 oak 1 cedar off service drop going to house and to highway		0	No
369	26.4	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1oak 1 cedar off service drop		0	No
370	26.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 catalpa 1 fruit tree by house off service drop		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
371	8.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	1 high risk tree Make safe dead tree across highway from pole 14 33 in back left corner of house		0	No
372	80.5	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 locust 1 pine off service drop 2 dying pondo pines risk trees by service line make safe		0	No
373	27.5	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA	5304674167		lift_climb	Make safe 1 dying pondo pine by house with bird box on it off service drop. Remove pondo pine brush to cycle spec in between span from marked pole to highway 1000sq ft brush in between 2 span to highway		0	No
374	80.8	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 sycamore 1 silver maple with alot of dead in the top 1 oak off service drop to shed from pole		0	No
375		7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 plum cherry off service drop to house 1 oak heading out towards highway under wire 1 pondo pine by highway startbof drive		0	No
376		7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Make safe 1 dying pondo pine off service drop		0	No
377	80.3	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 Pine by pole 2 pines mid span heading toward highway Remove 3 juniper mid span heading toward highway remove 1 big bent pondo leaning toward wire in pig pen remove 2 small pines mid span before pole 054300 remove 3 pondo pine under wire mid span tha		0	No
378	71.1	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 plum cherry off service drop to house 1 pine close to pole 2 overhanging pondo pine mid span 3 oak mid span heading north from pole		0	No
379	71.2	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 4 Pondo pine heading south toward house in entire span. 1 oak 1 pondo pine heading NW put towards highway bunch of 6 pine along fence going up toward wire		0	No
380	26.5	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 6 cherry by around pole		0	No
381	29.9	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 5ft pondo pine brush north of pole toward highways PTS entire span pole 324200 to pole 323203 to pole 6 pondo pine moving south down drive to [redacted]		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
382	29.8	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 2ft pondo brush north of pole right by it PTS 3 pondo mid span 1 is on opposite side of drive also remove 4ft pondo brush mid span		0	No
383	30.2	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 2 dying pondos by white garage		0	No
384	30.1	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 3 pondo pines 1east 1 at pole 1 west of pole heading towards next span		0	No
385	30.1	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 8 pondo pine north of pole 3 pondo 1 locust off service drop by shed 1 locust 1 maple SW of pole in front yard mid span 2 locust 1 pondo pine at entrance of house 1 dying top of pondo right side of entrance into gate after locust codominate stem		0	No
386	30.2	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Pondo pine off service drop 1 pondo heading SW of pole toward other service drop pole beside manufactured house 1 pondo off that service drop		0	No
387	32.2	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Climb	PTS 1 huge pondo near pole 3 pondo pines mid span heading towards highway		0	No
388	32.3	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	PTS 1 pondo by pole 2 pondo at pole across street surrounding pole		0	No
389	32.4	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			lift_climb	Remove 50 ft brush PTS 4 pondo pine mid span remove 1 pondo flagged pink		0	No
390	32.5	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			lift_climb	PTS 2 pondos 1 cherry off service drop by old shed		0	No
391	32.1	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 choke cherry at bridge 1 pondo SW of pole across higway heading into green view.		0	No
392	61.9	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	To get there head south down highway after main street and before S. Kiddervcreek rd you will see a hay barn turn left if heading south right if heading north. Follow that rd through alfalfa fields to pole. PTS 1 poplar 1 black Hawthorne remove 10ft willo		1	No
393	12.7	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 4 black Hawthorne 1 locust along highway at mailbox 124		0	No
394	12.8	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pondo 1 locust off service drop 1 cedar 1 Aspen heading East toward old tractor by pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
395	12.9	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 1 juniper 1 pondo at pole behind garage/shed		0	No
396	13.1	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 lilac off service drop house [redacted]		0	No
397	13.7	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 oak by pole 3 oak all on downhill side heading south from pole		0	No
398	13.8	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 pondo off service rd to the left before pole that Y in line		0	No
399	13.9	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 pondo south of pole on downhill side (right) of wire		0	No
400	14.1	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 dead cedar 1 pondo by pole 6 oak mid span of pole heading toward end pole		0	No
401	14.2	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 2 oak by pole		0	No
402	13.6	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 3 oak heading up hill, PTS 1 oak next span		0	No
403	13.5	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 3 oak 1 pine heading towards end pole		0	No
404	13.4	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 4 oaks along span heading NW		0	No
405	13.3	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 2 oak heading NW down line		0	No
406	17.1	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 oak by pole head east into trees PTS 2 poplar make safe dead poplar mid span 8 pine 1 oak 1 poplar mid span to pole 332700 600sq ft brush		0	No
407	16.9	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 8 small pines at pole 2 poplar 3 pines heading SE towards next pole 2 pines mid span 3 pines 1 cedar at next pole		0	No
408	16.8	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 overhanging pine at fence with cars 1 fir 1 silver maple off service drop PTS 1 oak 1 fir mid span 3 pines heading up hill 1 silver maple after next pole heading up hill		0	No
409	55.1	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 Pondo pine by pole 1 oak by pole 1 oak mid span		0	No
410	55.6	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS from pole 297702 to pole 297700 1 oak by marked pole 2 oaks at next pole 1 oak 1 cherry off service drop. To White House 1 dying elm off service drop to sage house [redacted]. PTS dead out of top of pine at pole 297700		0	No
411	55.5	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 elm mid span by speed limit 25		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
412	42.1	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 cedar by black mailbox across from marked pole 295706		0	No
413	41.9	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust off service drop next to pole		0	No
414	41.5	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cedar 1 elm by pole 295505		0	No
415	41.6	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust off service drop from pole		0	No
416	41.7	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 apple 1 willow off service drop at pole to house		0	No
417	41.8	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Locust off sevice drop to house by pole 1 pine in yard of 6924		0	No
418	41.2	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 box elder 1 locust by pole in front of house 1 dying fruit tree in yard of 6929 1 choke cherry 2 locust 1 box elder off service drop mid span at 6922 heading toward next pole 295600 1 box elder 1 locust off service drop at next pole heading south do		0	No
419	41.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 locust off service drop 2 locust mid span heading south down main off next service drop.		0	No
420	14.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 wisteria off service drop 3 willow 2 cedar 3 Aspen 1 oak in front yard 2 pondo pine 1 locust mid span		0	No
421	14.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 4 pondo pines along white fence east of pole mid span from last pole 1 pondo 1 box elder by pole and locked gate go through gate PTS 1 mulberry 1 Aspen mid span heading toward the river.		0	No
422	14.5	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pondo off service drop 1 pondo heading south towards [redacted] 3 poplar, sycamore mid-span with tree house, 1 maple 1 pondo mid span 2 pondo 1 box elder at gate of 123 Starr access be aware of loose dogs		0	No
423	14.6	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 oak off service drop to red house		0	No
424	14.7	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pondo by pole 7 oak heading south towards end pole		0	No
425	14.8	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 OAK 1 blue spruce 1 box elder in front of house off service drop		0	No
426	13.2	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Flagging	PTS 1 choke cherry under line by bridge		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
427	15.1	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Go to Etha creek on back of property PTS 1 poplar under line mid span of pole in field. Cross creek 3 poplar on that side at pole		0	No
428	15.2	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 4 pondo pines by pole 3 pondo mid span heading west towards next pole		0	No
429	15.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 mulberry off service drop by White House [redacted]		0	No
430	15.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 2 pondo pine mid span head west and 3 more pines at next pole on corner		0	No
431	15.5	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 oak 1 cedar by pole 1 pak 1 pine off service drop by shed 2 pondo pines mid span heading toward red door storage sheds		0	No
432	15.6	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 oak by pole 1 cedar 1 mulberry 1 mid span 2 willow at next pole 285203 1 oak off service drop pole 285202		0	No
433	15.7	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 overhanging oak at pole move to service drop pole 284200 PTS 1 pondo 1 cedar 1 Hawthorne to house 955		0	No
434	15.8	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 weeping birch trees off service drop		0	No
435	15.9	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 box elder 1 locust off service drop		0	No
436	16.1	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 choke cherry off service drop 1 plum cherry		0	No
437	69.8	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 apple of service drop		0	No
438	69.7	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 black Hawthorne SW of pole right next to it		0	No
439	69.6	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 5 black Hawthorne		0	No
440	69.5	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 black Hawthorne 1 fruiting tree by pole		0	No
441	69.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 poplar Bush by red fence remove 10ft black Hawthorne brush opposite side of poplar bush		0	No
442	69.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 4 black Hawthorne by pole heading out into field		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
443	27.6	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove all pondo brush in entire span from pole 055203 to pole 055202 directly under line 10 small trees/brush by pole head away from highway cross driveway and remove 14 pondo trees/brush 2 oak brush until you reach next pole 055202. Prune trees over 6 i		0	No
444	27.7	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 Pine 2 oak remove 6 small brush pine		0	No
445	27.9	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 1 dying pondo PTS 1 oak reaching towards line 1 oak at end of line pole 2 overhanging pines		0	No
446	27.8	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak off service drop		0	No
447	28.1	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 3 dying pondos mid span PTS 1 oak 1 pine off service drop		0	No
448	28.2	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust mid span of service drop 1 overhanging mulberry at address 4508		0	No
449	28.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 mulberry/ash in yard off service drop		0	No
450	28.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 maple 1 cedar off service drop		0	No
451	32.9	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust in the front yard off service drop 1 elm off service drop reaching towards wire		0	No
452	41.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 box elder 1 locust front yard [redacted] 2 locust mid span heading into town 1 by white stucco house 1 at myrtle street white house 1 locust off service drop behind house 6825		0	No
453	26.3	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 locust North of pole the one the end PTS 1 lilac 1 plum cherry by driveway South of pole		0	No
454	26.7	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 black Hawthorne by substation		0	No
455	26.8	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 5 black Hawthorne/cherry in ditch NE of pole heading towards Fort jones		0	No
456	26.9	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 mulberry mid span by 2 dead trees heading NE		0	No
457	27.1	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 6 choke cherry 1 black Hawthorne in front of house down along the highway heading towards etna		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
458	27.2	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 locust at driveway 1 locust behind wooden fence in front yard 1 locust off service drop on the side of the house. Not service drop 8n driveway		0	No
459	69.9	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 locust 1 maple in middle of creek. You can drive down there to work.		0	No
460	27.3	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo pine off service drop after gate of Patterson ranch		0	No
461	27.4	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 200 sq ft locust brush 1 mid span 1 near next pole 4 34		0	Yes
462	29.6	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak in middle of field only one under the wire		0	No
463	80.7	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 3 dead pondo pines at driveway off to the left		0	No
464	43.8	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 small apple mid span heading NE down line away from town		0	No
465	43.9	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 6 locust trees entire span from pole B126 to pole B8237		0	No
466	44.1	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 15ft of choke cherry brush by and around pole. No clean up		0	No
467	44.2	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS Entire span pole B135 to pole B136 1 oak 7 choke cherry remove dead out of top of 3 poplars 1 overhanging poplar. No clean up		0	No
468	44.3	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 4ft choke cherry brush move East down line PTS 3 choke cherry. No clean up		0	No
469	44.4	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 5 ft choke cherry brush at pole		0	No
470	44.5	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust west of pole 2 locust East of pole		0	No
471	45.3	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 7 oak on downhill side of pole		0	No
472	45.1	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 7 oaks on downhill side		0	No
473	45.2	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 6 oaks on downhill side of pole		0	No
474	39.6	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Make safe 1 leaning dying pondo pine remove 2ft oak brush by guy wire of pole		0	No
475	39.5	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 4 ft pondo pine brush directly underline south of pole 300100 mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
476	33.9	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 pine west of pole right next to it at American flag remove 5ft pondo pine brush west at yellow guy wire remove 4ft pondo pine brush under oak after 2338 green address sign remove dead out choke cherry and remove 3ft choke cherry brush in dry canal		0	No
477	33.8	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 OAK mid span remove 2ft oak brush mid span by oak tree		0	No
478	33.7	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 2ft pondo pine brush at pole PTS 1 pondo pine mid span remove 6ft pondo pine brush in middle of loop driveway along rd under wire remove 2 ft pondo pine brush PTS 1 oak 1 pondo pine opposite side of road at white tent structure remove 12ft pondo p		0	No
479	33.6	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 oak 1 pondo pine by pole		0	No
480	34.1	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove all pondo brush from pole 310900 to pole 369903		0	No
481	34.2	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove all pondo brush from pole 369903 to pole 369904 14ft worth		0	No
482	34.8	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 2 groupings of pondo pine brush 2 ft close to pole 5ft mid span by span		0	No
483	34.9	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak east of pole 1 pondo pine 1 oak west of pole		0	No
484	45.4	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 5 Oak on downhill side from pole		0	No
485	35.1	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 pondo pine by pole 1 oak west of that		0	No
486	35.9	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 3 dead pine trees		0	No
487	36.1	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 Oak 4 pondo pines off service drop make safe 2 dying pondo pines off second service drop close to house mid span. Beware of dogs		0	No
488	36.2	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 oak mid span 2 oak near next pole 365900 heading west		0	No
489	36.3	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 pondo 1 oak by pole		0	No
490	45.5	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 oak off service drop by shed		0	No
491	44.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak on left side of pole 249700 2 oaks mid span, one on each side of the road reaching out towards the line. Move to end pole at house 9635 Pts. 1 overhanging side pine		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
492	45.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 oak mid span on downhill side		0	No
493	45.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span heading downhill 1 oak by pole 3 oak mid span 3 oak near next pole B287		0	No
494	45.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 apple trees in front yard under wire 2 oaks near next pole B288		0	No
495	45.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 5 oak mid span B288		0	No
496	46.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Lift	PTS 3 oak mid span remove 15ft of oak brush mid span under line		0	No
497	46.2	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1oak 1 pine at pole 1 pine side mid span 2 oak mid span 1 oak at next pole remove 15ft oak brush under line move toward house pts 1 cedar side 1 oak under wire before next pole		0	No
498	49.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 4 bunches of black Hawthorne/fruiting trees around pole 1 cedar side 1 alder at next pole 236201		1	No
499	49.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 Huge pondo pine by pole back by old barn		0	No
500	49.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 black Hawthorne in creek close to end pole		0	No
501	50.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 3 oak at pole		0	No
502	50.2	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 apple mid span left side of drive at culvert 1 oak overhanging powerline		0	No
503	50.4	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 oak sides cross drive pts 2 more oak sides at next pole 2 cedar side mid span in drive way front of house 1 overhanging cedar stole B11227 1 overhanging pine mid span		0	No
504	50.5	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 cedar side 3 oak mid span heading down across field 1 pine at end corner pole of property. Move up drive towards dead end pts 3 cedars 1 overhanging pine 1 cedar 2 overhanging pine at pole B11230		0	No
505	50.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 Doug fir at pole 1 overhanging pine 1 oak up the rd from pole 3 overhanging oaks 1 dead branches out of overhanging pine		0	No
506	49.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 8 poplar 3 willow SW of pole 2 pondo pine 100ft willow brush 3 pondo pine heading NE of pole toward pole B7462		1	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
507	49.5	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 pondo pine 2 cherry remove 3 dead pondo pines unnder 6DBH mid span make safe 5 dying pondo pines in end span heading NE back towards town		0	No
508	49.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust 1 oak off service drop 1 oak side up dirt drive mid span to next pole B9783		0	No
509	47.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 oaks where wire crosses rd 3 oak at school sign white mailbox		0	No
510	36.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo off service drop work towards house 2 oaks after dreek 1 pine close to house remove 2 dead trees in front of house		0	No
511	37.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 fir mid span 1 oak mid span remove all small pines directly under line 11 brush size pines		0	No
512	37.2	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 oaks North of pole 1 oak 1 pine South of pole		0	No
513	37.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo by pole 1 pondo mid span reaching toward line 2 oak 1 pine down at next pole 358601 1 pine 1 oak off service drop of that pole		0	No
514	37.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 pondo pine off service drop Remove 20ft of pondo pine brush throughout span PTS 1 small dead pine close to next pole 358502		0	No
515	37.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 1 small pondo pine brush 1 small for brush at pole		0	No
516	38.2	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo East of pole 1 pondo west of pole		0	No
517	38.3	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 20ft pondo pine brush around pole on each side		0	No
518	38.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 1 pondo pine brush by pole PTS 1 oak and remove 1 oak brush mid span heading south of pole towards N kidder 1 oak mid span heading SW toward home		0	No
519	38.5	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak East of pole mid span, 1 pondo 1 fir by pole SW of pole		0	No
520	38.4	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 cedar 1 oak off service drop to grey house at end of line		0	No
521	38.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pondo 1 fir mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
522	38.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak mid span heading SE remove 1 oak brush mid span remove 50ft pondo pine brush of entire span until you reach pole 358401		0	No
523	37.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 20ft of oak at pole on each side PTS 2 pondo mid span East of pole		0	No
524	38.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 Doug fir off service drop to house off that pole		0	No
525	38.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 cedar off service drop remove 5ft of pine brush at pole		0	No
526	37.3	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 oak at pole to mid span		0	No
527	36.4	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak mid span down whispering pines rd		0	No
528	36.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pondo 2 oak off service drop		0	No
529	36.5	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 pines close to pole 1 mid span		0	No
530	36.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 pondo pines throughout entire span.		0	No
531	36.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 pondo pinesoff service drop		0	No
532	34.3	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak 1 pine mid span remove 4 pondo pine bushes 8ft in span		0	No
533	34.6	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak 1pine off service drop 3 pines mid span make safe 1 dead pondo pine in driveway of hone mid span		0	No
534	34.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 5 pondo pines in entire span remove 3ft pondo brush		0	No
535	35.2	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 cedar 1 pondo by pole South side 1 pondo North of pole mid span by entrance of driveway		0	No
536		8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 pondos mid span heading North towards next pole		0	No
537	35.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 1 dying pondo. Tree with 5921 address sign on it.		0	No
538	35.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 1 dying pondo SE of pole PTS 1 pondo on opposite side of rd Remove 5 pondo bushes mid span more towards 1 pine at end pole		0	No
539	35.6	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 oaks off service drop each side of pole		0	No
540	35.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 2 pondo brush along entire span 4ft PTS dying top of mid span pondo		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
541	35.8	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 1 pondo brush 2 ft by pole heading across street PTS 2 oaks heading to house [redacted] 1 oak off sevice drop to house beware dog PTS 2 pondo mid span heading SW		0	No
542	39.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pine 2 oak by pole		0	No
543	39.3	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pondo pine off service drop PTS 6 pondo pines 1 oak in front yard along fence line under wire		0	No
544	39.2	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 5 OAK mid span heading NE PTS 1 oak mid span remove 2ft pondo brush 4 ft oak brush		0	No
545	39.1	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 cedar off service drop		0	No
546	37.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 3 pondo pines mid span heading back towards kidder access to house off bedrock rd 4 pondo pine by pole 3 mid span heading towards next pole SE		0	No
547	37.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 3 pondo brush 1 oak brush under line 10ft total heading NE of pole towards 5600 house PTS at 5501 3 pondos SW of pole towards white Cobb house 3 pines off service drop to 5501 white Cobb house		0	No
548	34.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 oaks off service drop 2 pines off service drop		0	No
549	34.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 pine by garden		0	No
550	39.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 5 ft pondo brush under line NE of pole 15ft choke cherry brush remove 10ft choke cherry remove mid span 20ft choke cherry Brush near next pole 308401 PTS 1 poplar off browns lane and self serve eggs sign		0	No
551	39.9	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 choke cherry along white fence mid span		0	No
552	40.1	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pondo pine off service drop		0	No
553	39.8	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 silver maple off service drop remove 30 ft of choke cherry brush throughout entire span heading toward greenview remove dead top from tall pine on opposite side rd of wire		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
554	40.2	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 3 pine side first span Make safe 1 dying pondo pine mid span down dirt rd PTS 1 choke cherry SE of pole 1 side pine last span		0	No
555	40.3	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 locust 1 lilac off service drop to green house		0	No
556	40.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 poplar by pole		0	No
557	40.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 40 ft locust brush next to pole 2 groupings		0	No
558	40.6	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Letter				Etna	CA			Lift	PTS 1 choke cherry by pole 292501 PTS 1 red bud off service drop pole 292403		0	No
559	40.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 locust off service drop to house		0	No
560	55.8	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust by pole		0	No
561	61.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Li ft	PTS 6 poplar mid span 1 alder mid span		1	No
562	61.6	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Li ft	PTS 7 poplar 2 of which have dead tops along entire span		1	No
563	61.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Li ft	PTS 4 choke cherry off service drop rope dead out of poplar		1	No
564	61.8	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 choke cherry 1 poplar out towards creek 1 poplar with dead top prune half that is leaning towards wire		0	Yes
565	31.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pondo pine mid span heading toward yellow house		0	No
566	31.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Li ft	PTS 2 black Hawthorne 1 mid span one at pole 329801		0	No
567	31.3	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Li ft	PTS 2 black Hawthorne one on each side of pole		0	No
568	52.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 white poplar 1 oak mid span on uphill side. Head down oro fino rd where wire crosses street pts 1 overhanging pine move to pole B13526 pts 2 side pine 1 overhanging pine		0	No
569	53.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pondo behind barn heading NE mid span 1 oak mid span heading East make safe 2 dead pine trees on right side of quartz hill lookout 2 small trees mid span. Kinda hidden 1 overhanging pine		0	No
570	53.3	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 fir 3 oaks mid span make safe 6 dying pondo pines. Area will have more dead trees soon. Work NW of pole B158 and remove 200ft of brush throughout entire span pts 1 fir side		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
571	43.7	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 5 oak N of pole heading out of town pts 1 huge pine opposite side of rd defective codominate stem leaning toward wire make safe		0	No
572	43.6	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Starting at pole PTS 3 black Hawthorne south of pole. Then PTS 3 black throughout span heading North out of town		0	No
573	43.5	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pondo 1 oak next to pole heading into town south bound mid span 1 black Hawthorne 2 oak near next pole 308902		0	No
574	43.4	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 3 Pondo pines 1 next to pole 2 mid span heading put of town north		0	No
575	43.3	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 5 oak 2 pines mid span 2 black Hawthorne work entire span pole to pole heading south out of town		0	No
576	43.2	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 5 oak 2 pondo pines from pole to pole heading north out of town		0	No
577	43.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	at pole 290700 PTS remove 1 dead pondo pine and prune 1 oak at pole then PTS 3 oak 6 pondo pines throughout entire span heading out of town north		0	No
578	42.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 2 pine 1 oak at pole 4 oak 2 dead snags 1 at pole 1 mid span heading north		0	No
579	42.8	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 hazard tree at pole 1 pine side already cut needs more clearance		0	No
580	42.7	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 oak mid span heading towards town then work put of 5own to Remove 1000sq ft willow PTS 2 oak mid span		0	No
581	42.6	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 silver maple next to pole 1 maple off service drop west of pole 1 elm off service drop to the NE of pole at house 1500		0	No
582	42.5	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust East of pole towards town 1 pine side 1 oak in yard 1 juniper off service drop house with green roof		0	No
583	42.2	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 1 locust off service drop		0	No
584	41.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 elm 1 locust mid span 1 apple end of span heading down first street. 1 locust off service drop to turquoise house		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
585	40.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 Elm off service drop		0	No
586	40.8	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 locust off service drop		0	No
587	33.5	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 catalpa off service drop to trailer 1 dying elm off service drop to abandoned junk yard along with 2 locust off service drop in junkyard PTS 1 maple end of line cornor of main and kidder creek		0	No
588	33.2	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 juniper 1 pine 1 cedar under 1 spruce 1 mulberry off service drop to light blue house 3 spruce off service drop to green house		0	No
589	33.3	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 spruce 1 silver maple off service drop		0	No
590	33.4	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pine 3 juniper 1 elm off service drop		0	No
591	33.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 Arborvitae 3 pine 1 elm off service drop		0	No
592	31.2	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			lift_climb	PTS 1 locust off service drop		0	No
593	30.3	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Make safe 3 huge pines by pole 2 mid span remove 3 pondo brush by pole remove 7 pondo brush mid span 16ft brush		0	No
594	30.7	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 Pine by pole remove 5 pondo brush in corner PTS dead out of tree with 221 address sign on it.		0	No
595	30.6	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak off service drop		0	No
596	30.4	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 pondo off service drop in backyard 1 pondo off yellow stucco house		0	No
597	30.5	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 4 pondo SE of pole 4 pondo NW of pole		0	No
598	30.8	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 2 pondo brush		0	No
599	30.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Make safe 1 dying pondo by across from pole		0	No
600	31.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pondo off service drop remove 5 pondo pine brush N of pole heading away from house in span		0	No
601	31.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 2 poplars mid span in creek		0	No
602	32.6	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 elm off service drop PTS 3 pondo mid span heading away from home back to town		0	No
603	32.7	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Maple off service drop 1 red maple under line mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
604	32.8	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pondo pine reaching for the wire mid span		0	No
605	9.8	8/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	In field off Holzhauser rd and crystal creek PTS 2 black Hawthorne at pole		0	No
606	9.7	8/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 black Hawthorne remove 10ft black brush		0	No
607	9.6	8/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 4 black Hawthorne in entire span 10 ft black Hawthorne brush		0	No
608	9.5	8/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 4 black Hawthorne at corner pole		0	No
609	17.6	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA	5305980658		Lift	PTS 1 locust mid span heading S SW towards town 8n front yard of house [redacted] use caution while cutting tree. Call ahead		0	No
610	17.7	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 white birch mid span in front yard of house		0	No
611	17.9	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 elms in front yard		0	No
612	18.1	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust mid span heading into town at front drive		0	No
613	18.2	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust by old wood shed mid span		0	No
614	18.3	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 3 maples in front yard		0	No
615	18.4	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust mid span 1 locust 1 Cedar at pole 281210		0	No
616	28.7	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 2 dying pondos off by lifted house. Remove 22 pondo brush suckers		0	No
617	28.8	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 pondo pine off service drop		0	No
618	28.6	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 47 pondo brush/suckers along entire span pole to pole		0	No
619	28.5	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 100 pondo pine brush/suckers use brush mower on parts of span pole to pole		0	No
620	28.9	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 30 pondo pine brush		0	No
621	29.1	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 90 pondo brush suckers, brush mower		0	No
622	29.2	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 70 pondo pine brush suckers		0	No
623	29.3	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 19 pondo pine brush		0	No
624	29.4	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 24 pondo brush suckers		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
625	44.8	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak by pole 2 overhanging pines work to pole B280 pts 1 fir side 2 oak side mid span heading up hill 1 lower oak at top of hill by pine and overhang oak will need to climb this portion		0	No
626	44.6	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Remove 3 pondo pine brush by pole top of hill, work down hill mid span PTS 2 oak keep moving out towards open field PTS 2 oak next span before clearing		0	No
627	44.7	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Remve pine brush at pole B278 Make safe 1 dying pondo pine with non active bird nest in it 1 dead pondo behind that. Next head SW uphill span PTS 2 oak mid span heading up hill next make safe 1 dramatically leaning potential to hit if broken in windstorm		0	No
628	46.3	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pine 4 oak heading N down line toward open field. At field, PTS 2 huge overhaning pondo pine. Also Remove 5ft pondo pine brush suckers 15ft oak brush suckers		0	No
629	61.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 choke cherry mid span		0	No
630	46.8	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak at pole in field at canal 3 oak at fence and canal spot mid span of pole up to pole with guy wire B312		0	No
631	46.9	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 3 oak mid span heading west down line		0	No
632	47.2	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 3 Oak mid span 2 oak at next pole B314 remove 1 dead pine at pole B314		0	No
633	47.3	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Pts 1 overhanging pine 1 under growth pine Make safe 1 dying pondo pine mid span dead top PTS 1 oak mid span		0	No
634	47.1	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak at end pole behind house		0	No
635	46.7	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 6 oak by pole		0	No
636	46.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 3 Pondo pine 1 oak at pole 1 oak 1 pine at next pole by red shed		0	No
637	46.5	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 4 oak at pole heading down hill side		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
638	46.6	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Starting at the top of the hill by red barn work down the line away from house 2 pondo 1 fir mid span 2 poplar 1 alder right before you start going up drive 6 oak at next pole 10764. 3 on each side and 1 pondo 1 pine mid span in dry creek		0	No
639	60.9	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak at pole 3 oaks North of pole following rd out of town on sevice drop 1 oak across street off service drop in yard of blue Victorian home 1 oak off service drop by red house off yard with blue home 10604 10602		0	No
640	70.1	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 cedar off pole 1 side oak 1 overhanging cedar at next pole 63B8 1 oak across street at next service drop pole 1 pine at 10703		0	No
641	49.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS to the left of pole all tress already pruned in mid span. Need more clearance 4 cedars 5 oaks 1 oak at pole 1 juniper 2 oaks mid span		0	No
642	49.3	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak off service drop pole 3 oak side		0	No
643	49.2	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	3 overhanging oaks		0	No
644	47.5	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 deadora cedar off service drop 1 pine mid span under wire as your driving up to pole 1 pine 4 oaks work up to pole B315 Pts 6 oaks throught span to top of hill remove oak brush at pole		0	No
645	47.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 3 dying pondo pine remove dead out of top of 1 oak pts 2 overhanging pine at pole 1 oak 1 pine side PTS 1 oak 1 overhanging pine 1 overhanging oak l side pine as you work past dumpster down line 3 oak side rest of open span		0	No
646	47.6	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Make safe 2 dying pondo pines mid span behind house climb		0	No
647	47.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 6 dying pondo pine by pole 3 overhanging pine 1 oak mid span heading down hill 1 pine side mid span		0	No
648	47.8	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 outreaching oak 3 oak on downhill side		0	No
649	48.1	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 Oak off of service drop 1 oak at pole 1 oak mid span heading into field		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
650	48.2	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 willow mid span		0	No
651	48.3	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pine side 2 oak mid span heading back towards house from pole		0	No
652	48.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Take top off 1 dead cottonwood mid span		0	No
653	48.5	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 black Hawthorne before bridge 1 willow 2 alder mid span 1 overhanging cotton wood mid span 1 alder 1 choke cherry at end of bridge		0	No
654	48.6	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 poplar/elm in front yard		0	No
655	48.8	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				E	CA			Lift	PTS 1 cedar by pole		0	No
656	48.7	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 3 Hawthornes in 2 spans of pole. Work to end pole		0	No
657	48.9	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 3 poplars across from pole make safe 1 dying pondo pine mid span PTS 1 oak mid span 2 pines 1 overhanging oak at pole B7150		0	No
658	51.9	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 fruiting trees on near pole B2840 1 at next pole heading North		0	No
659	52.1	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 willow at start of riverside 2 alder mid span 1 pondo pine near other side of river		0	No
660	67.5	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak brush 5ft mid span heading E away from rd down to corner pole 1 overhanging pine		0	No
661	67.6	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 pondo pine Remove 12 pondo pine brush 1 Doug fir brush mid span heading South down valley pines. Remove 1 oak brush near the end of span and next pole 068100		0	No
662	66.5	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pondo pine at drive or[redacted] underline		0	No
663	66.2	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA	530598030		lift_climb	Make safe do not do complete removal 1 large dead Jeffery pine Call ahead and clean up from last Job		0	No
664	66.3	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Make safe 1 dead pondo mid span end pole by house, beware dogs		0	No
665	66.4	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Work entire span south down valley pines Remove 1 oak brush 2ft PTS 1 pine 1 oak mid span PTS 5 pines more towards next pole 066103		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
666	22.7	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 cedar by pole off service drop make safe 1 dying pondo pine off service drop on other side of rd then PTS 1 maple 1 cedar off drop after pondo close to other pole then PTS 1 pondo 1 maple off other service drop from pole 322002 then move down sawyer		0	No
667	22.8	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 pondo pines		0	No
668	22.9	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 poplar by pole 2 poplar make safe off service drop 1 oak 1 cedar off service drop 2 oaks 1 pine mid span		0	No
669	22.4	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 red bud tree at pole 2 locust in front yard		0	No
670	22.5	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 oak off service drop 1 apple up church street		0	No
671	23.1	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 cherry 1 apple mid span		0	No
672	23.3	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 white birch 2 locust at pole		0	No
673	23.2	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 spruce off service drop		0	No
674	23.4	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 locust off service drop		0	No
675	23.5	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 locust up drive reaching toward line		0	No
676	23.6	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pondo pine off service drop		0	No
677	23.7	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 locust by dirt pile		0	No
678	23.8	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 1 dead pine at [redacted] PTS 4 oak by house 3 under wire 1 overhanging 1 oak by pole 2 cedar off service drop to White House [redacted] 1 elm mid span at White House 1721		0	No
679	23.9	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Pts 1 overhanging pine with slow down new baby fawns PTS 1 oak at driveway mid span		0	No
680	24.1	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak at pole		0	No
681	24.2	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 box elder on right side of driveway as you enter		0	No
682	24.4	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 locust 1 spruce 1 red maple		0	No
683	24.3	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Flagging	PTS 70ft pondo pine brush on downhill side 1 pondo pine off service drop by oak with service drop attached to trunk, oak side on downhill side.		0	No
684	24.5	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak off service drop deflection of wire mid span on uphill side		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
685	24.6	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pear off pole service drop to White House		0	No
686	24.7	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 elm by pole in field		0	No
687	24.8	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 cedar mid span at cemetery 1 overhanging pine at pole 328803		0	No
688	25.2	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak iff service drop		0	No
689	12.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span 6 oak 1 apple 1 oak after pole 14 37 heading NE down highway away from town		0	No
690	16.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cedar off service drop 2 walnut in front yard 1 locust mid span 2 locust at next pole 284108		0	No
691	16.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 poplar at end pole		0	No
692	16.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust by pole 1 box elder mid span 1 locust mid span		0	No
693	16.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 catalpa mid span work to pole 284001 1 cedar 1 apple 1 sycamore off service drops		0	No
694	16.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 sycamore in front yard 1 maple mid span 2 walnut after that towards next pole		0	No
695	16.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust in yard 1 cedar off service drop		0	No
696	17.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 silver maple in yard reaching toward line head south down line towards etna PTS entire span 3 choke cherry 1 apple 1 Arborvitae 1 juniper 1 willow 2 cedar 1 choke cherry next to next pole 283104		0	No
697	17.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 willow in front yard off service drop 1 willow mid span heading toward town		0	No
698	17.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 plum cherry at pole		0	No
699	17.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 choke cherry off service drop		0	No
700	17.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 locust in front yard		0	No
701	18.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 vine on pole guy wire		0	No
702		8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Aspen in front yard		0	No
703	18.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 poplar off service drop		0	No
704	18.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 Box elder off service drop		0	No
705	19.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 silver maple off service drop		0	No
706	19.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 box elder by pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
707	19.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cedar off service drop		0	No
708	19.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 maple off service drop to brick building		0	No
709	19.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak by pole 1 cedar front yard		0	No
710	19.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 choke cherry/hawthorn by pole 1 pine off service drop 1 spruce in front yard 369		0	No
711	19.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 poplar at pole		1	No
712	19.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 silver maple in front yard 1 box elder yard of [redacted] mid span		0	No
713	19.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	PTS 1 silver maple at pole 1 sycamore I'm front yard of [redacted] reaching toward wire		0	No
714	20.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 elm mid span west by white fence 1 maple mid span heading down gravel alley 1 plum cherry at end pole		0	No
715	20.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak off service drop		0	No
716	20.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 locust in front yard of [redacted] off marked pole service drop then off 299105 service drop		0	No
717	20.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak mid span front yard 1 choke cherry front yard in span with oak move right of span towards Howell PTS 1 catalpa 1 boxer elder		0	No
718	20.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 cherry off service drop next to keep out red barn		0	No
719	20.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 Cherry 1 blue spruce west of pole 1 box elder across street off service drop 1 cedar mid span heading east of pole off service drop		0	No
720	20.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak at pole		0	No
721	20.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 oak at pole 1 poplar working SE toward pole 298306 at that pole remove 20 ft white poplar brush 10 ft black Hawthorne brush 1 cherry off service drop across the street by metal roof shed		0	No
722	20.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire span on side if house 3 oak 1 walnut by pole 1 oak mid span 2 oak end of span 2 European white birch 1 cherry at next pole 298205 house [redacted]		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
723	21.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 maple under et line 1 white birch in yard 1 sycamore by pole		0	No
724	21.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 1 dying pondo pine along opposite side of driveway in yard PTS 1 oak across rd by pole 296204		0	No
725	21.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 for 1 pine 1 oak near pole 2 oak mid span 1 pine 2 oak at next pole 296301 PTS 1 fir 1 oak off service drop lots of contact deflecting wire aggressively end at pole 296300		0	No
726	21.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS entire 2 spans 1 sycamore at address mid span 1 oak across street from sycamore 1 juniper at next pole 2 sycamore off service drop of that pole at house [redacted] next span 1 maple 1 plum Cherry 1 oak in yard of 641 1 cherry off service drop 641		0	No
727	21.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 cherry by pole 1 elm across street off service drop		0	No
728	21.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 cherry's mid span heading into tow from pole front yard		0	No
729	21.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 box elder off service drop pole 297104 PTS 1 sycamore mid span in front yard of 412 PTS 1 cherry in yard of [redacted]		0	No
730	21.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 silver maples side of house 2 pine 1 catalpa 1 liquid amber in front yard 1 choke cherry off service drop to house		0	No
731	22.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 birch 1 locust in yard with white fence and house		0	No
732	21.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 white birch by pole		0	No
733	22.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 elm side of house mid span		0	No
734	22.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 cherry 1 apple at pole go up gravel drive PTS 1 sycamore 2 lilac 1 ash 1 sycamore 1 oak until next pole 296104		0	No
735	22.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100ft pine brush for entire span		0	No
736	22.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pine off service drop behind house by shed.		0	No
737	22.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 willow off service drop 1 box elder and 1 walnut over by barn garage mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
738	25.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak off service stand under wire 1 locust mid span by red barn		0	No
739	25.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 plum cherry at pole 1 Hawthorne 1 silver maple in yard 1 box elder 1 maple at corner pole 330905 work entire span from corner to end pole 2 alder 1 birch 4 choke cherry 3 willow 2 pone off service drop 1 oak off other service drop remove 50ft willow		1	No
740	24.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA	5304673264		Lift	PTS 7 silver maples off service drop. Oak behind end pole PTS		0	No
741	22.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 locust at pole 1 locust at next pole with speed sign on it off service drop 1 walnut in front of house [redacted] 1 maple in front of house [redacted] 1 catalpa at house [redacted]		0	No
742	25.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pine off service drop to restaurant 1 oak mid span heading towards North highway		0	No
743	25.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 choke cherry by pole		0	No
744	25.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 oak at pole 1 apple 1 oak mid span heading SE PTS 1 oak NW of pole remove 100 ft pondo pine brush with mower to next pole NW of pole away from house		0	No
745	25.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 OAK remove 50 ft pondo pine brush work west down highway		0	No
746	29.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 pine 1 oak off service drop at end pole		0	No
747	29.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 Oak mid span heading west down highway towards greenview		0	No
748	44.6	8/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS			
749		9/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Seiad	CA			lift_climb	Make safe 1 dead cedar at top of hill next to pole		0	No
750	50.7	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 4 locust 4 black Hawthorne remove 200ft black Hawthorne brush mid span right along highway move down to next pole 12 32 PTS 3 locust at pole 1 locust overhang locust mid span remove 300sq ft black Hawthorne		0	No
751	50.8	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS group of 30 locusts in crystal creek mid span 100ft of pine and hawthorn brush at pole		1	Yes
752	50.9	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 1 dead locust in yard		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
753	51.1	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft choke cherry by pole head south for rest of work through entire span remove 600 sq ft brush mix of pine and oak PTS 1 overhanging oak 1 pine side mid span 1 pine side at pole		0	Yes
754	51.2	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 1 dying pine pts 2 oak sides East of pole 17 33 PTS 1 OAK remove 1200 sq ft brush in entire span from pole 17 33 to pole 16 33 pts 1 oak side		0	Yes
755	51.3	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 500 sq ft of pine brush PTS 2 overhanging pondo pines at driveway		0	Yes
756	51.4	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 overhanging pine at pole 14 33 1 oak mid span heading south down highway		0	No
757	51.6	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 oak 3 pine remove 500 sq ft brush 100 sq ft pine brush after pole 12 33		0	No
758	51.7	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Flagging	PTS 1 oak mid span north ala right side of highway move south work entire span remove 800 sq ft brush PTS 2 pine 1 overhanging pine 2 pine sides by mailboxes		0	No
759	51.8	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft brush		0	No
760	51.9	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 200 sq ft pine south of pole make safe 1 dying pondo pine off highway backseat from line pts 1 pine side at address 4316 move NW down the line pts 1 overhanging pine at pole 055402		0	No
761	52.1	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft pine brush around pole and driveway 1 side pine 1 oak under line down the drive 1 overhanging pine heading toward end pole. 150sq ft brush near next pole along highway 4 33 1 overhanging pine at forest walk rd		0	No
762	52.2	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 oak remove 200 sq ft of pine in fence through entire span until pole 3 33 PTS 1 pine at pole.		0	No
763	52.3	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 pine remove 1 overhanging pine 200 sq ft brush in fence line to pole 2 33 keep working next span 300 more square feet in entire fence to next pole 1 33 1 pine side at hoot owl ln		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
764	52.4	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 pine mid span remove all brush in entire span 800 sq ft move back to pole 233 mid span make safe 1 twisted dying pine between hoot owl ln and forest lane 1 overhanging pine at pole 1 33 move NW down rd 2 overhanging pines mid span		0	No
765	52.5	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 1500 sq ft brush through entire span make safe 1 dying pine mid span pts leaning portion of pine of codom stem of knobcone pine pole 19 32 to pole 18 32 make safe 1 leaning oak 1 overhanging pine at pole 17 32 NW down highway at culvert also 1 knob		0	No
766	52.6	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 oak mid span remove brush entire span pole to pole 1000 sq ft pine brush		0	No
767	52.7	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 black Hawthorne remove 100 ft black Hawthorne brush		0	No
768	53.4	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 Oak 1 choke cherry SE of pole PTS 1 overhanging pondo mid span 2 Doug firs 1 pondo by pole 1 oak mid span remove 300ft brush		0	No
769	53.5	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 3 oak by pole 1 apple 1 cedar 1 oak mid span 1 overhanging pondo next pole beware dog it charged and I deployed spray. Very anger customer		0	No
770	68.2	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 overhanging pine by pole 1 pine mid span remove 300 ft brush throughout span 2 pondo pine neat pole 057201at that pole PTS 2 oak 1 oak mid span remove 100ft pine brush PTS 1 pine 1 cedar close to next house moving towards house		0	Yes
771	68.6	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 Pines mid span 1 overhanging pine near next pole heading NW 2 oak 2 pines at next pole 058201 remove 200ft brush through span 100 ft at pole 058201		0	No
772	68.7	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pole to pole heading NW down eller PTS 4 oaks 3 pondo pines remove 800 sq ft pine and oak, choke cherry brush throughout entire span		0	Yes

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
773	68.8	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 oak 4 pines on left side of pole 058200 1 oak by pole 1 overhanging oak mid span remove 1100 brush under wire in fence through entire span.		0	Yes
774	68.9	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 overhanging locust 1 oak across street make safe 1 dead pondo pine behind pole remove 700 sq ft brush		0	Yes
775	69.1	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 Overhanging locust heading out into field access [redacted]		0	No
776	69.2	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 200 sq ft oak Hawthorne brush 1 pine end of span 2 overhanging pines		0	No
777	70.8	9/11/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Pts 2 pine tree and remove 300 feet of pine brush and 200 feet of fir brush at pole b7968. Move off tap to rd pts 1 fir side 1 pine side		0	No
778	51.4	9/11/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41		Personal				Weed	CA			Lift	Pts 4 pines and 1 oak at pole b2835 and east of pole.		0	No
779	51.3	9/11/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 1 side trim pine. Pts 1 pine top. Pts 2 oak side. Pts 6 oak top. Remove 500 feet of pine brush at and east of pole b5005 through out span.		0	No
780	51.7	9/11/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove 200 feet of oak brush. Pts 4 oak side trims north of pole b2838.		0	No
781	70.5	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 overhanging pine2 PINE by pole remove 400ft pine brush entire span to pole B78968		0	Yes
782	70.7	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pine mid span 300ft brush heading towards rd		0	Yes
783	70.9	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 overhanging pine in 2 spans 2 poplar middle of trench under pine mid span remove 200ft brush		1	Yes
784	51.1	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	OR			lift_climb	PTS SE of pole 2 overhanging pine make shade 1 dying pine by overhanging pine, remove 400ft brush work NW down line away from pond 1 pine overhanging 2 oak on dirt drive rd 200ft pine brush 1000 ft pine brush till next span 1 oak close to next pole remove		0	No
785	51.2	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 4 pines heading North down line PTS 1 fruiting tree northin fence at next dirt rd		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
786	51.5	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Pts 1 overhanging pine at drive Make safe 2 dying pines uphill side by pole PTS 1 overhanging pine mid span remove 300 ft oak brush by next pole uphill heading north		0	No
787	51.6	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 oak remove 200ft oak downhill side by unmarked pole remove 800 ft oak uphill side to pole B2838		0	Yes
788	51.8	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak at pole 1 oak mud span on right heading towards field PTS 1 oak on left heading towards rd South west remove 500ft brush oak under line		0	No
789	50.9	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 OAK 1 pine at pole		0	No
790	50.8	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Herbicide	PTS 2 overhanging oak at pole 1 off service drop 1 oak mid span		0	No
791	50.7	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Make safe 1 dead pine pts 1 over hanging fir at fence 1 side fir at pole 1 cedar 1 pine mid span heading towards end house		0	No
792	60.1	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 oak 1 cedar across house		0	No
793	65.8	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			lift_climb	PTS 1 oak off service drop remove 100ft choke cherry mid span before gate remove 100ft pine/oak brush mid span after gate remove 100ft choke cherry by pondo pine stump		0	No
794	64.5	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pine remove 100ft pine PTS 1 Doug fir at driveway 1 blue spruce off service drop at driveway.		0	No
795	64.4	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 pine and 1 oak mid span South of pole remove 100ft mid span now work North of pole remove 400 ft entire span. 1 pine at pole 069702		0	No
796	64.3	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 200 ft of pine brush under line in fence mid span PTS deadpimbs out of overhanging pine mid span		0	No
797	64.2	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak at pole		0	No
798	63.8	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 100ft pine brush near next pole		0	No
799	63.5	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	PTS 1 pine of service drop from transformer move north down rd remove 200 ft brush at next pole juniper and pine		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
800	63.2	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pine at blue address marker mid span 1 pine off pole 066604 service drop		0	No
801	62.8	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS big pondo pine side across rd mid span			
802	62.6	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak at pole 1 overhanging oak mid spa heading towards house 1 oak further West by metal bar. 4 oaks total for both spans off pole.		0	No
803	62.7	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 100ft Arborvitae brush mid span		0	No
804	63.3	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 oak 1 pine in front of house mid span 1 Arborvitae by transformer remove 100ft pine brush mid span NW 1 oak prune 1 fir off service drop pole 067600 to house [redacted]		0	No
805		9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove all brush in entire span to end pole 068506 500ft PTS 1 pine at end pole. Pine side midspan. Oak crown reduction midspan.		0	No
806	63.9	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 2 pine at pole PTS dead out of 1 Jeffery pine mid span PTS 1 pine at stop sign crossing		0	No
807	3.2	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 7 black Hawthorne in span 101102 mid span heading down dirt rd		1	No
808	9.9	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 9 black Hawthorne in canal mid span		1	No
809	71.7	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 6 black Hawthorne mid span		0	No
810	65.7	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	Remove 100sq ft oak brush in fence 200sq ft oak brush mid span and at end pole		0	No
811	65.6	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove 100 ft oak brush at pole remove 100ft pine brush mid span to end of fence		0	Yes
812	65.5	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	1 pine mid span remove 400ft pine brush to pole 052901 PTS 1 pine under transformer		0	No
813	65.4	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pine		0	No
814	65.3	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 300ft pine brush around pole PTS 1 pine overhanging remove 100ft brush mid span 200ft end of span		0	No
815	64.9	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pine at pole remove 1 pine 1 fir 100ft pine in next span.		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
816	64.8	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pine towards house 100st feet pine remove 100sq ft pine at end pole		0	No
817	64.7	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 100sq ft pine on right side of drive remove 300 sq ft left side of drive. 100sq feet at next pole and speed limit 30 sign		0	No
818	64.6	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	Remove 100sq ft pine by pole 100sq ft across rd PTS 1 pine across rd 1 fruiting tree 2 pine at next pole 069904 NW down woods drive		0	No
819	61.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				ETNA	CA			Lift	Remove 200ft locust brush mid span PTS 1 locust midd span		0	Yes
820	61.2	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 1000ft locust brush throught span 100ft locust brush at next pole 318701 PTS 1 pine 7 locust		0	Yes
821	61.1	9/16/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pine mid span heading across the rd in fence PTS 2 pine at next pole. End pole		0	No
822	59.9	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 100 sq ft choke cherry brush 35 ft from pole remove 100ft pine brush mid span remove 150ft pine brush end of span near pole 316703 at this pole PTS 1 pine please work entire span.		0	Yes
823	59.8	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 100 square feet pine brush mid span work rest of an for removal of brush 300 square ft until next pole 316702		0	Yes
824	59.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1oak at pole remove 500 sq ft pine/oak brush along roadside underwire cross street to next pole Pts 1 oak Remove 300 sq ft pine brush under oak at pole 315701		0	Yes
825	59.6	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 100 sq ft brush at pole PTS 1 overhanging pine mid span		0	Yes
826	59.5	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 alder 1 apple at pole woek up hill across rd PTS 2 pine 2 oak remove 100 sq ft oak brush until next pole at top of hill		0	No
827	59.1	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pine at pole 1 oak 1 pine 1 fir before gully remove 300 sq ft pine brush mid span of pole 313500		0	No
828	59.2	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS remove 200 sq ft brush near pole 313602 PTS 4 oak 1 pine 1cedar throughout span to next corner pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
829	59.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak mid span south PTS 1 pine mid span north of pole 2 spans 1 each way off marked pole		0	No
830	58.9	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 oak by pole before gully behind house will have to climb		0	No
831	58.8	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak at pole 1 Doug fir 3 oaks moving down the span remove 100 sq ft cedar brush remove 100 sq ft oak brush mid span		0	No
832	58.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS leaning portion of poplar/cottonwood away from line Remove 300ft choke cherry brush 300 ft more cherry/pine brush mid span remove 800 sq ft cedar/pine brush the rest of the span work entire span removing all brush at and under 6ft DBH PTS 6 poplar 2 c		1	Yes
833	58.6	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	remove 100 square feet pine oak brush throughout entire span PTS 1 pondo next pole		0	Yes
834	58.5	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 poplar 1 Choke cherry mid span remove 100 soft choke cherry at poplar Remove 100ft brush mid span 100 sq ft oak end of span pole 367400		1	Yes
835	58.2	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 1000 sq ft brush PTS 1 poplar close go pole 2 poplars mid span 1 pine near end of span		0	Yes
836	57.9	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 pines throughout span PTS 2 poplar, 1 at end has dead branches overhanging remove 200 sq ft choke cherry brush mid span remove 400 sq ft choke cherry brush oak at end of span		0	Yes
837	57.8	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 outreaching oak with dead branches overhanging remove 100 sq ft pine brush mid span remove 100 sq ft choke cherry near end of span pole 365305		1	No
838	57.5	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 poplars remove 600 Sq ft choke cherry brush PTS 1 willow at pole B1149		1	Yes
839	57.6	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 3 poplars by pole 1 alder in creek 1 cherry in creek remove 100 Sq ft maple brush in creek remove 100 sq ft Doug fir 366300		1	Yes
840	57.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak at pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
841	57.4	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 outreaching poplar remove 300 square feet pine brush underline by pole in blackberries remove 100 sq ft cedar brush mid span remove 100 sq ft cedar brush at next pole 365301 PTS 1 overhanging pine at pole 365300		0	Yes
842	57.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 large cottonwood mid span behind kidder creek welcome sign Remove 300 sq ft pine and cedar brush at pole PTS 2 cedar mid span remove 200 sq cedar brush in fence line remove 300 sq ft choke cherry tree mid span under line remove 200 sq ft alder/ cher		1	No
843	56.9	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 200 ft cedar brush under line throught span		0	No
844	56.8	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 OAks before pole 363200		0	No
845	56.4	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 box elder behind pole with transformer 1 maple at marked pole 361101		0	No
846	56.5	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1000 sq ft willow 100 sq ft choke cherry make safe 1 dead poplar make safe 1 dead trunk poplar PTS 1 poplar at pole 362102		1	No
847	56.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 4 OAKS heading out to clearing		0	No
848	56.6	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 400 ft cedar pine brush under line		0	Yes
849	57.1	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100sq ft brush by pole under line		0	No
850	56.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 100 sq ft brush to the east of pole 300 ft brush to the west throught entire span to next pole 364202		0	No
851	57.2	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS dead out of 1 overhanging poplar PTS 1 Alder in creek remove 100 sq ft cedar brush		0	No
852	58.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove 200 sq ft pine work south towards rd PTS 1 poplar mid span		0	Yes
853	58.4	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Make safe 1 dead pondo pine mid span		0	No
854	58.1	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Work NW from pole PTS 2 overhanging pine as you cross rd remove 100 sq ft brush in fence PTS 4 pines		0	Yes
855	59.4	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Make safe 1 dead cottonwood behind end pole		0	No
856	71.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 box elder by pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
857	60.5	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 2 black Hawthorne make safe 1 dead top poplar		1	No
858	60.6	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 black Hawthorne 1 poplar willow mid span		1	No
859	60.7	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 poplar mid span 2 dead overhanging poplar near next pole make safe		1	No
860	60.8	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS dead out of 2 poplar near next corner pole PTS 1 black Hawthorne under line by poplars PTS 1 poplar 2 choke cherry at next poleB11376		1	No
861	60.2	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft oak brush before PTS 1 alder 1 Doug fir remove 100 sq ft pondo brush mid span		0	No
862	60.3	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Make safe 1 dead top poplar mid span opposite side of rd		0	No
863	60.4	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Remove 100 sq ft choke cherry under line		1	No
864	70.2	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft pine brush mid span south of pole 100 sqft pine at pole 200 sq ft pine and oak brush mid span north of pole, PTS 1 overhanging pine keep working north to next pole B2830 remove 100 sq ft oak brush		0	No
865	70.3	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 overhanging pine mid span remove 200 sq ft oak brush mid span head north remove 100 sq ft alder brush		0	No
866	70.4	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove brush entire span pole to pole 1000 sq ft pine brush heading north		0	No
867	52.2	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 outreaching oak at pole behind green gate with signs		0	No
868	52.3	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft pine brush near pole move mid span to the right pts 1 overhanging pine 1 side pine move to pole across the rd and remove 100 sq ft pine brush at pole keep moving down dangel away from town pts 1 overhanging pine across rd at green gate		0	No
869	52.4	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 300 sq ft willow poplar brush mid span PTS 1 poplar 1 Hawthorne/ ALDER mid span 1 Hawthorne at end pole remove 300 sq ft willow poplar brush near end pole		1	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
870	52.5	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 POPLAR mid span work along entire creek 2 spans pts 3 poplar sides 1 oak side 1 alder side 1 pine side 1 oak side before next pole remove 600 sq ft willow brush in beginning of second span work to pole B10205 at that pole PTS 1 overhanging pine		1	No
871	52.7	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Pts 1 pine at pole Remove 100 sq ft oak brush at pole remove dead out of 1 overhanging Doug fir prune bottom mid span at pole B14056 remove 600 sq ft brush oak willow pine pts 1 oak side PTS 1 overhanging pine at end pole with transformer		1	No
872	52.6	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 locust next to line 1 oak near pole		0	No
873	70.6	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Make safe 1 dead pondo pine mid span after cattle guard off to the left. Work your way down the line 2 spans ending at pole B10549 pts 2 pine side 6 overhanging pines		0	No
874	55.7	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft oak brush at pole pts 1 pine side 2 juniper sides		0	No
875	52.8	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 maple off service drop behind house Remive 100 Sq ft Russian olive next to pole PTS 1 box elder reaching up towards liberty right hand side if looking down the line		0	No
876	53.8	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft pondo cedar brush heading SW of pole towards end pole PTS 1 overhanging pondo pine mid span Remove 100 sq ft pine brush East of pole about 80ft 3 overhanging pine opposite direction into mid span		0	No
877	53.9	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 pine at pole PTS dead out of 1 overhanging pondo pine 1 over hanging pine mid span heading East of pole. Keep moving down line away from house pts 1 cedar side at pole 1 for side further down line		0	No
878	54.1	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft oak brush at pole 100 sq ft brush mid span heading west up line 1 overhanging pine1 fir side at next pole		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
879	53.7	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft pine/choke cherry brush at pole 100 ft pine brush mid span		0	No
880	53.2	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft locust brush 40 ft North of pole remove 100 sq ft pine brush near end pole under wire across street pts 1 side pine there		0	No
881	54.5	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Use gate code 2680 Remove 100 sq ft pine brush around pole move down line towards house pts 2 pine side 1 poplar side		0	No
882	54.6	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 oaks at pole make safe 1 dead pine mid span pts 2 overhanging pine heading South PTS 1 lean poplar near next pole 1 overhanging pine 1 pine at pole		0	No
883	54.7	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 pine on off shoot away from house 1 poplar under line 1 fruiting tree by poplar work East and remove 400 sq ft willow brush heading into mid span PTS 1 pine by horse trailer under line		0	No
884	54.8	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 oak remove 100 sq ft oak brush mid span 1 pine side stole on crest		0	No
885	54.9	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft oak brush mid span pts 3 oaks work to pole B177 pts 2 oak side 1 oak under		0	No
886	54.3	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove all brush pole to pole 4 spans until you hit quartz hill lookout rd 4000 sq ft pine brush		0	No
887	55.2	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove entire span of brush to the east of pole 200ft remove entire span of brush heading North of pole 400 to pole B1672 pts 3 overhanging pines 3 pine sides at pole B1672		0	No
888	55.3	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft pine brush at pole pts 3 overhanging pines 3 pine sides throughout 2 spans		0	No
889	55.4	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 Jeffery pine at pole 1 off service drop 4 oaks at next pole end pole		0	No
890	55.9	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 mulberry on back of property 1 Arborvitae mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
891	65.2	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 locust 1 poplar mid span 1 Arborvitae at next pole Remove 100sq ft locust brush beginning of span. Remove 100 sq ft pine brush at end of span next pole 321001		0	No
892	65.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 Overhanging poplar 1 oak 1 aspen mid span at creek remove 100 sq ft pine brush at pole and 100 sq ft pone brush at creek remove 100 sq ft pine/oak/ cherry brush after creek		1	No
893	62.4	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS dead out of overhanging pondo remove 400 sq ft pine brush all the ways gate until in the clear. Make safe 2 dead pine mid span across driveway right side mid span Remove 100 sq ft pine brush near next pole 321100 and [redacted] PTS 1 oak		0	No
894	62.3	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove all brush entire span pole to pole anything 6DBH and lower 600 sq ft		0	No
895	62.2	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Remove all brush entire span pole to pole 1700 sq ft PTS 1 pine off service drop to house 5304		0	No
896	64.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA	5053856288		Backyard_Lift	PTS overhanging pondo 1 at end pole 1 overhanging pondo by 1 oak mid span remove 100 sq ft pine brush before fence to next property. Call candace before tree work, man has dementia and will be angry and confused. Call ahead to set appointment.		0	No
897	63.7	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Telephone				Etna	CA			Lift	Remove 300 sq ft brush entire span		0	No
898	63.6	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 200 sq ft pine brush underline near pole		0	No
899	62.9	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 4 oak under line 2 pine by marked pole		0	No
900	63.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak at pole 1 oak mid span both across fence at pole remove 100 sq ft oak brush at pole along fence line		0	No
901	62.5	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft brush at green gate code 1964 PTS 3 pine at pole and 2 pine sides after pole, remove 100 Sq ft brush at pole, move down span to end pole remove 1200 sq ft pine brush PTS 1 pine mid span 1 oak at end pole 063700.		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
902	74.9	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 overhanging pine and make safe 1 dead top lodge pole behind oak pine remove 1200 sq ft pine brush in fence line mid span make safe 2 dead trees 1 lodge pole, 4 oak sides.		0	Yes
903	75.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 pine off service drop remove outreaching pine 100 ft from pole PTS 1 overhanging pine at that point PTS 1 more overhanging pine by oak PTS 1 oak tree remove 100 square ft pine brush mid span along canal		0	No
904	66.6	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Make safe 1 dead pine PTS 1 oak at pole. Prune pine side.		0	No
905	68.3	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS dead out of 1 oak PTS 1 oak mud span make safe 1 dead pine by shed under line PTS 2 oak remove all brush entire span pole to pole mix of oak and pine 1000 sq ft PTS 1 oak at next pole 057102		0	No
906	68.4	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 oak mid span work to pole 057104 PTS 2 overhanging trees oh ak and pine		0	No
907	68.5	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 2 oak under line remove 700 sq ft brush mid span up to next pole on eller lane rd		0	No
908	68.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Backyard_Li ft	PTS 1 locust by green metal shed 1 oak there as well head remove 100 sq ft brush at pole 1 oak at pole 057301 work down service drop as well PTS 1 silver maple in front yard of [redacted]		0	No
909	71.8	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 apple at pole		0	No
910	71.9	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak mid span under line heading east towards house		0	No
911	72.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 600 sq ft locust brush mid span 2 bushels		0	No
912	72.2	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 black Hawthorne mid span to end pole		0	No
913	72.3	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 2 spans worth of pine brush starting N at pole with white transformer move south and cross over Danville rd 40p sq ft of brush		0	No
914	72.4	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak by pole 1 pine mid span west. Make safe 1 dead cedar up hill by brome down silver car		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
915	72.6	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft pine brush in fence line PTS dead out of 1 pine mid span heading North		0	No
916	72.5	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 300 sq ft pine, fir, cedar brush in span		0	No
917	72.7	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 1 overhanging fir mid span heading toward house make safe 1 dying maple in creek remove all brush in span 1500 sq ft PTS 2 oak at next pole in front yard		0	No
918	72.8	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Backyard_Lift	PTS 2 pine mid span under wire heading NE down line		0	No
919	25.6	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 oak on street and driveway		0	No
920	73.4	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove entire span of cheery brush to the west towards the rd 1000 ft in fence and 1000 ft to the East in the fence. All are choke cherry		1	No
921	74.8	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 600 sq ft oak brush on uphillside PTS 2 oak on uphillside		0	No
922	74.7	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft pine brush around pole at top of hill move west a span and remove 300 sq ft pine brush PTS 2 pine one mid span one near next pole 326602		0	Yes
923	74.6	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 200 sq ft pine and oak brush work to pole on other side if paved drive with transformer		0	No
924	74.5	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 oak mid span in island area in front yard middle of circle drive		0	No
925	74.2	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft pine and cedar brush mid span at circular saw sign move East remove 100 sq ft locust at base of next pole 328200		1	Yes
926	73.9	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 overhanging trees to the west 1 poplar 1 choke cheery move east into creek remove all brush in entire span staring at pole cedar Chile cherry willow and pine 700 sq ft first part until rd then another 600 ft in creek. Cross creek work over next open		1	No
927	74.1	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak after shed mid span		0	No
928	73.6	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 oak mid span along driveway		0	No
929	73.5	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 1 overhanging oak mid span 2 oak mid span		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
930	73.8	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS entire span to end pole 6 oak 1 pine end pole 1 oak on the way out mid span at pink metal barn		0	No
931	73.7	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA	5304673133		lift_climb	PTS 1 elm at pole 1 elm off service drop 1 oak out by blue shed. Call ahead very concerned about prunning. You can back into drive, or leave chipper to turn around. Call ahead. Refused prunning on oak closets to pole.		0	No
932	74.3	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS 2 OAK by pole remove 100 sq ft brush around pole		0	No
933	74.4	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	PTS oaks mid span heading out towards sawyers bar.		0	No
934	53.6	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Work East from pole PTS 1 oak Remove 100 sq ft pine brush mid span remove 100 sq ft around pole		0	No
935	54.2	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 100 sq ft pine brush mid span		0	No
936	54.4	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 oak mid span 1 pine near next pole		0	No
937	66.7	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA	5303401035		Climb	Remove 200 sq ft pine brush NE of pole move West of pole and work entire span pole 053100 to pole remove 300 sq ft at pole then remove 200 ft of pine brush in fence then 600 sq ft at next pole 052101 do both sides including space to pole 052100 access fr		0	Yes
938	66.8	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Work entire span pole to pole Remove 100 sq ft pine brush beginning span mid span remove 100 sq ft oak/pine brush PTS 1 fir mid span then remove 1800 sq ft pine brush until you reach pole 051102		0	Yes
939	66.9	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA	5034675840		Climb	Remove 100 sq ft pine at pole 200 sq ft pine mid span remove 200 sq ft pine end of span at oak. Prune pine Overhanging at pole and side begin of span. 5 Pine side and crown 1/4 span to mid span. 3 Pine side 3/4 span. 1 side end of span. CALL AHEAD BEFORE		0	Yes
940	67.1	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove 200 sq ft pine brush mid span		0	Yes
941	67.2	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA				Make safe 2 recent dead pines 1 on each side of the wire remove brush throughout entire span to next pole 700 sq ft		0	Yes

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
942	67.3	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Remove brush starting mid span work west down line clear 1000 sq ft pine brush PTS 3 cedar 3 pine in span PTS 1 oak off service drop north of pole 050103		0	Yes
943	67.4	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Remove 600 sq ft pine brush		0	Yes
944	67.9	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA	5034675840		Climb	Work from valley pines rd work. South to back distribution line only top trees to spec. Work span and evenly top the trees to leave a border fence for customer. Very concerned and wants brush to remain. PTS 1 overhanging pine PTS 3 pine mid span Call AHEA		0	Yes
945	67.8	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft pine brush at pole 051301 remove 100 sq ft pine brush past pink boundary stake PTS 1 pine off service drop pole 051300		0	No
946	67.7	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Remove all pine brush in span 1000 sq ft PTS 2 pine at pole 1 pine 50 ft from pole. Oak crown pruning 1/4 span from pole p050200.		0	Yes
947	66.1	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Remove 100 sq ft brush each side of pole		0	No
948	65.9	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Make safe 2 dead pines on the right side of line work south from pole remove 100 sq ft brush work to next pole. At that pole make safe 1 dead pine big pine on left side of pole. Now work across street west mid span make safe 1 dead pine on Right if standi		0	Yes
949	73.2	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA	5305985651		lift_climb	PTS 1 overhanging oak heading west down the line remove all willow brush 1500 sq ft west PTS 1 oak mid span 1 oak near pole 298601 remove 1000 sq ft North if pole 4 47 make safe 4 dead poplar mid span north of pole		1	Yes
950	73.1	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 2 pine south of pole towards school remove 200 sq ft brush in creek move SW up line mid span remove 800 sq ft willow hike cherry brush		1	No
951	72.9	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Remove 2000 sq ft cedar pine brush entire span to pole 296601 make safe 1 dead cedar 20 ft back from pole remove 100 sq ft cedar brush NW pole 296601		0	Yes

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
952	71.5	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 3 willow reaching toward wire 2 Hawthorne by pole with transformer heading g out to field 1 willow in creek on opposite side of wire mid span remove 1 willow shoots off tree by dead fell tree from pole 112300 all needs done is PTS 1 Hawthorne mid span		1	Yes
953	71.4	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	PTS 1 outreaching willow by pole		1	No
954	71.6	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 Hawthorne at pole 1 willow under line PTS 1 Hawthorne at pole with transformer in field.		1	No
955	56.2	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	PTS 1 oak 2 pines at pole 1 pine mid span heading across river head back to house pts 1 oak mid span along drive by big pondo		0	No
956	56.3	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Remove 100 sq ft pine brush at pole work head SE down line PTS 1 poplar mid span 1 poplar at edge of creek		1	No
957	56.1	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Make safe 1 dead pine directly west from pole across the rd		0	No
958	18.6	10/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Cedar side and one sycamore. Just prune sycamore portion on Collier.		1	Yes
959		10/21/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 1 spruce in front yard. Prune side back to bole of tree.		0	No
960	75.2	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 overhanging side pine at arrow left sign PTS under growth pine at pole, with flag		0	No
961	75.3	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 overhanging pine mid span		0	No
962	75.4	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 side pine mid span PTS 1 pine side at pole 368900 move mid span PTS 2 overhanging pine and sides		0	No
963	75.5	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	PTS 1 pine side left of pole 25ft 2 overhanging pine at next pole 367903 2 overhanging pine mid span of pole 367904 heading West down kidder 1closer to next pole 366904		0	No
964	75.6	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 1 side pine 1 pine mid span towards hardrock rd 1 overhanging pine at pole 366902		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
965	75.6	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 1 side oak behind rock wall at beginning of house drive 1 overhanging pine by rock fence 1 overhanging pine left of pole end of rock fence move past pole 1 overhanging pine right side 1 overhanging pine mid span at 2908 driveway 1 pine side at drive 2		0	No
966		11/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Greenview	CA			Lift	PTS 1 maple 1 birch 2 overhanging pines 1 under wire pine		0	No
967		11/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Greenview	CA			Lift	PTS 3 oaks under wire		0	No
968		11/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	PTS 3 Oaks in span 1 oak at end pole with transformer		0	No
969		11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Climb	Pts 1 pine side 1 overhanging pine mid span			
970	75.7	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 4 pine side 2 overhanging pine in front of garage continue to move down line Pts 2 pine side after pole 366804		0	No
971	75.8	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Pts 1 pine 2 oak sides right of pole 1 overhanging pine after pole 1 poplar 1 pine mid span remove 1000 sq ft oak cedar pine brush under line		0	No
972	75.9	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 1 overhanging pine after bridge 1 overhanging oak mid span 1 side oak at gate entrance if [redacted]		0	No
973	76.1	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Pts dead out of 1 pine 2 oak at pole need more clearance		0	No
974	76.2	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 2 pine side around pole 1 overhanging pine mid span		0	No
975	76.3	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 1 pine side at pole work down whispering pines rd pts 2 overhanging pines 1 pine side at pole 363903 1 oak 1 pine mid span of that pole keep working down whispering pines pts 1 pine at pole 363801 pts 1 overhanging pine at California outdoor propertie		0	No
976	76.4	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	Pts 1 pine side 2 overhanging pines near next pole not along whispering pines 1 pine mid span before end pole 1 pine and pole		0	No
977	76.5	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 1 pine at pole 2 side pines after driveway 1 pine side at pole 363600		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
978	76.6	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 1 pine side to the right of pole 1 oak at pole 2 pine mid span towards drive remove 600 sq ft of pine brush throughout span		0	No
979	76.7	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 pine side			
980	76.8	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 2 overhanging pines and sides throughout span		0	No
981	76.9	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 1 side oak 3 side pines 1 overhanging pine next pole work past pole 1 pine side opposite side of rd 1 leaning pine towards wire off pole 358501 1 knobcone pine before pole 357500 1 overhanging pine at next pole 357403 1 cedar 1 outreaching pine opposi		0	No
982	77.1	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Pts 1 pine side at pole head across rd and pts 2 outreaching oaks 1 pine mid span 1 oak at end pole		0	No
983	77.2	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 1 overhanging pine 1 outreaching oak at driveway 2 side for trees down drive mid span 1 Jeffery pine side 1 pine side at pole 358401 keep moving down gravel drive 2 pine wide mid span that pole 1 pine side at pole 358400 left side 2 pines mid span unt		0	No
984	77.3	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 1 pine side 1 pine at end pole		0	No
985	77.3	11/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 4 oaks around pole make safe the one infected with mistletoe move up hill mid span 1 pine side		0	No
986	77.4	11/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Pts 1 pine side mid span work up hill past metal shed and green barn to next pole pts 3 oak side until pole B0768 pts 1 oak at that pole go up towards house pts 4 oak 1 overhanging pine 2 oaks at end pole		0	No
987	77.5	11/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Pts 3 fir sides 1 overhanging pine 1 overhanging fir at next pole pts 2 fir sides work to next pole B11951 pts 2 oak 1 fir 1 pine heading downhill		0	No
988	77.6	11/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	PTS 1 overhanging pine 1 cedar side left of pole move right side pts 3 overhanging cedar 1 overhanging pine mid span 4 cedar sides on. Right side of drive 2 cedar sides left of drive 1 overhanging pine		0	No

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Work Code	Contact Type	Ownership	Landowner Name	Address	City	State	Landowner Phone	Landowner Email	Crew Type	Work Description	Work Summary	Cycle Busters	TGR?
989		11/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	1 overhanging pine at pole 1 pine side at pole head down line away from rd pts 3 overhanging pines work to pole B1670 pts 4 pines in span move next span pts 2 overhanging pines		0	No
990		11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 3 oaks at pole		0	No
991		11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 2 pines at pole		0	No
992		11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Lift	Pts 1 overhanging pine 1 oak side mid span		0	No
993		11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 3 pine sides work to pole 369901 pts 1 overhanging pine 2 pine side 1 pine under work to pole 369902 pts 1 pine side 2 overhanging pines 1 pine side at next pole at fence property line 1 pine side at corner pole		0	No
994		11/16/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41		Door_Card				Etna	CA			lift_climb	3 overhanging pines 1 pine side head towards end pole with transformer pts 1 side pine		0	No
995	77.5	11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 1 side box elder at pole work down away from town to pole 12 37 pts 1 plum cherry in yard of 103 1 side and overhang of pine mid span by 45 mph sign		0	No
996	55.3	11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Door_Card				Etna	CA			Lift	Pts 3 pine sides		0	No
997		11/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			lift_climb	Pts 2 pine 1 overhanging pine 1 pine right off the driveway		0	No
998		11/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41		Personal				Etna	CA			Climb	Pts 3 pines at pole remove 400 sq ft pondo brush Pts 3 poplars in creek remove 400 sq ft poplar brush pts 1 pine side move to next span pts 2 pine side 1 overhanging pine move next span pts 1 overhanging fir tree		1	No

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
1	**Pacific Power - Distribution Inventory Report - All Work Codes**															**Total Inventoried Units by Mitigation Effort**									
2	For 1/1/2020 to 12/31/2020; Transmission Or Distribution: Distribution; All; All States; All Companies; All Inspectors; All Districts; Feeder or							**3383**	**1**	**795**	**84949**	**76**	**0**	**18**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**				
3	**R#**	**Date Inspected**	**Time Inspected**	**Inspector**	**Company**	**District**	**Feeder**	**Prune**	**Secondary Prunes**	**Brush Prune Sq Ft**	**Removals Brush Sq Ft**	**Removals 6-11"**	**Removals 12-23"**	**Removals 24"+**	**Reliability Prunes Brush Sq Ft**	**Reliability Prunes 6-11"**	**Reliability Prunes 12-23"**	**Reliability Prunes 24"+**	**Reliability Removals Brush Sq Ft**	**Reliability Removals 6-11"**	**Reliability Removals 12-23"**	**Reliability Removals 24"+**	**GIS References**			
																							LAT	**LONG**	**Form ID**	**Map Object ID**
4	2.9	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]	[redacted]	7938	261298
5	1.2	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				7956	261366
6	1.3	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				7957	261384
7	1.5	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				7958	261397
8	1.6	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	50	0	0	0	0	0	0	0	0	0	0	0				7971	261428
9	1.7	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				7974	261442
10	1.8	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				7979	261466
11	1.9	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				7982	261474
12	2.1	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				7984	261484
13	2.2	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				7987	261486
14	15.9	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	40	0	0	0	0	0	0	0	0	0	0	0	0	0				8000	261508
15	2.6	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				8007	261556
16	2.8	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8019	261598
17	3.1	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				8023	261294
18	1.1	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				9695	261364
19	2.7	6/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9696	261586
20	72.9	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8358	262802
21	73.2	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8362	262815
22	73.1	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8371	262820
23	73.3	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				8373	262842
24	72.6	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				8378	262863
25	72.4	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8381	262869
26	72.3	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	14	0	0	0	0	0	0	0	0	0	0	0	0	0				8385	262876
27	72.5	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8390	262893
28	71.7	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				8391	262902
29	70.9	6/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				8394	262907

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
30	6.6	6/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		8485	45417
31	4.7	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				8777	264466
32	4.5	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				8778	264467
33	4.6	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	2	0	0	0	0	0	0	0				8779	264468
34	4.9	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				8780	264469
35	5.1	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				8781	264470
36	4.8	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	2	0	0	0	0	0	0	0				8782	264471
37	6.9	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	1	0	0	0	0	0	0	0				8783	264472
38	7.1	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8784	264473
39	4.4	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8785	261683
40	4.1	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8786	261719
41	3.9	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8787	264474
42	4.2	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				8788	264475
43	4.3	6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				8789	264476
44		6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				8790	261628
45		6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8791	261627
46		6/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8792	261622
47	6.4	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8914	265244
48	6.5	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8915	265245
49	6.8	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				8916	265248
50	6.4	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10629	265244
51	6.5	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10630	265245
52	6.8	6/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10631	265248
53	17.3	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9182	266922
54	17.5	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9183	266923
55	17.6	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9184	262943
56	17.7	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9185	266924
57	17.8	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9186	266925

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
58	18.1	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		9187	266926
59	18.3	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				9188	266927
60	18.2	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				9189	266928
61	17.9	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9190	266929
62	19.2	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9191	266930
63	30.5	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9192	266931
64	30.3	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9193	266932
65	30.1	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9194	266933
66	30.2	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				9195	266934
67	20.9	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9196	266935
68	20.8	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9197	266936
69	20.7	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9198	266937
70	20.6	6/30/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9199	266938
71	17.1	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9388	267875
72	73.6	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9389	267876
73	74.1	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9390	267877
74	73.8	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	3	0	0	0	0	0	0	0	0	0	0				9391	267878
75	73.9	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9392	267879
76	73.4	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9393	267880
77	73.5	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9394	267881
78	73.7	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	1	0	0	0	0	0	0	0				9395	267882
79	16.1	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	1	0	0	0	0	0	0	0				9396	267883
80	15.5	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9397	267884
81	15.4	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9398	267885
82	15.3	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				9399	262481
83	15.2	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9400	267886
84	15.1	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9401	262482
85	14.9	7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9402	262483

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
86		7/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		9403	267888
87	3.3	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				9530	261619
88	5.2	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	6	0	6	0	0	0	0	0	0	0				9531	268326
89	5.3	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	4	0	0	0	0	0	0	0				9532	264478
90	5.8	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9534	268331
91	6.1	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9535	268332
92	6.2	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9536	262980
93	6.3	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9537	268333
94	5.9	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9538	268334
95	6.6	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9539	265246
96	6.7	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9540	265247
97	3.2	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	0	0	0	0	0	0	0	0				9541	261617
98	7.2	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9542	268335
99	8.8	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				9543	268339
100	8.9	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9544	268340
101	9.4	7/2/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9545	268341
102	11.7	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9697	268348
103	11.2	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9698	268347
104	11.1	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9699	268346
105	10.8	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9700	268349
106	10.6	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9701	268345
107	9.8	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9702	268353
108	10.4	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9703	268350
109	10.3	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9704	268351
110	10.1	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9705	268352
111	9.7	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9706	268344

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
112	9.5	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	1	0	0	0	0	0	0	0		[redacted]		9707	268343
113	9.5	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9708	268342
114	9.3	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9709	268336
115	9.2	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9710	268337
116	9.1	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9711	268338
117		7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				9712	269321
118	11.8	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9713	269326
119	11.4	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9714	269327
120	11.3	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9715	269328
121	11.5	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9716	269329
122	11.6	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9717	269330
123	10.9	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9718	269331
124	10.7	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9719	269332
125	10.5	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9720	269333
126	10.2	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9721	269334
127	9.9	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9722	269335
128	8.7	7/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9723	269325
129	12.1	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9841	269824
130	12.2	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9842	269825
131	12.4	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				9843	269826
132	12.5	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9844	269827
133	12.6	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9845	269828
134	12.7	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9846	269829
135	12.8	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				9847	269830
136	12.9	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9848	269831
137	12.3	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9849	269832

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
138	11.9	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		9850	269833
139	70.4	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9851	269834
140	70.2	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9852	269835
141	70.1	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9853	269836
142	61.9	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9854	262502
143	61.8	7/7/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9855	262503
144	8.4	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				9993	269322
145	8.6	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				9994	269323
146	8.3	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				9995	261739
147	16.2	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10007	270502
148	16.3	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10008	270503
149	16.4	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10009	270504
150	16.5	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10010	270505
151	16.6	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10011	270506
152	16.9	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10017	270508
153	16.7	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10018	270509
154	7.5	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10019	262092
155	7.7	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10020	262094
156	7.6	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10021	270510
157	7.4	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10022	270511
158	7.9	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10023	270512
159	8.1	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10024	270513
160	8.2	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10025	270514
161	8.5	7/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				10026	270515
162	14.7	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10115	262485

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
163	14.6	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		10116	270955
164	14.2	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10117	270956
165	14.1	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10118	262491
166	13.8	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10119	262494
167	13.7	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10120	262496
168	13.4	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10121	270957
169	13.3	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10122	262497
170	13.6	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10123	262495
171	13.5	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10124	270958
172	13.9	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10125	262492
173	14.5	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10126	262489
174	14.4	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10127	262487
175	17.2	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10129	266921
176	40.1	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10130	270963
177	40.2	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10131	270964
178	40.3	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				10132	270965
179	60.1	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10133	270966
180	60.2	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10134	270967
181	60.3	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10135	270968
182	50.9	7/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10136	270962
183	18.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10632	269845
184	18.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10633	269846
185	18.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10634	269847

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
186	18.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		10635	269844
187	18.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10636	269843
188	19.1	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10637	269848
189	5.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10638	272471
190	19.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10639	269850
191	19.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10640	272472
192	19.3	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10641	269849
193	19.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10642	269852
194	19.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10643	272473
195	19.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10644	269851
196	50.2	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10645	270977
197	50.3	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10646	270976
198	50.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10647	270975
199	50.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10648	272474
200	50.1	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10649	270974
201	40.9	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10650	270973
202	40.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10651	272475
203	40.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10652	270972
204	50.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10653	272476
205	40.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10654	272477
206	50.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10655	272478
207	50.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10656	272479

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
208	40.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		10657	270969
209	40.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10658	270961
210	30.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10659	272480
211	30.9	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10660	270960
212	30.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				10661	264481
213	19.9	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10662	269854
214	20.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				10663	269855
215	20.1	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10664	269860
216	20.3	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10665	269858
217	20.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10666	269857
218	20.2	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10667	269861
219	30.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10668	272481
220	60.4	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10669	266939
221	60.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10670	264479
222	60.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10671	272482
223	60.7	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10672	270959
224	30.6	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10673	264480
225	60.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10674	272483
226	70.5	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				10675	266941
227	70.8	7/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10676	262501
228	1.1	7/13/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11329	264479
229	1.2	7/13/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				11330	264481
230	1.3	7/13/2020	12:00 AM	Lorelei Phillips	Pacificorp - Pacific Power	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				11331	270974

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
231	71.8	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		10677	272484
232	72.7	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10678	272485
233	71.9	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				10679	272486
234	72.2	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	700	0	0	0	0	0	0	0	0	0	0	0				10680	272487
235	72.1	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				10681	272488
236	70.6	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				10682	272489
237	70.7	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10683	272490
238	70.3	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10684	272491
239	61.7	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10685	272492
240	61.6	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10686	269837
241	61.5	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10687	269838
242	61.2	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10688	269839
243	61.3	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10689	269840
244	61.4	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10690	269841
245	61.1	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				10691	269842
246	60.9	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10692	272493
247	18.9	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				10693	272470
248	17.4	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				10694	272494
249	5.4	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	1	0	0	0	0	0	0	0	0	0				10695	268328
250	5.5	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	1	0	0	0	0	0	0	0	0	0				10696	268327
251	5.6	7/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	1	0	0	0	0	0	0	0	0	0				10697	268329

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
252	1.3	7/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		10797	272968
253	5.5	7/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	2	0	0	0	0	0	0	0	0	0				11033	274047
254	71.6	7/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11034	274070
255	14.8	7/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11142	274473
256	16.8	7/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	3	0	0	0	0	0	0	0	0	0				11148	270507
257	1.1	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	21	0	0	10	2	0	0	0	0	0	0	0	0	0				11252	274068
258	1.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	20	4	0	0	0	0	0	0	0	0	0				11347	274067
259	1.3	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	20	0	0	0	0	0	0	0	0	0	0				11348	274066
260	1.4	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	8	0	0	0	0	0	0	0	0	0	0				11349	275219
261	1.5	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11350	274065
262	1.6	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	30	0	0	0	0	0	0	0	0	0	0				11351	274064
263	1.7	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	70	0	0	0	0	0	0	0	0	0	0				11352	274063
264	1.8	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	0	0	0	0	0	0	0	0	0	0	0				11353	274062
265	1.9	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				11354	275220
266	2.1	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	60	0	0	0	0	0	0	0	0	0	0				11355	274061
267	2.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	14	0	0	20	0	0	0	0	0	0	0	0	0	0				11356	274060

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
268	2.3	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		11357	274059
269	2.4	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	5	0	0	0	0	0	0	0	0	0	0				11358	274057
270	2.5	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				11359	274056
271	2.7	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	10	0	0	0	0	0	0	0	0	0	0				11360	274055
272	2.6	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11361	275221
273	2.8	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				11362	274054
274	2.9	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	40	0	0	0	0	0	0	0	0	0	0				11363	274053
275	3.1	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	50	0	0	0	0	0	0	0	0	0	0				11364	274052
276	3.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11365	274051
277	3.3	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11366	274049
278	3.4	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11367	275222
279	3.5	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				11368	274048
280	3.6	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	15	0	0	0	0	0	0	0	0	0	0				11369	275223
281	3.7	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11370	275224
282	3.8	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	2	0	0	0	0	0	0	0	0	0	0				11371	275225
283	3.9	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	5	0	0	0	0	0	0	0	0	0	0				11372	275226
284	4.1	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				11373	275227
285	4.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11374	275228
286	4.3	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11375	274071
287	4.4	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				11376	275229
288	4.5	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	10	0	0	0	0	0	0	0	0	0	0				11377	275230
289	4.6	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11378	275232
290	4.7	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11379	275233
291	4.8	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	0	0	0	0	0	0	0	0	0	0	0				11380	275234

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
292	74.2	7/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		11381	275236
293	8.6	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11483	275948
294	8.7	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				11484	275949
295	8.8	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11485	275950
296	8.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11486	275951
297	8.5	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				11487	275952
298	8.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11488	275953
299	8.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0				11489	275954
300	8.4	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11490	275955
301	8.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11491	275956
302	7.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11492	275957
303	7.8	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11493	275958
304	7.7	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	10	0	0	0	0	0	0	0	0	0	0				11494	275959
305	7.6	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	10	0	0	0	0	0	0	0	0	0	0				11495	275960
306	7.5	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11496	275961
307	7.4	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11497	275962
308	7.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				11498	275963
309	5.6	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				11499	275964
310	5.7	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	2	0	0	0	0	0	0	0	0	0				11500	275965
311	5.8	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	1	0	0	0	0	0	0	0	0	0				11501	275966
312	5.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11502	275967
313	6.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11503	275968
314	6.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11504	275969
315	6.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				11505	275970
316	6.4	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11506	275971

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
317	6.5	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	1	0	0	0	0	0	0	0	0	0		[redacted]		11507	275972
318	6.6	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	4	0	0	0	0	0	0	0	0	0				11508	275973
319	6.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	3	0	0	0	0	0	0	0	0	0				11509	275974
320	7.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	2	0	0	0	0	0	0	0	0	0				11510	275975
321	7.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				11511	275976
322	6.7	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11512	275977
323	6.8	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0				11513	275978
324	5.4	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11514	275979
325	5.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				11515	275980
326	5.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11516	262901
327	5.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11517	275981
328	4.9	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	30	0	0	0	0	0	0	0	0	0	0	0				11518	275982
329	9.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11519	275231
330	9.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11520	275983
331	9.3	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	0	0	0	0	0	0	0	0	0	0	0				11521	275984
332	80.2	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11523	275986
333	80.1	7/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11524	275987
334		7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	28	0	0	0	0	0	0	0	0	0	0				11693	277393
335		7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11694	277394
336		7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11695	277395
337		7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	50	0	0	0	0	0	0	0	0	0	0				11696	277396
338	26.1	7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				11697	277397
339	26.2	7/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	3	0	0	0	0	0	0	0	0	0	0				11698	277398

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
340	31.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	5	0	0	0	0	0	0	0	0	0	0	0		[redacted]		11775	277711
341	31.7	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	10	0	0	0	0	0	0	0	0	0	0	0				11776	277712
342	31.8	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	150	0	0	0	0	0	0	0	0	0	0				11777	277713
343		7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	14	0	0	60	0	0	0	0	0	0	0	0	0	0				11778	277714
344	10.1	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	50	0	0	0	0	0	0	0	0	0	0				11779	277715
345		7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	18	0	0	0	0	0	0	0	0	0	0	0	0	0				11780	277726
346	10.2	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0				11784	277752
347	10.3	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				11786	277754
348	10.4	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				11787	277770
349	10.5	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11788	277773
350	10.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	0	0	0	0	0	0	0	0	0	0	0				11790	277774
351	10.7	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				11791	277775
352	10.8	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11794	277783
353	10.9	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				11795	277791
354	11.1	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11796	277804
355	11.2	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				11797	277808
356	11.3	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11798	277815
357	11.4	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11800	277824
358	11.5	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11801	277827
359	11.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11802	277834

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
360	11.7	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		11806	277858
361	11.8	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11807	277861
362	11.9	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11808	277868
363	12.1	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11811	277874
364	12.2	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				11812	277881
365	12.3	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11813	277885
366	12.4	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				11814	277894
367	12.5	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11816	277906
368	25.9	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11818	277916
369	26.4	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11819	277922
370	26.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11820	277927
371	8.6	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11821	277934
372	80.5	7/27/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11822	277936
373	27.5	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	1000	0	0	0	0	0	0	0	0	0	0				11910	278326
374	80.8	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11911	278374
375		7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11912	278387
376		7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				11913	278391
377	80.3	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	9	0	0	0	0	0	0	0	0	0				11919	278417

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
378	71.1	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		11921	278445
379	71.2	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0				11922	278455
380	26.5	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				11925	278476
381	29.9	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	5	0	0	0	0	0	0	0	0	0	0				11926	278483
382	29.8	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	6	0	0	0	0	0	0	0	0	0	0				11927	278503
383	30.2	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	2	0	0	0	0	0	0	0	0	0				11930	278509
384	30.1	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11933	278519
385	30.1	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	18	0	0	0	0	0	0	0	0	0	0	0	0	0				11946	278556
386	30.2	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11949	278565
387	32.2	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				11968	278643
388	32.3	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11969	278653
389	32.4	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	50	1	0	0	0	0	0	0	0	0	0				11976	278661
390	32.5	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				11977	278663
391	32.1	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				11978	278664
392	61.9	7/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	10	0	0	0	0	0	0	0	0	0	0				11999	278700
393	12.7	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				12133	280358

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
394	12.8	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		12134	280359
395	12.9	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12135	280360
396	13.1	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	0	0	0	0	0	0	0	0				12136	280361
397	13.7	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				12137	280366
398	13.8	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12138	280367
399	13.9	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12139	280368
400	14.1	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				12140	280369
401	14.2	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12141	280370
402	13.6	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12142	280365
403	13.5	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				12143	280364
404	13.4	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				12144	280363
405	13.3	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12145	280362
406	17.1	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	15	0	0	600	0	0	0	0	0	0	0	0	0	0				12146	280371
407	16.9	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	19	0	0	0	0	0	0	0	0	0	0	0	0	0				12147	280372
408	16.8	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				12148	280373
409	55.1	7/29/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12149	280375
410	55.6	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				12421	281820
411	55.5	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12422	281821
412	42.1	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12423	281822
413	41.9	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12424	281823
414	41.5	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12425	281824
415	41.6	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12426	281825
416	41.7	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12427	281826

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
417	41.8	8/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		12428	281827
418	41.2	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				12464	282022
419	41.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12467	282048
420	14.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	13	0	0	0	0	0	0	0	0	0	0	0	0	0				12472	282086
421	14.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				12476	282124
422	14.5	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	0	0	0	0	0	0	0	0	0	0	0				12478	282125
423	14.6	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12479	282135
424	14.7	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				12480	282138
425	14.8	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12481	282146
426	13.2	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12484	282161
427	15.1	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				12487	282174
428	15.2	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				12490	282189
429	15.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12492	282198
430	15.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				12493	282199
431	15.5	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				12495	282211
432	15.6	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				12496	282213
433	15.7	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				12501	282214
434	15.8	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12502	282253

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
435	15.9	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		12503	282256
436	16.1	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12504	282264
437	69.8	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12582	282613
438	69.7	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12583	282614
439	69.6	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				12584	282615
440	69.5	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12585	282616
441	69.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	10	0	0	0	0	0	0	0	0	0	0				12586	282617
442	69.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				12587	282618
443	27.6	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	26	0	0	0	0	0	0	0	0	0	0				12588	282619
444	27.7	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	6	0	0	0	0	0	0	0	0	0	0				12589	282620
445	27.9	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	1	0	0	0	0	0	0	0	0	0				12590	282621
446	27.8	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12591	282622
447	28.1	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				12592	282623
448	28.2	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12593	282624
449	28.3	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12594	282625
450	28.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12595	282626
451	32.9	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12596	282627
452	41.4	8/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				12597	282628
453	26.3	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12676	277400
454	26.7	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12677	283080
455	26.8	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				12678	277404
456	26.9	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12679	277405

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
457	27.1	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]	[redacted]	12680	277406
458	27.2	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12681	277408
459	69.9	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12682	283081
460	27.3	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12683	283082
461	27.4	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				12684	277928
462	29.6	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12685	283083
463	80.7	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	3	0	0	0	0	0	0	0	0	0				12686	278343
464	43.8	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12688	283103
465	43.9	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				12689	283104
466	44.1	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	15	0	0	0	0	0	0	0	0	0	0				12690	283110
467	44.2	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0				12691	283113
468	44.3	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	4	0	0	0	0	0	0	0	0	0	0				12692	283114
469	44.4	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	5	0	0	0	0	0	0	0	0	0	0				12693	283119
470	44.5	8/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				12695	283136
471	45.3	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				12955	284231
472	45.1	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				12956	284230
473	45.2	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				12957	284234
474	39.6	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	2	0	0	0	0	0	0	0	0	0	0				12958	284235
475	39.5	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	4	0	0	0	0	0	0	0	0	0	0				12959	284236
476	33.9	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	12	0	0	0	0	0	0	0	0	0	0				12960	284237
477	33.8	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	2	0	0	0	0	0	0	0	0	0	0				12961	284238

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
478	33.7	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	22	0	0	0	0	0	0	0	0	0	0		[redacted]		12962	284239
479	33.6	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				12963	284240
480	34.1	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	20	0	0	0	0	0	0	0	0	0	0				12964	284241
481	34.2	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	14	0	0	0	0	0	0	0	0	0	0				12965	284242
482	34.8	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	7	0	0	0	0	0	0	0	0	0	0				12966	284243
483	34.9	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12967	284244
484	45.4	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				12968	284232
485	35.1	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12969	284245
486	35.9	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	3	0	0	0	0	0	0	0	0	0				12970	284246
487	36.1	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				12971	284247
488	36.2	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				12972	284248
489	36.3	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				12973	284249
490	45.5	8/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				12974	284233
491	44.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13229	285710
492	45.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13230	285711
493	45.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				13231	285712
494	45.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13232	285713
495	45.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13233	285714
496	46.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	15	0	0	0	0	0	0	0	0	0	0				13234	285715
497	46.2	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	15	0	0	0	0	0	0	0	0	0	0				13235	285716
498	49.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13236	285718
499	49.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13237	285719

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
500	49.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		13238	285720
501	50.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13239	285721
502	50.2	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13240	285722
503	50.4	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				13241	285723
504	50.5	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	0	0	0	0	0	0	0	0	0	0	0				13242	285724
505	50.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				13243	285725
506	49.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	16	0	0	100	0	0	0	0	0	0	0	0	0	0				13244	285726
507	49.5	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	0	3	0	0	0	0	0	0	0	0	0				13245	285727
508	49.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13246	285728
509	47.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13247	285729
510	36.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	2	0	0	0	0	0	0	0	0	0				13248	284252
511	37.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	11	0	0	0	0	0	0	0	0	0				13249	285730
512	37.2	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13250	285731
513	37.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				13251	285732
514	37.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	20	0	0	0	0	0	0	0	0	0	0				13252	285733
515	37.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	10	0	0	0	0	0	0	0	0	0	0				13253	285734
516	38.2	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13254	285735
517	38.3	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	40	0	0	0	0	0	0	0	0	0	0				13255	285736

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
518	38.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	10	0	0	0	0	0	0	0	0	0	0		[redacted]		13256	285737
519	38.5	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13257	285738
520	38.4	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13258	285739
521	38.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13259	285740
522	38.1	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	55	0	0	0	0	0	0	0	0	0	0				13260	285741
523	37.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	20	0	0	0	0	0	0	0	0	0	0				13261	285742
524	38.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13262	285743
525	38.9	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	5	0	0	0	0	0	0	0	0	0	0				13263	285744
526	37.3	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13264	285745
527	36.4	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13265	285746
528	36.8	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13266	284250
529	36.5	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13267	285747
530	36.6	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13268	285748
531	36.7	8/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13269	285749
532	34.3	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	8	0	0	0	0	0	0	0	0	0	0				13344	286700
533	34.6	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13345	286701
534	34.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	3	0	0	0	0	0	0	0	0	0	0				13346	286702
535	35.2	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13347	286703
536		8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13348	286704
537	35.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13349	286705
538	35.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	10	0	0	0	0	0	0	0	0	0	0				13350	286706
539	35.6	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13351	286707
540	35.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	4	0	0	0	0	0	0	0	0	0	0				13352	286708

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
541	35.8	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	2	0	0	0	0	0	0	0	0	0	0		[redacted]		13353	286709
542	39.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13354	286710
543	39.3	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				13355	286711
544	39.2	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	6	0	0	0	0	0	0	0	0	0	0				13356	286712
545	39.1	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13357	286713
546	37.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	0	0	0	0	0	0	0	0	0	0	0				13358	286714
547	37.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	10	0	0	0	0	0	0	0	0	0	0				13359	286715
548	34.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13360	286716
549	34.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13361	286717
550	39.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	50	0	0	0	0	0	0	0	0	0	0				13362	286718
551	39.9	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13363	286719
552	40.1	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13364	286720
553	39.8	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	30	0	0	0	0	0	0	0	0	0	0				13365	286721
554	40.2	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13366	286722
555	40.3	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13367	286723
556	40.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13368	286724
557	40.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	40	0	0	0	0	0	0	0	0	0	0				13369	286725
558	40.6	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13370	286726
559	40.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13371	286727
560	55.8	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13372	286728

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
561	61.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		13373	286729
562	61.6	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				13374	286730
563	61.7	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13375	286731
564	61.8	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13376	286732
565	31.5	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13377	286733
566	31.4	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13378	286734
567	31.3	8/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13379	286735
568	52.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				13541	287599
569	53.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13542	287600
570	53.3	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	200	0	0	0	0	0	0	0	0	0	0				13543	287601
571	43.7	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13544	287602
572	43.6	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13545	287603
573	43.5	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13546	287604
574	43.4	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13547	287605
575	43.3	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				13548	287606
576	43.2	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				13549	287607
577	43.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	0	1	0	0	0	0	0	0	0	0	0				13550	287608

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
578	42.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		13551	287609
579	42.8	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13552	264477
580	42.7	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	1000	0	0	0	0	0	0	0	0	0	0				13553	261620
581	42.6	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13554	287610
582	42.5	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13555	287611
583	42.2	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13556	287612
584	41.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13557	287613
585	40.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13558	287614
586	40.8	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13559	287615
587	33.5	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13560	287616
588	33.2	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				13561	287617
589	33.3	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13562	287618
590	33.4	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13563	287619
591	33.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13564	287620
592	31.2	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13565	287621
593	30.3	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	20	0	0	0	0	0	0	0	0	0	0				13566	287622
594	30.7	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	10	0	0	0	0	0	0	0	0	0	0				13567	287623
595	30.6	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13568	287624
596	30.4	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13569	287625
597	30.5	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				13570	287626
598	30.8	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	5	0	0	0	0	0	0	0	0	0	0				13571	287627
599	30.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13572	287628

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
600	31.1	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	10	0	0	0	0	0	0	0	0	0	0		[redacted]		13573	287629
601	31.9	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13574	287630
602	32.6	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13575	287631
603	32.7	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13576	287632
604	32.8	8/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13577	287633
605	9.8	8/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13584	290522
606	9.7	8/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	10	0	0	0	0	0	0	0	0	0	0				13585	290523
607	9.6	8/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	10	0	0	0	0	0	0	0	0	0	0				13586	290524
608	9.5	8/14/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13587	290525
609	17.6	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13776	291753
610	17.7	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13777	291754
611	17.9	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13778	291756
612	18.1	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13779	291757
613	18.2	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13780	291758
614	18.3	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13781	291759
615	18.4	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13782	291760
616	28.7	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	44	0	0	0	0	0	0	0	0	0	0				13783	291768
617	28.8	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13784	291769
618	28.6	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				13785	291770
619	28.5	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				13786	291771
620	28.9	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	60	0	0	0	0	0	0	0	0	0	0				13787	291772
621	29.1	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	180	0	0	0	0	0	0	0	0	0	0				13788	291773
622	29.2	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	140	0	0	0	0	0	0	0	0	0	0				13789	291774
623	29.3	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	40	0	0	0	0	0	0	0	0	0	0				13790	291775
624	29.4	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	50	0	0	0	0	0	0	0	0	0	0				13791	291776
625	44.8	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				13792	291777

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
626	44.6	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	6	0	0	0	0	0	0	0	0	0	0		[redacted]		13793	291778
627	44.7	8/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	100	0	0	0	0	0	0	0	0	0	0				13794	291779
628	46.3	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	20	0	0	0	0	0	0	0	0	0	0				13925	292585
629	61.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13926	292586
630	46.8	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13927	292587
631	46.9	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13928	292588
632	47.2	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	1	0	0	0	0	0	0	0	0	0				13929	292589
633	47.3	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13930	292590
634	47.1	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13931	292591
635	46.7	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13932	292592
636	46.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13933	292593
637	46.5	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13934	292594
638	46.6	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	14	0	0	0	0	0	0	0	0	0	0	0	0	0				13935	292595
639	60.9	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13936	292596
640	70.1	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				13937	292597
641	49.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	13	0	0	0	0	0	0	0	0	0	0	0	0	0				13938	292598
642	49.3	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13939	292599

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
643	49.2	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		13940	292600
644	47.5	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	13	0	0	0	0	0	0	0	0	0	0	0	0	0				13941	292601
645	47.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	15	0	0	0	0	0	0	0	0	0	0	0	0	0				13942	292602
646	47.6	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13943	292603
647	47.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	0	0	0	0	0	0	0	0	0	0	0				13944	292604
648	47.8	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				13945	292605
649	48.1	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13946	292606
650	48.2	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13947	292607
651	48.3	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13948	292608
652	48.4	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13949	292609
653	48.5	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				13950	292610
654	48.6	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13951	292611
655	48.8	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				13952	292612
656	48.7	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				13953	292613
657	48.9	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	3	0	0	0	0	0	0	0	0	0				13954	292614
658	51.9	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				13955	292615
659	52.1	8/19/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				13956	292616
660	67.5	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	5	0	0	0	0	0	0	0	0	0	0				14021	293058
661	67.6	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	25	0	0	0	0	0	0	0	0	0	0				14022	293059
662	66.5	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14023	293060

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
663	66.2	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		14024	293061
664	66.3	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14025	293062
665	66.4	8/20/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	2	0	0	0	0	0	0	0	0	0	0				14026	293063
666	22.7	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	0	0	0	0	0	0	0	0	0	0	0				14164	293525
667	22.8	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14165	293526
668	22.9	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				14166	293527
669	22.4	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14167	293528
670	22.5	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14168	293529
671	23.1	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14169	293530
672	23.3	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14170	293531
673	23.2	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14171	293532
674	23.4	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14172	293533
675	23.5	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14173	293534
676	23.6	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14174	293535
677	23.7	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14175	293536
678	23.8	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				14176	293537
679	23.9	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14177	293538
680	24.1	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14178	293539
681	24.2	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14179	293540
682	24.4	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14180	293541
683	24.3	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	70	0	0	0	0	0	0	0	0	0	0				14181	293542
684	24.5	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14182	293543
685	24.6	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14183	293544
686	24.7	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14184	293545

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
687	24.8	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		14185	293546
688	25.2	8/21/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14186	293547
689	12.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				14450	294706
690	16.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				14451	294707
691	16.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14452	294708
692	16.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14453	294709
693	16.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				14454	294710
694	16.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				14455	294711
695	16.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14456	294712
696	17.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	0	0	0	0	0	0	0	0	0	0	0				14457	294713
697	17.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14458	294714
698	17.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14459	294715
699	17.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14460	294716
700	17.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14461	291755
701	18.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14462	291761
702		8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	0	0	0	0	0	0	0	0				14464	294717
703	18.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	0	0	0	0	0	0	0	0				14465	294718
704	18.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14466	294719
705	19.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14467	294720
706	19.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14468	291763
707	19.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14470	291767
708	19.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14472	291766
709	19.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14473	291765
710	19.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				14476	291764
711	19.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14478	294755
712	19.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14479	294757
713	19.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14481	294767

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
714	20.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		14484	294771
715	20.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14487	294785
716	20.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14490	294813
717	20.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				14494	294815
718	20.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14495	294831
719	20.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				14497	294839
720	20.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14499	294849
721	20.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	30	0	0	0	0	0	0	0	0	0	0				14501	294860
722	20.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	0	0	0	0	0	0	0	0	0	0	0				14504	294870
723	21.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14507	294888
724	21.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14511	294895
725	21.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	10	0	0	0	0	0	0	0	0	0	0	0	0	0				14513	294907
726	21.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				14514	294914
727	21.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14515	294876
728	21.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14516	294917
729	21.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14517	294879

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
730	21.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		14518	294929
731	22.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14520	294938
732	21.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14522	294939
733	22.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14523	294947
734	22.2	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				14524	294953
735	22.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				14525	294963
736	22.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14526	294967
737	22.6	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14530	294975
738	25.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14531	294976
739	25.1	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	18	0	0	50	0	0	0	0	0	0	0	0	0	0				14532	294990
740	24.9	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				14533	294995
741	22.3	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				14534	295015
742	25.4	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14535	295038
743	25.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				14536	295039
744	25.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	100	0	0	0	0	0	0	0	0	0	0				14539	295048
745	25.8	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	50	0	0	0	0	0	0	0	0	0	0				14541	295052
746	29.5	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				14542	295065
747	29.7	8/25/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14543	295067
748	44.6	8/28/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	0	0	0	0	0	0	0	0				14950	296832
749		9/3/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				15419	299793

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
750	50.7	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	600	0	0	0	0	0	0	0	0	0	0		[redacted]		15480	300092
751	50.8	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	30	0	0	100	0	0	0	0	0	0	0	0	0	0				15481	300093
752	50.9	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				15482	300094
753	51.1	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	700	0	0	0	0	0	0	0	0	0	0				15483	300095
754	51.2	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	1200	0	0	0	0	0	0	0	0	0	0				15484	300096
755	51.3	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	500	0	0	0	0	0	0	0	0	0	0				15485	277931
756	51.4	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				15486	300097
757	51.6	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	600	0	0	0	0	0	0	0	0	0	0				15487	261463
758	51.7	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	800	0	0	0	0	0	0	0	0	0	0				15488	300098
759	51.8	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				15489	300099
760	51.9	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	200	0	0	0	0	0	0	0	0	0	0				15490	300100
761	52.1	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	250	0	0	0	0	0	0	0	0	0	0				15491	300101
762	52.2	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	200	0	0	0	0	0	0	0	0	0	0				15492	300102
763	52.3	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	500	0	0	0	0	0	0	0	0	0	0				15493	300103

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
764	52.4	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	800	0	0	0	0	0	0	0	0	0	0		[redacted]		15494	300104
765	52.5	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	1500	0	0	0	0	0	0	0	0	0	0				15495	300105
766	52.6	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	1000	0	0	0	0	0	0	0	0	0	0				15496	300106
767	52.7	9/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	100	0	0	0	0	0	0	0	0	0	0				15497	300107
768	53.4	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	300	0	0	0	0	0	0	0	0	0	0				15608	300838
769	53.5	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				15609	300839
770	68.2	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	400	0	0	0	0	0	0	0	0	0	0				15610	300840
771	68.6	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	300	0	0	0	0	0	0	0	0	0	0				15611	300847
772	68.7	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	800	0	0	0	0	0	0	0	0	0	0				15612	300848
773	68.8	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	1100	0	0	0	0	0	0	0	0	0	0				15613	300849
774	68.9	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	700	0	0	0	0	0	0	0	0	0	0				15614	300850
775	69.1	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				15615	300851
776	69.2	9/8/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	200	0	0	0	0	0	0	0	0	0	0				15616	300852

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
777	70.8	9/11/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41	4	0	0	500	0	0	0	0	0	0	0	0	0	0		[redacted]		15795	302130
778	51.4	9/11/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				15796	302146
779	51.3	9/11/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41	10	0	0	500	0	0	0	0	0	0	0	0	0	0				15797	302147
780	51.7	9/11/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41	4	0	0	200	0	0	0	0	0	0	0	0	0	0				15798	302148
781	70.5	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	400	0	0	0	0	0	0	0	0	0	0				15833	302264
782	70.7	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	300	0	0	0	0	0	0	0	0	0	0				15834	302265
783	70.9	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	200	0	0	0	0	0	0	0	0	0	0				15835	302266
784	51.1	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	13	0	0	1200	3	0	0	0	0	0	0	0	0	0				15836	302267
785	51.2	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				15837	302268
786	51.5	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	300	0	0	0	0	0	0	0	0	0	0				15838	302269
787	51.6	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	1000	0	0	0	0	0	0	0	0	0	0				15839	302270
788	51.8	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	500	0	0	0	0	0	0	0	0	0	0				15840	302271
789	50.9	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				15841	302272
790	50.8	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				15842	302274
791	50.7	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				15843	302275
792	60.1	9/11/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				15844	302273
793	65.8	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	300	0	0	0	0	0	0	0	0	0	0				15981	303422

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
794	64.5	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	100	0	0	0	0	0	0	0	0	0	0		[redacted]		15989	303432
795	64.4	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	400	0	0	0	0	0	0	0	0	0	0				15990	303433
796	64.3	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				15991	303434
797	64.2	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				15992	303435
798	63.8	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				15993	303436
799	63.5	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	200	0	0	0	0	0	0	0	0	0	0				15994	303437
800	63.2	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				15995	303438
801	62.8	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				15996	303439
802	62.6	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				15997	303440
803	62.7	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				15998	303441
804	63.3	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	100	0	0	0	0	0	0	0	0	0	0				15999	303442
805		9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	500	0	0	0	0	0	0	0	0	0	0				16000	303443
806	63.9	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				16001	303444
807	3.2	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				16002	303445
808	9.9	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				16003	303446
809	71.7	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				16004	303447
810	65.7	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	300	0	0	0	0	0	0	0	0	0	0				16005	303423
811	65.6	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				16006	303424
812	65.5	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	400	0	0	0	0	0	0	0	0	0	0				16007	303425
813	65.4	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				16008	303426
814	65.3	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	600	0	0	0	0	0	0	0	0	0	0				16009	303427

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
815	64.9	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	100	0	0	0	0	0	0	0	0	0	0		[redacted]		16010	303428
816	64.8	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	200	0	0	0	0	0	0	0	0	0	0				16011	303429
817	64.7	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	500	0	0	0	0	0	0	0	0	0	0				16012	303430
818	64.6	9/15/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	200	0	0	0	0	0	0	0	0	0	0				16013	303431
819	61.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	200	0	0	0	0	0	0	0	0	0	0				16125	304080
820	61.2	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	1100	0	0	0	0	0	0	0	0	0	0				16126	304081
821	61.1	9/16/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				16127	304082
822	59.9	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	350	0	0	0	0	0	0	0	0	0	0				16128	304083
823	59.8	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	400	0	0	0	0	0	0	0	0	0	0				16129	304084
824	59.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	800	0	0	0	0	0	0	0	0	0	0				16130	304085
825	59.6	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	100	0	0	0	0	0	0	0	0	0	0				16131	304086
826	59.5	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	100	0	0	0	0	0	0	0	0	0	0				16132	304087
827	59.1	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	300	0	0	0	0	0	0	0	0	0	0				16133	304088
828	59.2	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	200	0	0	0	0	0	0	0	0	0	0				16134	304089
829	59.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				16135	304090
830	58.9	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				16136	304091
831	58.8	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	200	0	0	0	0	0	0	0	0	0	0				16137	304092

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
832	58.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	1400	0	0	0	0	0	0	0	0	0	0		[redacted]		16138	304093
833	58.6	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				16139	304094
834	58.5	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	300	0	0	0	0	0	0	0	0	0	0				16140	304095
835	58.2	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	1000	0	0	0	0	0	0	0	0	0	0				16141	304096
836	57.9	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	600	0	0	0	0	0	0	0	0	0	0				16142	304097
837	57.8	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	200	0	0	0	0	0	0	0	0	0	0				16143	304098
838	57.5	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	600	0	0	0	0	0	0	0	0	0	0				16144	304099
839	57.6	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	200	0	0	0	0	0	0	0	0	0	0				16145	304100
840	57.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				16146	304101
841	57.4	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	500	0	0	0	0	0	0	0	0	0	0				16147	304102
842	57.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	1000	0	0	0	0	0	0	0	0	0	0				16148	304103
843	56.9	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				16149	304105
844	56.8	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				16150	304106
845	56.4	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				16151	304107

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
846	56.5	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	1200	0	0	0	0	0	0	0	0	0	0		[redacted]		16152	304108
847	56.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				16153	304109
848	56.6	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	400	0	0	0	0	0	0	0	0	0	0				16154	304110
849	57.1	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				16155	304111
850	56.7	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	400	0	0	0	0	0	0	0	0	0	0				16156	304112
851	57.2	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	100	0	0	0	0	0	0	0	0	0	0				16157	304113
852	58.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	200	0	0	0	0	0	0	0	0	0	0				16158	304114
853	58.4	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				16159	304115
854	58.1	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	100	0	0	0	0	0	0	0	0	0	0				16160	304116
855	59.4	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				16161	304117
856	71.3	9/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				16162	304118
857	60.5	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				16217	304537
858	60.6	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				16218	304538
859	60.7	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				16219	304539
860	60.8	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				16220	304540
861	60.2	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	200	0	0	0	0	0	0	0	0	0	0				16221	304541
862	60.3	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				16222	304542
863	60.4	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				16223	285717
864	70.2	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	500	0	0	0	0	0	0	0	0	0	0				16224	304543
865	70.3	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	300	0	0	0	0	0	0	0	0	0	0				16225	304544
866	70.4	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	1000	0	0	0	0	0	0	0	0	0	0				16226	304545
867	52.2	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				16227	304546

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
868	52.3	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	200	0	0	0	0	0	0	0	0	0	0		[redacted]		16228	304547
869	52.4	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	31	0	0	600	0	0	0	0	0	0	0	0	0	0				16229	304548
870	52.5	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	600	0	0	0	0	0	0	0	0	0	0				16230	304549
871	52.7	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	700	0	0	0	0	0	0	0	0	0	0				16231	304550
872	52.6	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				16232	304551
873	70.6	9/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				16233	304552
874	55.7	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	100	0	0	0	0	0	0	0	0	0	0				16254	304741
875	52.8	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	100	0	0	0	0	0	0	0	0	0	0				16258	304760
876	53.8	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	200	0	0	0	0	0	0	0	0	0	0				16259	304771
877	53.9	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				16260	304774
878	54.1	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	200	0	0	0	0	0	0	0	0	0	0				16261	304775
879	53.7	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				16262	304776

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
880	53.2	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	200	0	0	0	0	0	0	0	0	0	0		[redacted]		16266	304802
881	54.5	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	100	0	0	0	0	0	0	0	0	0	0				16267	304806
882	54.6	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				16268	304810
883	54.7	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	400	0	0	0	0	0	0	0	0	0	0				16269	304813
884	54.8	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	100	0	0	0	0	0	0	0	0	0	0				16270	304822
885	54.9	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	100	0	0	0	0	0	0	0	0	0	0				16271	304824
886	54.3	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	4000	0	0	0	0	0	0	0	0	0	0				16272	304827
887	55.2	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	600	0	0	0	0	0	0	0	0	0	0				16273	304833
888	55.3	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	100	0	0	0	0	0	0	0	0	0	0				16274	304834
889	55.4	9/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				16275	304839
890	55.9	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				17630	306260
891	65.2	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	200	0	0	0	0	0	0	0	0	0	0				17631	306261
892	65.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	300	0	0	0	0	0	0	0	0	0	0				17632	306262
893	62.4	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	500	0	0	0	0	0	0	0	0	0	0				17633	306263
894	62.3	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	600	0	0	0	0	0	0	0	0	0	0				17634	306264

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
895	62.2	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	1700	0	0	0	0	0	0	0	0	0	0		[redacted]		17635	306265
896	64.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	100	0	0	0	0	0	0	0	0	0	0				17636	306266
897	63.7	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	300	0	0	0	0	0	0	0	0	0	0				17637	306267
898	63.6	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				17638	306268
899	62.9	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	0	0	0	0	0	0	0	0	0	0	0				17639	306270
900	63.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	100	0	0	0	0	0	0	0	0	0	0				17640	306271
901	62.5	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	1300	0	0	0	0	0	0	0	0	0	0				17641	306272
902	74.9	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	1200	0	0	0	0	0	0	0	0	0	0				17642	306273
903	75.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	200	0	0	0	0	0	0	0	0	0	0				17643	306274
904	66.6	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				17644	306275
905	68.3	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	1000	0	0	0	0	0	0	0	0	0	0				17645	306276
906	68.4	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				17646	306277
907	68.5	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	700	0	0	0	0	0	0	0	0	0	0				17647	306278
908	68.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	100	0	0	0	0	0	0	0	0	0	0				17648	306279
909	71.8	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17649	306280
910	71.9	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17650	306281

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
911	72.1	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	600	0	0	0	0	0	0	0	0	0	0		[redacted]		17651	306282
912	72.2	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17652	306283
913	72.3	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	400	0	0	0	0	0	0	0	0	0	0				17653	306284
914	72.4	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				17654	306285
915	72.6	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	100	0	0	0	0	0	0	0	0	0	0				17655	306286
916	72.5	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	300	0	0	0	0	0	0	0	0	0	0				17656	306287
917	72.7	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	1500	0	0	0	0	0	0	0	0	0	0				17657	306288
918	72.8	9/22/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				17658	306289
919	25.6	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17714	306660
920	73.4	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	2000	0	0	0	0	0	0	0	0	0	0				17715	306661
921	74.8	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	600	0	0	0	0	0	0	0	0	0	0				17716	306662
922	74.7	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	400	0	0	0	0	0	0	0	0	0	0				17717	306663
923	74.6	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				17718	306664
924	74.5	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				17719	306665
925	74.2	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				17720	306666
926	73.9	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	1300	0	0	0	0	0	0	0	0	0	0				17721	306667
927	74.1	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17722	306668
928	73.6	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17723	306669
929	73.5	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				17724	306670

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
930	73.8	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		17725	306671
931	73.7	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				17726	306672
932	74.3	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	100	0	0	0	0	0	0	0	0	0	0				17727	306673
933	74.4	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				17728	306674
934	53.6	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	200	0	0	0	0	0	0	0	0	0	0				17749	306823
935	54.2	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	100	0	0	0	0	0	0	0	0	0	0				17762	306869
936	54.4	9/23/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				17763	306875
937	66.7	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	1100	0	0	0	0	0	0	0	0	0	0				17866	307656
938	66.8	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	2000	0	0	0	0	0	0	0	0	0	0				17867	307657
939	66.9	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	500	0	0	0	0	0	0	0	0	0	0				17868	307658
940	67.1	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				17869	307659
941	67.2	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	700	0	0	0	0	0	0	0	0	0	0				17870	307660
942	67.3	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	1	0	1000	0	0	0	0	0	0	0	0	0	0				17871	307661
943	67.4	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	600	0	0	0	0	0	0	0	0	0	0				17872	307662
944	67.9	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	1300	0	0	0	0	0	0	0	0	0	0				17873	307663

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
945	67.8	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	200	0	0	0	0	0	0	0	0	0	0		[redacted]		17874	307664
946	67.7	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	1000	0	0	0	0	0	0	0	0	0	0				17875	307665
947	66.1	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	200	0	0	0	0	0	0	0	0	0	0				17876	307666
948	65.9	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	200	0	0	0	0	0	0	0	0	0	0				17877	307667
949	73.2	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	2500	0	0	0	0	0	0	0	0	0	0				17878	307668
950	73.1	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	1000	0	0	0	0	0	0	0	0	0	0				17879	307669
951	72.9	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	2100	0	0	0	0	0	0	0	0	0	0				17880	307670
952	71.5	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	9	0	0	0	0	0	0	0	0	0	0	0	0	0				17881	307671
953	71.4	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17882	307672
954	71.6	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				17883	307675
955	56.2	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				17884	307676
956	56.3	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	100	0	0	0	0	0	0	0	0	0	0				17885	307677
957	56.1	9/24/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				17886	307678
958	18.6	10/1/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				14463	291762
959		10/21/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				19485	310282

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
960	75.2	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		20409	326442
961	75.3	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	1	0	0	0	0	0	0	0	0	0	0	0	0	0				20410	326443
962	75.4	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				20411	326444
963	75.5	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				20412	326445
964	75.6	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20413	326446
965	75.6	11/4/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	0	0	0	0	0	0	0	0	0	0	0				20414	326447
966		11/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				20415	326448
967		11/5/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20416	326449
968		11/6/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0				20433	326884
969		11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				20449	327282
970	75.7	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				20450	327283
971	75.8	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	6	0	0	1000	0	0	0	0	0	0	0	0	0	0				20451	327284
972	75.9	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20452	327285
973	76.1	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20453	327286
974	76.2	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20454	327287
975	76.3	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	8	0	0	0	0	0	0	0	0	0	0	0	0	0				20455	327288
976	76.4	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				20456	327289

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
977	76.5	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]	[redacted]	20457	327290
978	76.6	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	4	0	0	600	0	0	0	0	0	0	0	0	0	0				20458	327291
979	76.7	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	0	0	0	0	0	0	0	0	0	0	0	0	0	0				20459	327292
980	76.8	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				20460	327293
981	76.9	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0				20461	327294
982	77.1	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				20462	327295
983	77.2	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	16	0	0	0	0	0	0	0	0	0	0	0	0	0				20463	327296
984	77.3	11/9/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				20464	327297
985	77.3	11/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				20862	330402
986	77.4	11/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0				20863	330405
987	77.5	11/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0				20864	330406
988	77.6	11/12/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	13	0	0	0	0	0	0	0	0	0	0	0	0	0				20865	330407
989		11/13/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	11	0	0	0	0	0	0	0	0	0	0	0	0	0				20866	330408
990		11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20867	330409
991		11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				20868	330410
992		11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	2	0	0	0	0	0	0	0	0	0	0	0	0	0				20869	330411

	A	B	C	D	E	F	G	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ	AK	AM	AN	AO	AP
3	R#	Date Inspected	Time Inspected	Inspector	Company	District	Feeder	Prune	Secondary Prunes	Brush Prune Sq Ft	Removals Brush Sq Ft	Removals 6-11"	Removals 12-23"	Removals 24"+	Reliability Prunes Brush Sq Ft	Reliability Prunes 6-11"	Reliability Prunes 12-23"	Reliability Prunes 24"+	Reliability Removals Brush Sq Ft	Reliability Removals 6-11"	Reliability Removals 12-23"	Reliability Removals 24"+	LAT	LONG	Form ID	Map Object ID
993		11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	12	0	0	0	0	0	0	0	0	0	0	0	0	0		[redacted]		20870	330412
994		11/16/2020	12:00 AM	Joshua Sparacio	ACRT	YREKA	5G41	5	0	0	0	0	0	0	0	0	0	0	0	0	0				20871	330413
995	77.5	11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20872	330414
996	55.3	11/16/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20873	330415
997		11/17/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	3	0	0	0	0	0	0	0	0	0	0	0	0	0				20874	330417
998		11/18/2020	12:00 AM	Jordan McMillan	ACRT	YREKA	5G41	7	0	0	800	0	0	0	0	0	0	0	0	0	0				21047	331392